		UST Service Provider List (Co	oastal)		
Company		Listing Submitted		Area of state conducts work	
ABC Global Contracting LLC	ı	Phone (810) 533-2416		Coastal (East of I-95): Yes	
32032 28 Mile Road		Fax		Central (West of I-95 and East of I-77): Yes	
Lenox, Michigan 48048-				Mountains (West of I-77): Yes	
	We	ebsite abcglobalcontracting.com		(rroce c. r r y. r co	
Com	pliance Testii	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:		Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:		UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:		UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:		Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
E	nvironmental	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	ı No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	8/4/2020	Area of state conducts work	
Company Advanced Environmental Services, Inc.	ı	Phone (336) 282-3586	8/4/2020	Area of state conducts work Coastal (East of I-95): Yes	
Advanced Environmental Services, Inc. PO Box 38218	I		8/4/2020	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Advanced Environmental Services, Inc.		Phone (336) 282-3586	8/4/2020	Coastal (East of I-95): Yes	
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438	We	Phone (336) 282-3586 Fax (336) 282-3587	8/4/2020	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438	We pliance Testii	Phone (336) 282-3586 Fax (336) 282-3587 Phone (336) 282-3587 Phone (336) 282-3586 advancedenvironmental.com	8/4/2020 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438 Com	We pliance Testin	Phone (336) 282-3586 Fax (336) 282-3587 Phone (336) 282-3587 Phone (336) 282-3586 advancedenvironmental.com Ing and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438 Com Automatic Line Leak Detector Testing:	We pliance Testin No No	Phone (336) 282-3586 Fax (336) 282-3587 Phone (336) 282-3587 Phone (336) 282-3586 Fax (336) 282-3587 Phone (336) 282-3587 Phone (336) 282-3586 Fax (336) 282-3587 Phone (No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438 Com Automatic Line Leak Detector Testing: Containment Sump Testing:	We pliance Testin No No No	Phone (336) 282-3586 Fax (336) 282-3587 Phosite advancedenvironmental.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	We pliance Testin No No No	Phone (336) 282-3586 Fax (336) 282-3587 Phosite advancedenvironmental.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	We pliance Testin No No No No	Phone (336) 282-3586 Fax (336) 282-3587 Phosite advancedenvironmental.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Pliance Testin No No No No No No No	Phone (336) 282-3586 Fax (336) 282-3587 Posite advancedenvironmental.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Pliance Testin No No No No No No No	Phone (336) 282-3586 Fax (336) 282-3587 Phosite advancedenvironmental.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Pliance Testine No	Phone (336) 282-3586 Fax (336) 282-3587 Phosite advancedenvironmental.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Pliance Testin No	Phone (336) 282-3586 Fax (336) 282-3587 Phosite advancedenvironmental.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Pliance Testin No	Phone (336) 282-3586 Fax (336) 282-3587 Posite advancedenvironmental.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanup	Pliance Testin No	Phone (336) 282-3586 Fax (336) 282-3587 Phosite advancedenvironmental.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Pliance Testin No	Phone (336) 282-3586 Fax (336) 282-3587 Posite advancedenvironmental.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST	Service Provider List (Co	astal)		
Company			Listing Submitted		Area of state conducts work	
Advanced Environmental Solutions, LLC		Phone	(828) 664-9822		Coastal (East of I-95): Yes	
P.O. Box 1426		Fax	(866) 425-2661		Central (West of I-95 and East of I-77): Yes	
Black Mountain, NC 28711					Mountains (West of I-77): Yes	
	'	Website	advancedenvironmentalsolutions.com			
Comp	oliance Tes	sting and	Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill	Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistic	cal Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Pre	evention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Ti	ghtness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Int	ternal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Int	ternal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>				UST System Removal:	No
Er	nvironmen	tal Servic	ce Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Co	ompliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Eq	quipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste I	Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					
Company			Listing Submitted	2/1/2021	Area of state conducts work	
Company Advanced Environmental Solutions, LLC		Phone	/\ ·	2/1/2021	Area of state conducts work Coastal (East of I-95): Yes	
Advanced Environmental Solutions, LLC P.O. Box 1426		Phone Fax	(828) 664-9822	2/1/2021	Coastal (East of I-95): Yes	
Advanced Environmental Solutions, LLC		_		2/1/2021	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Advanced Environmental Solutions, LLC P.O. Box 1426	1	_	(828) 664-9822	2/1/2021	Coastal (East of I-95): Yes	
Advanced Environmental Solutions, LLC P.O. Box 1426 Black Mountain, NC 28711		Fax Website	(828) 664-9822 (866) 425-2661	2/1/2021	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Advanced Environmental Solutions, LLC P.O. Box 1426 Black Mountain, NC 28711		Fax Website sting and	(828) 664-9822 (866) 425-2661 advancedenvironmentalsolutions.com	2/1/2021 Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Advanced Environmental Solutions, LLC P.O. Box 1426 Black Mountain, NC 28711 Comp	oliance Tes	Fax Website sting and Overfill	(828) 664-9822 (866) 425-2661 advancedenvironmentalsolutions.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Advanced Environmental Solutions, LLC P.O. Box 1426 Black Mountain, NC 28711 Compared Automatic Line Leak Detector Testing:	oliance Tes <u>Yes</u>	Fax Website sting and Overfill Statistic	(828) 664-9822 (866) 425-2661 advancedenvironmentalsolutions.com Monitoring Prevention Equipment Operability Check:	Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Advanced Environmental Solutions, LLC P.O. Box 1426 Black Mountain, NC 28711 Comparison Comparison Containment Sump Testing:	Oliance Tes Yes Yes	Fax Website sting and Overfill Statistic Spill Pre	(828) 664-9822 (866) 425-2661 advancedenvironmentalsolutions.com Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services:	Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Advanced Environmental Solutions, LLC P.O. Box 1426 Black Mountain, NC 28711 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Oliance Tes Yes Yes No	Fax Website sting and Overfill Statistic Spill Pre Tank Tig	(828) 664-9822 (866) 425-2661 advancedenvironmentalsolutions.com Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing:	Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Advanced Environmental Solutions, LLC P.O. Box 1426 Black Mountain, NC 28711 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes Yes No No Yes Yes Yes	Fax Website sting and Overfill Statistic Spill Pre Tank Tig UST Int UST Int	(828) 664-9822 (866) 425-2661 advancedenvironmentalsolutions.com I Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing:	Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
Advanced Environmental Solutions, LLC P.O. Box 1426 Black Mountain, NC 28711 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	Yes Yes No No Yes Yes Yes No	Fax Website sting and Overfill Statistic Spill Pre Tank Tig UST Int	(828) 664-9822 (866) 425-2661 advancedenvironmentalsolutions.com Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing: ternal Inspections (Integrity Assessments):	Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Advanced Environmental Solutions, LLC P.O. Box 1426 Black Mountain, NC 28711 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes Yes No No Yes Yes Yes	Fax Website sting and Overfill Statistic Spill Pre Tank Tig UST Int UST Int	(828) 664-9822 (866) 425-2661 advancedenvironmentalsolutions.com Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing: ternal Inspections (Integrity Assessments):	Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Advanced Environmental Solutions, LLC P.O. Box 1426 Black Mountain, NC 28711 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No No Yes Yes Yes No	Fax Website sting and Overfill Statistic Spill Pre Tank Tig UST Int UST Int Other:	(828) 664-9822 (866) 425-2661 advancedenvironmentalsolutions.com Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing: ternal Inspections (Integrity Assessments): ternal Lining Inspections:	Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Advanced Environmental Solutions, LLC P.O. Box 1426 Black Mountain, NC 28711 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No No Yes Yes No Yes Yes No Yes	Fax Website sting and Overfill Statistic Spill Pre Tank Tig UST Int UST Int Other:	(828) 664-9822 (866) 425-2661 advancedenvironmentalsolutions.com Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing: ternal Inspections (Integrity Assessments): ternal Lining Inspections:	Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Advanced Environmental Solutions, LLC P.O. Box 1426 Black Mountain, NC 28711 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No No Yes Yes No Yes Yes No Yes No Yes No Yes	Fax Website sting and Overfill Statistic Spill Pre Tank Tig UST Int UST Int Other: tal Service UST Co	(828) 664-9822 (866) 425-2661 advancedenvironmentalsolutions.com Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing: ternal Inspections (Integrity Assessments): ternal Lining Inspections:	Yes Yes Yes Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Advanced Environmental Solutions, LLC P.O. Box 1426 Black Mountain, NC 28711 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	Yes Yes No No Yes Yes No Yes No Yes No Yes No Yes No Yes No Yes	Fax Website sting and Overfill Statistic Spill Pre Tank Tig UST Int UST Int Other: tal Service UST Co UST Eq	(828) 664-9822 (866) 425-2661 advancedenvironmentalsolutions.com Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing: ternal Inspections (Integrity Assessments): ternal Lining Inspections:	Yes Yes Yes Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Advanced Environmental Solutions, LLC P.O. Box 1426 Black Mountain, NC 28711 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes Yes No No Yes Yes No Yes No Yes No Yes No Yes No Yes No Yes	Fax Website sting and Overfill Statistic Spill Pre Tank Tig UST Int UST Int Other: tal Service UST Co UST Eq	(828) 664-9822 (866) 425-2661 advancedenvironmentalsolutions.com Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing: ternal Inspections (Integrity Assessments): ternal Lining Inspections: ce Firms ompliance Consultants: quipment Verification:	Yes Yes Yes Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List (Co	oastal)		
Company		Listing Submitted	5/17/2021	Area of state conducts work	
AES of Greenville LLC		Phone (252) 758-3311		Coastal (East of I-95): Yes	
141 S. Market Street		Fax (252) 481-5814		Central (West of I-95 and East of I-77): Yes	
Washington, NC 27889	,	Al-haita		Mountains (West of I-77): Yes	
		Website www.aes-nc.com			
Comp	oliance Tes	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
Er	nvironment	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
· · · · · · · · · · · · · · · · · · ·	No	Listing Submitted	4/15/2021	Area of state conducts work	
Soil and Water Testing Lab:	No	Listing Submitted Phone (919) 777-8543	4/15/2021	Area of state conducts work Coastal (East of I-95): Yes	
Company American UST Compliance Testing 180 BPW Club Rd. A-1	No		4/15/2021	Coastal (East of I-95): Yes	
Soil and Water Testing Lab: Company American UST Compliance Testing	No	Phone (919) 777-8543	4/15/2021	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Company American UST Compliance Testing 180 BPW Club Rd. A-1		Phone (919) 777-8543	4/15/2021	Coastal (East of I-95): Yes	
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510	\	Phone (919) 777-8543 Fax	4/15/2021	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510	\	Phone (919) 777-8543 Fax Website	4/15/2021 Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	Yes
Soil and Water Testing Lab: Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Comp	\ bliance Tes	Phone (919) 777-8543 Fax Website		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	Yes No
Soil and Water Testing Lab: Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Company Automatic Line Leak Detector Testing:	\ Dliance Tes Yes	Phone (919) 777-8543 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check:	Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	Voliance Tes Yes Yes	Phone (919) 777-8543 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Dliance Tes Yes Yes No	Phone (919) 777-8543 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	Yes No Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No <u>Yes</u>
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Diiance Tes Yes Yes No No	Phone (919) 777-8543 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	Yes No Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No <u>Yes</u> No
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No Yes	Phone (919) 777-8543 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	Yes No Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No <u>Yes</u> No <u>Yes</u>
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Ves Yes Yes No No Yes Yes	Phone (919) 777-8543 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No <u>Yes</u> No <u>Yes</u> No
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Yes Yes No No Yes Yes No Yes	Phone (919) 777-8543 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No Yes No Yes No No No
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Yes Yes No No Yes Yes No Yes	Phone (919) 777-8543 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes No Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No Yes No No
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Yes Yes No Yes Yes No Yes Yes No Yes No Yes	Phone (919) 777-8543 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes No Yes Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No Yes No No
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	Ves Yes No No Yes Yes No Yes Yes No Yes No Yes No Yes No Yes	Phone (919) 777-8543 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants:	Yes No Yes Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No Yes No No No
Company American UST Compliance Testing 180 BPW Club Rd. A-1 Carrboro, NC 27510 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Ves Yes No No Yes Yes No Yes Yes No Yes No Yes No Yes No Yes	Phone (919) 777-8543 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification:	Yes No Yes Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes No Yes No No No

		UST Service Provider List (C	oastal)		
Company		Listing Submitted		Area of state conducts work	
Apex Engineering, PC		Phone (301) 417-0200		Coastal (East of I-95): Yes	
15850 Crabbs Branch Way		Fax (301) 975-0169		Central (West of I-95 and East of I-77): Yes	
Suite 200 Rockville, Maryland 20855-				Mountains (West of I-77): Yes	
Trookviile, Maryland 20000		Website <u>www.apexcos.com</u>		,	
Com	pliance Tes	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
E	nvironmen	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	yes	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	<u>Yes</u>	Other:			
Soil and Water Testing Lab:	<u>Yes</u>				
Con and trater rooming Lab.	163				
Company	103	Listing Submitted	2/1/2019	Area of state conducts work	
	163	Listing Submitted Phone (757) 410-5974	2/1/2019	Area of state conducts work Coastal (East of I-95): Yes	
Company Bay Compliance and Testing P.O. Box 16628	163	Phone (757) 410-5974	2/1/2019	Coastal (East of I-95): Yes	
Company Bay Compliance and Testing	169		2/1/2019	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No	
Company Bay Compliance and Testing P.O. Box 16628		Phone (757) 410-5974	2/1/2019	Coastal (East of I-95): Yes	
Company Bay Compliance and Testing P.O. Box 16628 Chesapeake, NC 23328	,	Phone (757) 410-5974 Fax	2/1/2019	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No	
Company Bay Compliance and Testing P.O. Box 16628 Chesapeake, NC 23328	,	Phone (757) 410-5974 Fax Website	2/1/2019 Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No	No
Company Bay Compliance and Testing P.O. Box 16628 Chesapeake, NC 23328 Com Automatic Line Leak Detector Testing: Containment Sump Testing:	pliance Tes	Phone (757) 410-5974 Fax Website sting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors	
Company Bay Compliance and Testing P.O. Box 16628 Chesapeake, NC 23328 Com Automatic Line Leak Detector Testing:	pliance Tes	Phone (757) 410-5974 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check:	Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No
Company Bay Compliance and Testing P.O. Box 16628 Chesapeake, NC 23328 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	pliance Tes Yes Yes	Phone (757) 410-5974 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	<u>Yes</u> No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Company Bay Compliance and Testing P.O. Box 16628 Chesapeake, NC 23328 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	pliance Tes Yes Yes No	Phone (757) 410-5974 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	Yes No Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No
Company Bay Compliance and Testing P.O. Box 16628 Chesapeake, NC 23328 Company Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	pliance Tes Yes Yes No Yes Yes Yes Yes Yes	Phone (757) 410-5974 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
Company Bay Compliance and Testing P.O. Box 16628 Chesapeake, NC 23328 Company Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	pliance Tes Yes Yes No Yes Yes	Phone (757) 410-5974 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	Yes No Yes Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No
Company Bay Compliance and Testing P.O. Box 16628 Chesapeake, NC 23328 Company Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	pliance Tes Yes Yes No Yes Yes Yes Yes Yes	Phone (757) 410-5974 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Company Bay Compliance and Testing P.O. Box 16628 Chesapeake, NC 23328 Commandary Commandary Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	pliance Tes Yes Yes No Yes Yes Yes No Yes Yes No Yes	Phone (757) 410-5974 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Company Bay Compliance and Testing P.O. Box 16628 Chesapeake, NC 23328 Commandary Commandary Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	pliance Tes Yes Yes No Yes Yes Yes No Yes Yes No Yes	Phone (757) 410-5974 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes No Yes Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Company Bay Compliance and Testing P.O. Box 16628 Chesapeake, NC 23328 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	pliance Tes Yes Yes No Yes Yes Yes No Yes No Yes No Yes	Phone (757) 410-5974 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes No Yes Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Company Bay Compliance and Testing P.O. Box 16628 Chesapeake, NC 23328 Company Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	pliance Tes Yes Yes No Yes Yes Yes Yes No Yes No Yes No You	Phone (757) 410-5974 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants:	Yes No Yes Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Company Bay Compliance and Testing P.O. Box 16628 Chesapeake, NC 23328 Commandatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	pliance Tes Yes Yes No Yes Yes Yes Yes No Yes No Yes No You	Phone (757) 410-5974 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants: UST Equipment Verification:	Yes No Yes Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

		UST Service Provider List (Co	astal)		
Company		Listing Submitted		Area of state conducts work	
Blue Ridge Geological Services, Inc.		Phone (336) 382-6849		Coastal (East of I-95): Yes	
7356 Belmont Drive		Fax		Central (West of I-95 and East of I-77): Yes	
Trinity, NC 27370				Mountains (West of I-77): Yes	
		Website www.blueridgegeo.com		•	
Comp	pliance Te	esting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
E	nvironme	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	<u>Yes</u>				
Company		Listing Submitted	2/1/2021	Area of state conducts work	
Company Buckeye Elm Contracting		Listing Submitted Phone (888) 315-8663	2/1/2021	Area of state conducts work Coastal (East of I-95): Yes	
• •		Phone (888) 315-8663	2/1/2021	Coastal (East of I-95): Yes	
Buckeye Elm Contracting			2/1/2021	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Buckeye Elm Contracting PO Box 1026		Phone (888) 315-8663	2/1/2021	Coastal (East of I-95): Yes	
Buckeye Elm Contracting PO Box 1026 Mocksville, NC 27028	pliance Te	Phone (888) 315-8663 Fax	2/1/2021	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Buckeye Elm Contracting PO Box 1026 Mocksville, NC 27028	pliance Te	Phone (888) 315-8663 Fax Website www.buckeye-elm.com	2/1/2021 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Buckeye Elm Contracting PO Box 1026 Mocksville, NC 27028 Com		Phone (888) 315-8663 Fax Website www.buckeye-elm.com esting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Buckeye Elm Contracting PO Box 1026 Mocksville, NC 27028 Comparison Comparis	No	Phone (888) 315-8663 Fax Website www.buckeye-elm.com esting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Buckeye Elm Contracting PO Box 1026 Mocksville, NC 27028 Comparison Comparison Containment Sump Testing:	No No	Phone (888) 315-8663 Fax Website www.buckeye-elm.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Buckeye Elm Contracting PO Box 1026 Mocksville, NC 27028 Comparison Comparison Containment Sump Testing: Corrosion Protection Design Experts:	No No No	Phone (888) 315-8663 Fax Website www.buckeye-elm.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Buckeye Elm Contracting PO Box 1026 Mocksville, NC 27028 Comparison Comparison Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No	Phone (888) 315-8663 Fax Website www.buckeye-elm.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Buckeye Elm Contracting PO Box 1026 Mocksville, NC 27028 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No	Phone (888) 315-8663 Fax Website www.buckeye-elm.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Buckeye Elm Contracting PO Box 1026 Mocksville, NC 27028 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No	Phone (888) 315-8663 Fax Website www.buckeye-elm.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
Buckeye Elm Contracting PO Box 1026 Mocksville, NC 27028 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No	Phone (888) 315-8663 Fax Website www.buckeye-elm.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Buckeye Elm Contracting PO Box 1026 Mocksville, NC 27028 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No	Phone (888) 315-8663 Fax Website www.buckeye-elm.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Buckeye Elm Contracting PO Box 1026 Mocksville, NC 27028 Comparison Protection Design Experts: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (888) 315-8663 Fax Website www.buckeye-elm.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Buckeye Elm Contracting PO Box 1026 Mocksville, NC 27028 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release:	No N	Phone (888) 315-8663 Fax Website www.buckeye-elm.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Intal Service Firms UST Compliance Consultants:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Buckeye Elm Contracting PO Box 1026 Mocksville, NC 27028 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (888) 315-8663 Fax Website www.buckeye-elm.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Intal Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List (Co	astal)		
Company		Listing Submitted		Area of state conducts work	
Cape Lookout Environmental Sciences, PLLC		Phone (919) 757-7901		Coastal (East of I-95): Yes	
8005 Clear Brook Drive		Fax		Central (West of I-95 and East of I-77): Yes	
Raleigh, NC 27615				Mountains (West of I-77): Yes	
	V	Vebsite CapeLookoutEnv.com		modificanto (Woot of 177).	
Comp	liance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	vironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	Yes	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	11/14/2018	Area of state conducts work	
Carbon Fuel Services, LLC		Phone (704) 419-9939		Coastal (East of I-95): Yes	
301 E Main Street		Fax		Central (West of I-95 and East of I-77): Yes	
Cherryville, NC 28021-					
	V	Vebsite <u>www.carbonfuelservices.com</u>		Mountains (West of I-77): Yes	
Comp	liance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other: Diesel Fuel Compliance Laboratory	Testing	UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	vironment	al Service Firms		Other: Diesel Fuel Polishing, Filtration, and Recovery S	Services
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other: Diesel Fuel Additives and Tank Cleaning			
Soil and Water Testing Lab:	No				

		UST Service Provider List (Co	astal)		
Company		Listing Submitted	8/18/2020	Area of state conducts work	
Cathodic Protection Services, Inc.		Phone (423) 895-1500		Coastal (East of I-95): Yes	
445 Gap Creek Rd.		Fax (423) 542-8955		Central (West of I-95 and East of I-77): Yes	
Elizabethton, TN 37643	W	/ebsite		Mountains (West of I-77): Yes	
				HOTE :	
		ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services: Line Tightness Testing:	No No	Other:		UST Piping/Sump Installation: UST System Removal:	No No
		al Camina Firma		Other:	NO
		al Service Firms	NI-		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	No		
Oil and Water Testing Lab	No No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	1/3/2020	Area of state conducts work	
CATLIN Engineers and Scientists		Phone (910) 452-5861		Coastal (East of I-95): Yes	
220 Old Dairy Road		Fax		Central (West of I-95 and East of I-77): Yes	
Wilmington, NC 28405	10	/ebsite www.CatlinUSA.com		Mountains (West of I-77): No	
		ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling: Soil and Water Testing Lab:	No <u>Yes</u>	Other:			

		UST Service Provider List (Co	pastal)		
Company		Listing Submitted		Area of state conducts work	
Charles Broadfoot & Associates, Inc.		Phone (910) 574-4748		Coastal (East of I-95): Yes	
PO Box 53730		Fax 253-681-05		Central (West of I-95 and East of I-77): Yes	
1827 Morganton Rd. Fayetteville, NC 28305		Website www.ustcomonline.com		Mountains (West of I-77): Yes	
Com	nliance Te	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	Off	Overfill Prevention Equipment Operability Check:	Off	Dispenser Meter Repair/Calibration:	Off
Containment Sump Testing:	Off	Statistical Iventory Reconciliation Services:	Off	Leak Detection Equipment Installation Servicing:	Off
Corrosion Protection Design Experts:	Off	Spill Prevention Equipment Testing:	Off	Spill Bucket Installation Repair:	Off
Corrosion Protection System Repairs:	Off	Tank Tightness Testing:	Off	UST Equipment Installation - Other:	Off
Corrosion Protection System Testing:	Off	UST Internal Inspections (Integrity Assessments):	Off	UST Equipment Repair:	Off
Leak Detection Equipment Operability Check:	Off	UST Internal Lining Inspections:	Off	UST System Installation - Complete Systems:	Off
Leak Detection Monitoring Services:	Off	Other:		UST Piping/Sump Installation:	Off
Line Tightness Testing:	Off			UST System Removal:	Off
	nvironmor	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Off	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	Off	UST Equipment Verification:	Off		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	Off		
Oil and Solvent Recycling:	Off	Other:	Oli		
Soil and Water Testing Lab:	Off	Other.			
0		Linting Only with a	0/47/0000	Anna af state and desta condi-	
Company		Listing Submitted	6/17/2020	Area of state conducts work	
Clark Group dba Clark Environmental Service	es, PC	Phone (910) 392-5555	6/17/2020	Area of state conducts work Coastal (East of I-95): Yes	
Clark Group dba Clark Environmental Service P.O. Box 10136	es, PC		6/17/2020		
Clark Group dba Clark Environmental Service		Phone (910) 392-5555 Fax (910) 392-5552	6/17/2020	Coastal (East of I-95): Yes	
Clark Group dba Clark Environmental Service P.O. Box 10136		Phone (910) 392-5555	6/17/2020	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Clark Group dba Clark Environmental Service P.O. Box 10136 Wilmington, NC 28404		Phone (910) 392-5555 Fax (910) 392-5552	6/17/2020	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Clark Group dba Clark Environmental Service P.O. Box 10136 Wilmington, NC 28404		Phone (910) 392-5555 Fax (910) 392-5552 Website www.clarkgroup.us	6/17/2020 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Clark Group dba Clark Environmental Service P.O. Box 10136 Wilmington, NC 28404	pliance Te	Phone (910) 392-5555 Fax (910) 392-5552 Website www.clarkgroup.us sting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	
Clark Group dba Clark Environmental Service P.O. Box 10136 Wilmington, NC 28404 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	<mark>pliance Te</mark> No	Phone (910) 392-5555 Fax (910) 392-5552 Website www.clarkgroup.us sting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No
Clark Group dba Clark Environmental Service P.O. Box 10136 Wilmington, NC 28404 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	pliance Te No No	Phone (910) 392-5555 Fax (910) 392-5552 Website www.clarkgroup.us sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No
Clark Group dba Clark Environmental Service P.O. Box 10136 Wilmington, NC 28404 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	pliance Te No No No	Phone (910) 392-5555 Fax (910) 392-5552 Website www.clarkgroup.us sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No
Clark Group dba Clark Environmental Service P.O. Box 10136 Wilmington, NC 28404 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	pliance Te No	Phone (910) 392-5555 Fax (910) 392-5552 Website www.clarkgroup.us sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
Clark Group dba Clark Environmental Service P.O. Box 10136 Wilmington, NC 28404 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	pliance Te No	Phone (910) 392-5555 Fax (910) 392-5552 Website www.clarkgroup.us sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Clark Group dba Clark Environmental Service P.O. Box 10136 Wilmington, NC 28404 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	pliance Te No	Phone (910) 392-5555 Fax (910) 392-5552 Website www.clarkgroup.us sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Clark Group dba Clark Environmental Service P.O. Box 10136 Wilmington, NC 28404 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	pliance Te No No No No No No No No No N	Phone (910) 392-5555 Fax (910) 392-5552 Website www.clarkgroup.us sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Clark Group dba Clark Environmental Service P.O. Box 10136 Wilmington, NC 28404 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	pliance Te No No No No No No No No No N	Phone (910) 392-5555 Fax (910) 392-5552 Website www.clarkgroup.us sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Clark Group dba Clark Environmental Service P.O. Box 10136 Wilmington, NC 28404 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	pliance Te No	Phone (910) 392-5555 Fax (910) 392-5552 Website www.clarkgroup.us sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Clark Group dba Clark Environmental Service P.O. Box 10136 Wilmington, NC 28404 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	pliance Te No	Phone (910) 392-5555 Fax (910) 392-5552 Website www.clarkgroup.us sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: ottal Service Firms UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Clark Group dba Clark Environmental Service P.O. Box 10136 Wilmington, NC 28404 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	pliance Te No No No No No No No No No N	Phone (910) 392-5555 Fax (910) 392-5552 Website www.clarkgroup.us sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: utal Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

		UST	Service Provider List (Co	astal)		
Company			Listing Submitted	5/14/2021	Area of state conducts work	
Cobb Environmental & Technical Services, Inc	c.	Phone	(662) 841-0995		Coastal (East of I-95): Yes	
P. O. Box 1602, Tupelo, MS 38802		Fax	(662) 841-0810		Central (West of I-95 and East of I-77): Yes	
871 South Green Street Tupelo, MS 38804					Mountains (West of I-77): Yes	
1 upelo, 1/13 30004	We	ebsite	www.cobbenv.com			
Comp	oliance Testi	ing and	l Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill	Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistic	cal Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Pr	evention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:			ightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:			ternal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:			ternal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:		Other:			UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No				UST System Removal:	<u>Yes</u>
E	nvironmenta	I Servi	ce Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Co	ompliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST E	quipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste	Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					
Company			Listing Submitted	11/14/2018	Area of state conducts work	
Company Cohesion, Inc.		Phone		11/14/2018	Area of state conducts work Coastal (East of I-95): Yes	
Cohesion, Inc. 5216 Yates Mill Pond Road		Phone Fax	(919) 233-8626	11/14/2018	Coastal (East of I-95): Yes	
Cohesion, Inc.		_	(919) 233-8626	11/14/2018	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Cohesion, Inc. 5216 Yates Mill Pond Road		_	(919) 233-8626 (919) 233-8909	11/14/2018	Coastal (East of I-95): Yes	
Cohesion, Inc. 5216 Yates Mill Pond Road Raleigh, NC 27606		Fax ebsite	(919) 233-8626 (919) 233-8909 www.cohesion-inc.com	11/14/2018	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Cohesion, Inc. 5216 Yates Mill Pond Road Raleigh, NC 27606	We	Fax ebsite	(919) 233-8626 (919) 233-8909 www.cohesion-inc.com	11/14/2018 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Cohesion, Inc. 5216 Yates Mill Pond Road Raleigh, NC 27606 Comp	Wo pliance Testi No	Fax ebsite ing and	(919) 233-8626 (919) 233-8909 www.cohesion-inc.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Cohesion, Inc. 5216 Yates Mill Pond Road Raleigh, NC 27606 Comparison Leak Detector Testing:	Wooliance Testi No No	Fax beging and coverfill Statistic	(919) 233-8626 (919) 233-8909 www.cohesion-inc.com I Monitoring Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Cohesion, Inc. 5216 Yates Mill Pond Road Raleigh, NC 27606 Comparison Leak Detector Testing: Containment Sump Testing:	We pliance Testi No No No	Fax debsite ding and Overfill Statistic Spill Pr	(919) 233-8626 (919) 233-8909 www.cohesion-inc.com I Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No
Cohesion, Inc. 5216 Yates Mill Pond Road Raleigh, NC 27606 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Wooliance Testi No No No No	Fax debsite ing and Overfill Statistic Spill Pro Tank Ti	(919) 233-8626 (919) 233-8909 www.cohesion-inc.com I Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Cohesion, Inc. 5216 Yates Mill Pond Road Raleigh, NC 27606 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No No	Fax Tebsite Ting and Overfill Statistic Spill Pr Tank Ti UST Int UST Int UST Int	(919) 233-8626 (919) 233-8909 www.cohesion-inc.com I Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
Cohesion, Inc. 5216 Yates Mill Pond Road Raleigh, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No No No No	Fax Tebsite Tank Ti UST Int	(919) 233-8626 (919) 233-8909 www.cohesion-inc.com I Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing: ternal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Cohesion, Inc. 5216 Yates Mill Pond Road Raleigh, NC 27606 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No No	Fax Tebsite Ting and Overfill Statistic Spill Pr Tank Ti UST Int UST Int UST Int	(919) 233-8626 (919) 233-8909 www.cohesion-inc.com I Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing: ternal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Cohesion, Inc. 5216 Yates Mill Pond Road Raleigh, NC 27606 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Fax Tebsite Te	(919) 233-8626 (919) 233-8909 www.cohesion-inc.com I Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing: ternal Inspections (Integrity Assessments): ternal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Cohesion, Inc. 5216 Yates Mill Pond Road Raleigh, NC 27606 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Fax Tebsite Ting and Overfill Statistic Spill Pr Tank Ti UST Int UST Int Other:	(919) 233-8626 (919) 233-8909 www.cohesion-inc.com I Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing: ternal Inspections (Integrity Assessments): ternal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Cohesion, Inc. 5216 Yates Mill Pond Road Raleigh, NC 27606 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Fax Tebsite Te	(919) 233-8626 (919) 233-8909 www.cohesion-inc.com I Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing: ternal Inspections (Integrity Assessments): ternal Lining Inspections:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Cohesion, Inc. 5216 Yates Mill Pond Road Raleigh, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release:	No N	Fax Tebsite Te	(919) 233-8626 (919) 233-8909 www.cohesion-inc.com I Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing: ternal Inspections (Integrity Assessments): ternal Lining Inspections:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Cohesion, Inc. 5216 Yates Mill Pond Road Raleigh, NC 27606 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Fax Tebsite Te	(919) 233-8626 (919) 233-8909 www.cohesion-inc.com I Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing: ternal Inspections (Integrity Assessments): ternal Lining Inspections: ce Firms ompliance Consultants: quipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List (Co	pastal)		
Company		Listing Submitted	11/15/2018	Area of state conducts work	
CROMPCO, LLC		Phone (800) 646-3161		Coastal (East of I-95): Yes	
1815 Gallagher Road		Fax (610) 278-7621		Central (West of I-95 and East of I-77): Yes	
Plymouth Meeting, PA 19462				Mountains (West of I-77): Yes	
	We	ebsite <u>www.crompco.com</u>		,	
Comp	pliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
E	nvironmenta	I Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	l No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	0/4/0040	Area of state conducts work	
T. T. 1177		Listing Submitted	8/1/2019	Area of State Conducts work	
D.H. Griffin Wrecking, Inc.		Phone (336) 389-3647	8/1/2019	Coastal (East of I-95): Yes	
D.H. Griffin Wrecking, Inc. 4716 Hilltop Road		Phone (336) 389-3647	8/1/2019	Coastal (East of I-95): Yes	
D.H. Griffin Wrecking, Inc.	l	Phone (336) 389-3647 Fax (336) 389-3647	8/1/2019	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
D.H. Griffin Wrecking, Inc. 4716 Hilltop Road		Phone (336) 389-3647	8/1/2019	Coastal (East of I-95): Yes	
D.H. Griffin Wrecking, Inc. 4716 Hilltop Road Greensboro, NC 27407	We	Phone (336) 389-3647 Fax (336) 389-3647	8/1/2019	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
D.H. Griffin Wrecking, Inc. 4716 Hilltop Road Greensboro, NC 27407	We	Phone (336) 389-3647 Fax (336) 389-3647 ebsite www.dhgriffin.com	8/1/2019 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
D.H. Griffin Wrecking, Inc. 4716 Hilltop Road Greensboro, NC 27407 Comp	Wo pliance Testi No	Phone (336) 389-3647 Fax (336) 389-3647 ebsite www.dhgriffin.com ng and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
D.H. Griffin Wrecking, Inc. 4716 Hilltop Road Greensboro, NC 27407 Compa	Wo pliance Testi No No	Phone (336) 389-3647 Fax (336) 389-3647 ebsite www.dhgriffin.com ng and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
D.H. Griffin Wrecking, Inc. 4716 Hilltop Road Greensboro, NC 27407 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	Website No No No No	Phone (336) 389-3647 Fax (336) 389-3647 ebsite www.dhgriffin.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
D.H. Griffin Wrecking, Inc. 4716 Hilltop Road Greensboro, NC 27407 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Website No No No No No No	Phone (336) 389-3647 Fax (336) 389-3647 ebsite www.dhgriffin.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
D.H. Griffin Wrecking, Inc. 4716 Hilltop Road Greensboro, NC 27407 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Wo pliance Testi No No No No No	Phone (336) 389-3647 Fax (336) 389-3647 ebsite www.dhgriffin.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
D.H. Griffin Wrecking, Inc. 4716 Hilltop Road Greensboro, NC 27407 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No No	Phone (336) 389-3647 Fax (336) 389-3647 ebsite www.dhgriffin.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
D.H. Griffin Wrecking, Inc. 4716 Hilltop Road Greensboro, NC 27407 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Wo pliance Testi No No No No No No	Phone (336) 389-3647 Fax (336) 389-3647 ebsite www.dhgriffin.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
D.H. Griffin Wrecking, Inc. 4716 Hilltop Road Greensboro, NC 27407 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (336) 389-3647 Fax (336) 389-3647 ebsite www.dhgriffin.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
D.H. Griffin Wrecking, Inc. 4716 Hilltop Road Greensboro, NC 27407 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (336) 389-3647 Fax (336) 389-3647 ebsite www.dhgriffin.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
D.H. Griffin Wrecking, Inc. 4716 Hilltop Road Greensboro, NC 27407 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (336) 389-3647 Fax (336) 389-3647 ebsite www.dhgriffin.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
D.H. Griffin Wrecking, Inc. 4716 Hilltop Road Greensboro, NC 27407 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Entergency Cleanup - Spill/Release:	No N	Phone (336) 389-3647 Fax (336) 389-3647 ebsite www.dhgriffin.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
D.H. Griffin Wrecking, Inc. 4716 Hilltop Road Greensboro, NC 27407 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (336) 389-3647 Fax (336) 389-3647 ebsite www.dhgriffin.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List (C	oastal)		
Company		Listing Submitted		Area of state conducts work	
East Carolina Petroleum Services Inc		Phone (252) 339-3655		Coastal (East of I-95): Yes	
PO Box 1923		Fax (252) 331-2754		Central (West of I-95 and East of I-77): No	
510 W Broad Street Elizabeth City, NC 27909		, ,		Mountains (West of I-77): No	
Elizabeth City, NC 27909		Website ecpetro.com			
Comp	oliance Te	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
Eı	nvironmer	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	l No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	5/26/2020	Area of state conducts work	
East Coast Environmental PA		Phone (919) 772-0268		Coastal (East of I-95): Yes	
East Coast Environmental PA 3815 Junction Boulevard		,			
		Phone (919) 772-0268 Fax		Central (West of I-95 and East of I-77): Yes	
3815 Junction Boulevard		,			
3815 Junction Boulevard Raleigh , NC 27603		Fax		Central (West of I-95 and East of I-77): Yes	
3815 Junction Boulevard Raleigh , NC 27603		Fax Website eastcoastenv.com	No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	Yes
3815 Junction Boulevard Raleigh , NC 27603	pliance Te	Fax Website eastcoastenv.com sting and Monitoring	No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors	Yes Yes
3815 Junction Boulevard Raleigh , NC 27603 Comp Automatic Line Leak Detector Testing:	pliance Te	Fax Website eastcoastenv.com sting and Monitoring Overfill Prevention Equipment Operability Check:		Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
3815 Junction Boulevard Raleigh , NC 27603 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	pliance Tes No No	Fax Website eastcoastenv.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	<u>Yes</u>
3815 Junction Boulevard Raleigh , NC 27603 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No No	Fax Website eastcoastenv.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	Yes Yes
3815 Junction Boulevard Raleigh , NC 27603 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No	Fax Website eastcoastenv.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	Yes Yes Yes
3815 Junction Boulevard Raleigh , NC 27603 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	Fax Website eastcoastenv.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	Yes Yes Yes Yes
3815 Junction Boulevard Raleigh , NC 27603 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Fax Website eastcoastenv.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes
3815 Junction Boulevard Raleigh , NC 27603 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Fax Website eastcoastenv.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes Yes
3815 Junction Boulevard Raleigh , NC 27603 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Fax Website eastcoastenv.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
3815 Junction Boulevard Raleigh , NC 27603 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Fax Website eastcoastenv.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
3815 Junction Boulevard Raleigh , NC 27603 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release:	No N	Fax Website eastcoastenv.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: ottal Service Firms UST Compliance Consultants:	No No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
3815 Junction Boulevard Raleigh , NC 27603 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Fax Website eastcoastenv.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: other: Other: Other: Other Compliance Consultants: UST Equipment Verification:	No No No No Ves Yes	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes

Eastern Carolina Environmental Services, Inc. Phone (252) 508-4509 Fax Coastal (East of 1-95): Yes Coastal (East of 1-95): Yes Coastal (East of 1-95): Yes Website Seatern Carolina Environmental East of 1-77): Yes Website Seatern Carolina Environmental East of 1-77): Yes Website Seatern Carolina Environmental East of 1-77): Yes Website Seatern Carolina Environmental Engineering East of 1-77): Yes Website Seatern Carolina Environmental Engineering East of 1-77): Yes Website Seatern Carolina Environmental Engineering East of 1-77): Yes Website Seatern Carolina Environmental Engineering East of 1-77): Yes Website Seatern Carolina Engineering East of 1-77): Yes Website Seatern Carolina Engineering East of 1-77): Yes Website Seatern East of 1			UST Service Provider List (Co	pastal)		
Fax Website Fax Website We	Company		Listing Submitted	8/28/2020	Area of state conducts work	
Website Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Contrainment Suny Testing: No Spill Prevention Equipment Operability Check: No Corrosion Protection System Repairs: No Spill Prevention Equipment Operability Check: No Corrosion Protection System Repairs: No Spill Prevention Equipment Operability Check: No UST Internal Inspections (Integrity Assessments): No UST Internal Inspections (Integrity Assessments): No UST Internal Inspections (Integrity Assessments): No UST Equipment Operability Check: No UST Internal Inspections (Integrity Assessments): No UST Equipment Operability Check: No UST Equipment Operability Check: No UST Internal Inspections (Integrity Assessments): No UST Equipment Operability Check: No UST Equipment Opera	Eastern Carolina Environmental Services, Inc.		Phone (252) 508-4509		Coastal (East of I-95): Yes	
Website Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Overfill Prevention Equipment Operability Check: No Spill Prevention Equipment Operability Check: No Ocrosion Protection System Repairs: No Tark Tightness Testing: No UST Internal lines peculoris (integrity Assessments): No UST Internal lines prepared on the Complete Systems: No Other: Lask Detection Equipment Operability Check: No UST Internal lines Inspections: No Other: Lask Detection Equipment Operability Check: No UST Internal lines Inspections: No Other: Emergency Clearup - Spill/Release: No UST Compliance Consultants: No Other: Monitoring Services: No Ust Equipment Prepair: No UST System Installation: Complete Systems: No UST System Installation: No UST System Installation: Complete Systems: No UST System Installation: No UST System Removal: UST System Removal: UST System Removal: Other: Emergency Clearup - Spill/Release: No UST Equipment Prepair: No UST System Removal: No UST Equipment Installation Services: No UST Equipment System Removal: No UST Equipment Removal: No UST Equipment	1450 Johnson Drive		Fax		Central (West of I-95 and East of I-77): Yes	
Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Disponser Meter Repair/Calibration: No Statistical Ventroy Reconcilation Services: No Spill Bruseration Services: No Spill Bruseration Services: No Spill Prevention Equipment Testing: No Spill Bruseration Services: No UST Equipment Installation Chiter: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST System Installation - Chiter: No UST System Installation - Chiter: No UST System Installation: No UST System Installati	Williamston, NC 27892	,	Mahaita		Mountains (West of I-77): Yes	
Automateic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Octroation Protection Design Experts: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No Tank Tightness Testing: No UST Internal Lining Inspections (Integrity Assessments): No UST Equipment Installation - Other: No UST Internal Lining Inspections: No UST Internal Lining Inspections: No UST Equipment Repairs: No UST System Installation - Other: No UST System Installation:						
Containment Sump Testing: No Satistical Joentory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Bucket Installation Equipment Installation Servicing: No Corrosion Protection Design Experts: No Tank Trightness Testing: No UST Internal Inspections: No UST Internal Inspections: No UST Internal Lining Inspections: No UST Internal Lining Inspections: No UST Internal Lining Inspections: No UST Internal Inspections: No UST Internal Inspections: No UST Internal Inspections: No UST Internal Lining Inspections: No UST Compliance Consultants: No UST System Installation - Complete Systems: No UST Complete System System System Installation - Complete Systems: No UST Equipment Service Strems: No UST Internal Lining Inspections: No UST System Repair: No UST System Repair: No UST System Repair: No U	Comp	liance Tes	sting and Monitoring			
Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No UST Equipment Repairs: No UST Internal Inspections (Integrity Assessments): No UST Equipment (Integrity Assessments): N	Automatic Line Leak Detector Testing:	No		No		No
Corrosion Protection System Repairs: No UST Internal Inspections: No UST Payment Repair: No UST System Installation - Complete Systems: No UST System Installation: No UST System Removal: No UST Removement Verification: No UST Equipment Verification: No UST Equipment Verification: No UST Equipment Verification: No UST Equipment Verification: No UST System Removal: No UST Sys		No		No		No
Corrosion Protection System Teating: No UST Internal Inspections (Integrity Assassments): No Leak Detection Monitoring Services: No Other: No UST Neumant Inspections: No Other: No UST Repuir Installation - Complete Systems: No Leak Detection Monitoring Services: No Other: No UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST System Removal:		No		No		No
Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No UST System Installation - Complete Systems: No UST Complete Systems: No UST System Removal: No UST S		No		No	UST Equipment Installation - Other:	No
Leak Detection Monitoring Services: No Other: Listing Straing: No Other: Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No Other: Emergency Cleanup - Spill/Release: No UST Equipment Verification: No Other: Emergency Cleanup - Spill/Release: No UST Equipment Verification: No Other: Monitoring Well Construction and Abandonment Soli and Solvent Recycling: No Other: Monitoring Well Construction and Abandonment Soli and Solvent Recycling: No Other: Monitoring Well Construction and Abandonment Soli and Water Testing Lab: Phone (910) 843-4456 EMEC Environmental Phone (910) 843-4456 EFAX (910) 843-5376 Website Complance Testing and Monitoring Website Complance Testing and Monitoring Listing Submitted 2/1/2021 Area of state conducts work Control (West of 1-95 and East of 1-77): Yes Mountains (West of 1-77): No Corrolationets Sump Testing: No Overfill Prevention Equipment Operability Check: No Containment Sump Testing: No Spill Brokention System Repairs: No Spill Prevention Equipment Testing: No Corrosion Protection System Repairs: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: No UST System Installation - Other: No UST System Testing: No Other: No UST System Installation - Other No UST System Install	Corrosion Protection System Testing:	No		No		No
Line Tightness Testing: No Environmental Service Firms No Other:	Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Emergency Cleanup - Spill/Release: No UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Oil and Solvent Recycling: No Other: Monitoring Well Construction and Abandonment Soil and Solvent Recycling: No Other: Monitoring Well Construction and Abandonment Soil and Solvent Recycling: No Other: Monitoring Well Construction and Abandonment Soil and Solvent Recycling: No Other: Monitoring Well Construction and Abandonment Soil and Solvent Recycling: No Other: Monitoring Well Construction and Abandonment Soil and Water Testing Lab: No Other: Monitoring Well Construction and Abandonment Soil and Water Testing Lab: No Other: Monitoring Well Construction and Abandonment Soil and Water Testing Lab: No Other: Monitoring Well Construction and Abandonment Soil and Water Testing Lab: No Website Fax (910) 843-4456 Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No Website UST Equipment Service Contractors Website UST Equipment Service Contractors Dispenser Meter Repair/Calibration: No Containment Sump Testing: No Spill Prevention Equipment Testing: No Spill Revention Equipment Testing: No Spill Revention Equipment Testing: No Spill Revention Equipment Testing: No UST Internal Lining Inspections: No UST Internal Lining Inspections: No UST Internal Lining Inspections: No UST Requipment Installation - Other: No UST System Installation - Other: No UST System Installation: No UST Sy	Leak Detection Monitoring Services:	No	Other:			No
Energency Cleanup - Spill/Release: No UST Equipment Verification: No Other: Monitoring Well Construction and Abandonment Company	Line Tightness Testing:	No			UST System Removal:	No
Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: No Other: Monitoring Well Construction and Abandonment Soil and Solvent Recycling: No Other: Monitoring Well Construction and Abandonment Listing Submitted 2/1/2021 Area of state conducts work Company Listing Submitted 2/1/2021 Area of state conducts work EHC Environmental Phone (910) 843-4456 Fax (910) 843-5376 Central (West of I-95): Yes Others of I-95,	Er	vironmen	tal Service Firms		Other:	
Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: No Other: Monitoring Well Construction and Abandonment Soil and Solvent Recycling: No Other: Monitoring Well Construction and Abandonment Listing Submitted 2/1/2021 Area of state conducts work Company Listing Submitted 2/1/2021 Area of state conducts work EHC Environmental Phone (910) 843-4456 Fax (910) 843-5376 Central (West of I-95): Yes Others of I-95,	Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist Soil and GW Cleanu No Other: Monitoring Well Construction and Abandonment Soil and Solvent Recycling: No Other: Monitoring Well Construction and Abandonment Soil and Water Testing Lab: No		No		No		
Oil and Solvent Recycling: Soil and Water Testing Lab: No The phone (910) 843-4456 207 West Fourth Avenue Red Springs, NC 28377 Website Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No Corrosion Protection System Repairs: No Spill Sucket Installation - Complete Systems: No Corrosion Equipment Operability Check: No Corrosion Equipment Service Environmental Engineer/Geologist - Site Checks: No UST Equipment Version: No UST Equipment Repair: No UST Equipment Repair: No UST System Removal: Yes Other: Area of state conducts work Coastal (East of I-95): Yes Central (West of I-95) and East of I-77): Yes Mountains (West of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors UST Equipment Service Contractors No Leak Detection Equipment Installation Servicing: No UST Equipment Testing: No UST Equipment Repair: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST Piping/Sump Installation: No UST System Removal: Yes Other: Emergency Cleanup - Spill/Release: No UST Equipment Repair: No UST System Removal: Yes Other: Other: Area of state conducts work Central (West of I-77): Yes Central (West of I-77): Yes Central (West of I-77): Yes Central (West of I-77): No UST Equipment Repair: No Leak Detection Aguipment Installation Servicies: No UST Equipment Repair: No UST System Installation: UST System Removal: Yes Other: Other: Other: Other: Other: Other: Other: Other:		No		No		
Listing Submitted Z/1/2021 Area of state conducts work		No		onment		
EHC Environmental 207 West Fourth Avenue Red Springs, NC 28377 Website Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Corrosion Protection System Repairs: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Note: No UST Internal Lining Inspections: No UST System Installation - Other: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST Piping/Sump Installation: No UST System Removal: Yes Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: No Waste Disposal and Treatment: Yes Oll and Solvent Recycling: Yes Other: pandonments, Phase I ESA's, Landfarm Soil Disposal	Soil and Water Testing Lab:	No	ů .			
## Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No ## Website Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No Website	Company		Listing Submitted	2/1/2021	Area of state conducts work	
## Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No ## Website Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No Website	EHC Environmental		Phone (910) 843-4456		Coastal (East of I-95): Yes	
Website Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Servicing: No Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Other: No UST System Installation - Complete Systems: No UST System Installation - Other: No UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST System Installation: No UST System Repair: No UST System Installation: No UST System Removal: Yes Other: Environmental Service Firms Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: No Waste Disposal and Treatment: Yes Other: Jandonments, Phase I ESA's, Landfarm Soil Disposal	207 West Fourth Avenue					
Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Ocortainment Sump Testing: No Statistical Iventory Reconciliation Services: No Ocortainment Sump Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Brevention Equipment Testing: No UST Equipment Installation Servicing: No Ocorrosion Protection System Repairs: No UST Equipment Installation Servicing: No UST Equipment Installation - Other: No UST Equipment Installation - Other: No UST Equipment Repair: No UST Equipment Installation - Other: No UST Equipment Installation - Other: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Installation: No UST System Installation: No UST System Removal: Ves Other: Emergency Cleanup - Spill/Release: Yes Other: Dandonmental Engineer/Geologist - Site Checks: No UST Equipment Verification: No UST Equip	Red Springs, NC 28377		(010) 040 0010			
Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Servicing: No Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Other: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Installation: No UST System Removal: Yes Other: No UST Equipment Repair: No UST System Removal: Yes Other: No UST Equipment Repair: No UST System Removal: Yes Other: No UST Equipment No UST System Removal: Yes Other: No UST Equipment Repair: No UST System Removal: Yes Other: Ot		1	Website		Mountains (West of I-77): NO	
Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: No UST System Installation - Other: No UST System Installation - Other: No UST Equipment Repair: No UST System Installation - Other: No UST Equipment Repair: No UST System Installation - Other: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST Piping/Sump Installation: No UST System Removal: Ves UST System Removal: Ves Other: pandonments Preatment: Yes Other: pandonments, Phase I ESA's, Landfarm Soil Disposal	Comp	liance Tes	sting and Monitoring		UST Equipmment Service Contractors	
Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Equipment Installation - Other: No Corrosion Protection System Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST System Installation: No UST System Installation: No UST System Removal: Yes Emergency Cleanup - Spill/Release: Yes UST Compliance Consultants: No UST System Removal: Yes Other: And Solvent Recycling: Yes Other: andonments, Phase I ESA's, Landfarm Soil Disposal	Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Other: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: UST System Removal: Yes Emergency Cleanup - Spill/Release: Yes UST Compliance Consultants: No UST Equipment Verification: No Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: N	Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection System Testing: No UST Internal Inspections (Integrity Assessments): No Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Ves UST System Removal: Ves Other: Environmental Service Firms	Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST Piping/Sump Installation: No UST System Removal: Yes Complete Systems: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: Yes Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No UST System Removal: Yes Complete Systems: No UST Piping/Sump Installation: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Installation: No U	Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Leak Detection Monitoring Services: No Other: UST Piping/Sump Installation: No UST System Removal: Yes Other: Cher: UST System Removal: Yes Other: Other: UST System Removal: Yes Other: Ot	Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Line Tightness Testing: Environmental Service Firms	Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Emergency Cleanup - Spill/Release: Yes UST Compliance Consultants: No Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: No Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: Yes Other: pandonments, Phase I ESA's, Landfarm Soil Disposal	Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Emergency Cleanup - Spill/Release: Yes UST Compliance Consultants: No Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: No Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: Yes Other: pandonments, Phase I ESA's, Landfarm Soil Disposal	Line Tightness Testing:	No				<u>Yes</u>
Environmental Engineer/Geologist - Site Checks: No UST Equipment Verification: No Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: Yes Oil and Solvent Recycling: Yes Other: pandonments, Phase I ESA's, Landfarm Soil Disposal	Er	nvironmen	tal Service Firms		Other:	
Environmental Engineer/Geologist Soil and GW Cleanu No Waste Disposal and Treatment: Yes Oil and Solvent Recycling: Yes Other: pandonments, Phase I ESA's, Landfarm Soil Disposal	Emergency Cleanup - Spill/Pelease:	Yes	UST Compliance Consultants:	No		
Oil and Solvent Recycling: Yes Other: pandonments, Phase I ESA's, Landfarm Soil Disposal	Emergency Cleanup - Spill/Release.			NI-		
	Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	NO		
	Environmental Engineer/Geologist - Site Checks:	No	Waste Disposal and Treatment:	<u>Yes</u>		

		UST Service Provider List (Co	pastal)		
Company		Listing Submitted		Area of state conducts work	
EMS Environmental, Inc.		Phone (919) 596-0470		Coastal (East of I-95): Yes	
117 South Hoover Road		Fax (919) 596-0578		Central (West of I-95 and East of I-77): Yes	
Durham, NC 27703		Website www.emsenv.com		Mountains (West of I-77): Yes	
		<u> </u>			
-	oliance Te	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironmer	ital Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	<u>Yes</u>				
Company		Listing Submitted	7/30/2020	Area of state conducts work	
Company Environmental Contracting & Consulting Servi	ices, P	Phone (757) 912-2276	7/30/2020	Area of state conducts work Coastal (East of I-95): Yes	
Environmental Contracting & Consulting Serving 10 3rd Avenue	ices, P		7/30/2020	Coastal (East of I-95): Yes	
Environmental Contracting & Consulting Servi	ices, P	Phone (757) 912-2276	7/30/2020	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No	
Environmental Contracting & Consulting Servi		Phone (757) 912-2276	7/30/2020	Coastal (East of I-95): Yes	
Environmental Contracting & Consulting Serving 10 3rd Avenue Southern Shores, NC 27949		Phone (757) 912-2276 Fax	7/30/2020	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No	
Environmental Contracting & Consulting Serving 10 3rd Avenue Southern Shores, NC 27949 Company Automatic Line Leak Detector Testing:		Phone (757) 912-2276 Fax Website	7/30/2020 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No	No
Environmental Contracting & Consulting Serving 10 3rd Avenue Southern Shores, NC 27949 Compared Automatic Line Leak Detector Testing: Containment Sump Testing:	oliance Te	Phone (757) 912-2276 Fax Website sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Environmental Contracting & Consulting Serving 10 3rd Avenue Southern Shores, NC 27949 Compared Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	oliance Te No	Phone (757) 912-2276 Fax Website sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	
Environmental Contracting & Consulting Serving 10 3rd Avenue Southern Shores, NC 27949 Compared Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	pliance Te No No	Phone (757) 912-2276 Fax Website sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Environmental Contracting & Consulting Serving 10 3rd Avenue Southern Shores, NC 27949 Compared Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No	Phone (757) 912-2276 Fax Website sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No
Environmental Contracting & Consulting Serving 10 3rd Avenue Southern Shores, NC 27949 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (757) 912-2276 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
Environmental Contracting & Consulting Services: 10 3rd Avenue Southern Shores, NC 27949 Comparison of Comparison of Comparison of Comparison of Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No No No	Phone (757) 912-2276 Fax Website sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Environmental Contracting & Consulting Serving 10 3rd Avenue Southern Shores, NC 27949 Compared Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (757) 912-2276 Fax Website Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Environmental Contracting & Consulting Services: 10 3rd Avenue Southern Shores, NC 27949 Comparison Comparison Containment Sump Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (757) 912-2276 Fax Website sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Environmental Contracting & Consulting Services 10 3rd Avenue Southern Shores, NC 27949 Compared Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Erregency Cleanup - Spill/Release:	No No No No No No No No No No	Phone (757) 912-2276 Fax Website sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: ottal Service Firms UST Compliance Consultants:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Environmental Contracting & Consulting Services: 10 3rd Avenue Southern Shores, NC 27949 Comparison of Comparison of Comparison of Comparison of Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Environmental Engineer/Geologist - Site Checks:	No N	Phone (757) 912-2276 Fax Website sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: utal Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Environmental Contracting & Consulting Services: 10 3rd Avenue Southern Shores, NC 27949 Comparison of Comparison of Comparison of Comparison of Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanup	No N	Phone (757) 912-2276 Fax Website sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: utal Service Firms UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Environmental Contracting & Consulting Serving 10 3rd Avenue Southern Shores, NC 27949 Compared Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Environmental Engineer/Geologist - Site Checks:	No N	Phone (757) 912-2276 Fax Website sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: utal Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No Ves Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): No Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List (C	oastal)		
Company		Listing Submitted		Area of state conducts work	
Environmental Laboratories, Inc		Phone (864) 370-0637		Coastal (East of I-95): Yes	
PO Box 1729		Fax (864) 752-0948		Central (West of I-95 and East of I-77): Yes	
Travelers Rest, SC 29609				Mountains (West of I-77): Yes	
	V	Vebsite www.elabsinc.net		,	
Comp	oliance Test	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
Er	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	d 11/15/2018	Area of state conducts work	
EnviroTrac Ltd.		Phone (336) 763-6025		Coastal (East of I-95): Yes	
7343 West Friendly Avenue		Phone (336) 763-6025 Fax		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
		Fax		Central (West of I-95 and East of I-77): Yes	
7343 West Friendly Avenue	V	·			
7343 West Friendly Avenue Greensboro, NC 27410		Fax		Central (West of I-95 and East of I-77): Yes	
7343 West Friendly Avenue Greensboro, NC 27410		Fax Vebsite www.envirotrac.com	No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
7343 West Friendly Avenue Greensboro, NC 27410 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	pliance Test	Fax Vebsite www.envirotrac.com ting and Monitoring	No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
7343 West Friendly Avenue Greensboro, NC 27410 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	pliance Test	Fax Vebsite www.envirotrac.com ting and Monitoring Overfill Prevention Equipment Operability Check:		Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	
7343 West Friendly Avenue Greensboro, NC 27410 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No	Fax Vebsite www.envirotrac.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No
7343 West Friendly Avenue Greensboro, NC 27410 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No	Fax Vebsite www.envirotrac.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No
7343 West Friendly Avenue Greensboro, NC 27410 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Fax Vebsite www.envirotrac.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
7343 West Friendly Avenue Greensboro, NC 27410 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No No No	Fax Vebsite www.envirotrac.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
7343 West Friendly Avenue Greensboro, NC 27410 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Fax Vebsite www.envirotrac.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
7343 West Friendly Avenue Greensboro, NC 27410 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Fax Vebsite www.envirotrac.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
7343 West Friendly Avenue Greensboro, NC 27410 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release:	No N	Fax Vebsite www.envirotrac.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
7343 West Friendly Avenue Greensboro, NC 27410 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Fax Vebsite www.envirotrac.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
7343 West Friendly Avenue Greensboro, NC 27410 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No N	Fax Vebsite www.envirotrac.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants:	No No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
7343 West Friendly Avenue Greensboro, NC 27410 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Fax Vebsite www.envirotrac.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST	Service Provider List (Co	astal)		
Company			Listing Submitted		Area of state conducts work	
Evo Corporation		Phone	(336) 725-5844		Coastal (East of I-95): Yes	
1703 Vargrave Street		Fax	(336) 725-6244		Central (West of I-95 and East of I-77): Yes	
Winston-Salem, NC 27107		W . I . M .			Mountains (West of I-77): Yes	
	V	Vebsite	www.evocorp.net		, ,	
Comp	pliance Tes	ting and	Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No		Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No		cal Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No		evention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No		ghtness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No		ternal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Int	ternal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	No				UST System Removal:	<u>Yes</u>
E	nvironment	al Servic	ce Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Co	ompliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No		quipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	. No		Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	<u>Yes</u>	Other:	•			
Soil and Water Testing Lab:	No					
Company			Listing Submitted	7/29/2020	Area of state conducts work	
Company Excel Environmental Associates, PLLC		Phone		7/29/2020	Area of state conducts work Coastal (East of I-95): Yes	
• •		_	(704) 853-0800	7/29/2020	Coastal (East of I-95): Yes	
Excel Environmental Associates, PLLC		Phone Fax		7/29/2020	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Excel Environmental Associates, PLLC 625 Huntsman Court	V	_	(704) 853-0800	7/29/2020	Coastal (East of I-95): Yes	
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054		Fax Vebsite	(704) 853-0800 (704) 853-3949	7/29/2020	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054		Fax Vebsite ting and	(704) 853-0800 (704) 853-3949 www.excelengr.com	7/29/2020 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054	pliance Tes	Fax Vebsite ting and Overfill	(704) 853-0800 (704) 853-3949 www.excelengr.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comparison C	pliance Tes	Fax Vebsite ting and Overfill Statistic	(704) 853-0800 (704) 853-3949 www.excelengr.com Monitoring Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comparison Line Leak Detector Testing: Containment Sump Testing:	pliance Tes No No	Fax Vebsite ting and Overfill Statistic Spill Pre	(704) 853-0800 (704) 853-3949 www.excelengr.com Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comparison Comparison Containment Sump Testing: Corrosion Protection Design Experts:	pliance Tes No No No	Fax Vebsite ting and Overfill Statistic Spill Pre Tank Ti	(704) 853-0800 (704) 853-3949 www.excelengr.com I Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Fax Vebsite ting and Overfill Statistic Spill Pre Tank Tie UST Int UST Int	(704) 853-0800 (704) 853-3949 www.excelengr.com I Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No	Fax Vebsite ting and Overfill Statistic Spill Pre Tank Tic UST Int	(704) 853-0800 (704) 853-3949 www.excelengr.com Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing: ternal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Fax Vebsite ting and Overfill Statistic Spill Pre Tank Tie UST Int UST Int	(704) 853-0800 (704) 853-3949 www.excelengr.com Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing: ternal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comparison Comparison Containment Sump Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No	Fax Vebsite ting and Overfill Statistic Spill Pre Tank Tic UST Int UST Int Other:	(704) 853-0800 (704) 853-3949 www.excelengr.com I Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing: ternal Inspections (Integrity Assessments): ternal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comparison Comparison Containment Sump Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Fax Vebsite ting and Overfill Statistic Spill Pre Tank Ti UST Int UST Int Other:	(704) 853-0800 (704) 853-3949 www.excelengr.com I Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing: ternal Inspections (Integrity Assessments): ternal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comparison Protection Design Experts: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Fax Vebsite ting and Overfill Statistic Spill Pre Tank Ti UST Int UST Int Other:	(704) 853-0800 (704) 853-3949 www.excelengr.com Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing: ternal Inspections (Integrity Assessments): ternal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release:	No N	Fax Vebsite ting and Overfill Statistic Spill Pre Tank Ti UST Int UST Int Other: al Servic UST Co UST Eq	(704) 853-0800 (704) 853-3949 www.excelengr.com Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing: ternal Inspections (Integrity Assessments): ternal Lining Inspections:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Fax Vebsite ting and Overfill Statistic Spill Pre Tank Ti UST Int UST Int Other: al Servic UST Co UST Eq	(704) 853-0800 (704) 853-3949 www.excelengr.com Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing: ternal Inspections (Integrity Assessments): ternal Lining Inspections: ce Firms compliance Consultants: quipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

	ι	JST Service Provider List (Co	pastal)		
Company		Listing Submitted	8/4/2020	Area of state conducts work	
Fourstar Petroleum	Pl	hone (540) 563-1022		Coastal (East of I-95): Yes	
1119 Beaumont Rd.		Fax (540) 362-1802		Central (West of I-95 and East of I-77): Yes	
Roanoke, VA 24019	Wek	osite www.fourstarpetro.com		Mountains (West of I-77): Yes	
Comm	olionos Tostina	<u> </u>		UST Equipmment Service Contractors	
		g and Monitoring	Na		Vaa
Automatic Line Leak Detector Testing:		Overfill Prevention Equipment Operability Check:	No No	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing: Corrosion Protection Design Experts:		Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection Design Experts. Corrosion Protection System Repairs:		iank Tightness Testing:	No No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Repairs. Corrosion Protection System Testing:		IST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:		IST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:		Other:	INO	UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No	outer.		UST System Removal:	<u>Yes</u> Yes
				Other: Wayne Dispensers and Verifor	
	nvironmental S			Wayne Dispensers and Venior	101 00
Emergency Cleanup - Spill/Release:		JST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:		JST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Vaste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No O	Other:			
Soil and Water Testing Lab:	No				
Company		Linting Culturalities		Avec of state and desta words	
ouniparty .		Listing Submitted	11/14/2018	Area of state conducts work	
Galloway	Pi	hone (303) 770-8884	11/14/2018	Coastal (East of I-95): Yes	
Galloway 6162 South Willow Drive	Pi	<u> </u>	11/14/2018		
Galloway 6162 South Willow Drive Suite 320	PI	hone (303) 770-8884 Fax (303) 770-3636	11/14/2018	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Galloway 6162 South Willow Drive		hone (303) 770-8884	11/14/2018	Coastal (East of I-95): Yes	
Galloway 6162 South Willow Drive Suite 320 Greenwood Village, CO 80111	Web	hone (303) 770-8884 Fax (303) 770-3636	11/14/2018	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Galloway 6162 South Willow Drive Suite 320 Greenwood Village, CO 80111	Web	hone (303) 770-8884 Fax (303) 770-3636 psite www.GallowayUS.com	11/14/2018 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Galloway 6162 South Willow Drive Suite 320 Greenwood Village, CO 80111 Comp	Web	hone (303) 770-8884 Fax (303) 770-3636 psite www.GallowayUS.com g and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Galloway 6162 South Willow Drive Suite 320 Greenwood Village, CO 80111 Compa	Web Dliance Testing No O No S	hone (303) 770-8884 Fax (303) 770-3636 psite www.GallowayUS.com g and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Galloway 6162 South Willow Drive Suite 320 Greenwood Village, CO 80111 Compa Automatic Line Leak Detector Testing: Containment Sump Testing:	Web Diance Testing No O No S No S	hone (303) 770-8884 Fax (303) 770-3636 Disite www.GallowayUS.com g and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Galloway 6162 South Willow Drive Suite 320 Greenwood Village, CO 80111 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Web Diance Testing No O No S No S No T	hone (303) 770-8884 Fax (303) 770-8884 psite www.GallowayUS.com g and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Galloway 6162 South Willow Drive Suite 320 Greenwood Village, CO 80111 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No ONO SONO TO NO TO NO TO NO TO NO TO NO U	hone (303) 770-8884 Fax (303) 770-3636 psite www.GallowayUS.com g and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Galloway 6162 South Willow Drive Suite 320 Greenwood Village, CO 80111 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No ONO SONO TO NO UNO U	hone (303) 770-8884 Fax (303) 770-3636 psite www.GallowayUS.com g and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Sank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Galloway 6162 South Willow Drive Suite 320 Greenwood Village, CO 80111 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No ONO SONO TO NO UNO U	hone (303) 770-8884 Fax (303) 770-3636 psite www.GallowayUS.com g and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
Galloway 6162 South Willow Drive Suite 320 Greenwood Village, CO 80111 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No ONO S NO S NO S NO T NO U NO U NO O	hone (303) 770-8884 Fax (303) 770-3636 psite www.GallowayUS.com g and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Sank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Galloway 6162 South Willow Drive Suite 320 Greenwood Village, CO 80111 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No ONO TO NO ONO ONO ONO ONO ONO ONO ONO O	hone (303) 770-8884 Fax (303) 770-3636 psite www.GallowayUS.com g and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Sank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Galloway 6162 South Willow Drive Suite 320 Greenwood Village, CO 80111 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No ONO ONO ONO ONO ONO ONO ONO ONO ONO O	hone (303) 770-8884 Fax (303) 770-3636 posite www.GallowayUS.com g and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Sank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Galloway 6162 South Willow Drive Suite 320 Greenwood Village, CO 80111 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No ONO UNO NO UNO NO UNO NO ONO NO ONO NO ONO NO ONO NO ONO O	hone (303) 770-8884 Fax (303) 770-3636 psite www.GallowayUS.com g and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Galloway 6162 South Willow Drive Suite 320 Greenwood Village, CO 80111 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No ONO ONO ONO ONO ONO ONO ONO ONO ONO O	hone (303) 770-8884 Fax (303) 770-3636 psite www.GallowayUS.com g and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Galloway 6162 South Willow Drive Suite 320 Greenwood Village, CO 80111 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No ONO ONO ONO ONO ONO ONO ONO ONO ONO O	hone (303) 770-8884 Fax (303) 770-3636 psite www.GallowayUS.com g and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: UST Equipment Verification: Vaste Disposal and Treatment:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

		UST Service Provider List (Co	astal)		
Company		Listing Submitted	11/9/2018	Area of state conducts work	
Geo-Hydro Engineers, Inc.		Phone (704) 837-7174		Coastal (East of I-95): Yes	
2748 Interstate Street		Fax		Central (West of I-95 and East of I-77): Yes	
Suite A				Mountains (West of I-77): Yes	
Charlotte, NC 28208		Website www.geohydro.com		mountains (West 01177). 103	
Com	pliance Te	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
E	nvironme	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	yes	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	11/14/2018	Area of state conducts work	
Geological Resources, Inc.		Phone (704) 845-4010		Coastal (East of I-95): Yes	
3502 Hayes Road		Fax (704) 845-4012		Central (West of I-95 and East of I-77): Yes	
Monroe, NC 28110		(101) 010 1012			
		Website www.geologicalresourcesinc.com		Mountains (West of I-77): Yes	
Com	pliance Te	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
E	nvironme	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

		UST Service Provider List (Co	astal)		
Company		Listing Submitted		Area of state conducts work	
GREENWOOD APPLIED SERVICES LLC		Phone (252) 398-6022		Coastal (East of I-95): Yes	
P.O. BOX 238		Fax (252) 356-2208		Central (West of I-95 and East of I-77): No	
COLERAIN, NC 27924		(===, =======		Mountains (West of I-77): No	
	V	Website www.greenwoodapplied.com		mountains (West of 1-77). No	
Comp	oliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other: Landfarm Soil Disposal, MMPE,AFVR, Well	Drilling		
Soil and Water Testing Lab:	No				
Company		Listing Submitted	11/18/2020	Area of state conducts work	
Company Groundwater Management Associates, Inc.		Phone (252) 758-3310	11/18/2020	Area of state conducts work Coastal (East of I-95): Yes	
Groundwater Management Associates, Inc. 4300 Sapphire Court		Phone (252) 758-3310	11/18/2020	Coastal (East of I-95): Yes	
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100			11/18/2020	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Groundwater Management Associates, Inc. 4300 Sapphire Court	V	Phone (252) 758-3310	11/18/2020	Coastal (East of I-95): Yes	
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834		Phone (252) 758-3310 Fax	11/18/2020	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834		Phone (252) 758-3310 Fax Vebsite www.gma-nc.com	11/18/2020 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834 Comp	oliance Tes	Phone (252) 758-3310 Fax Vebsite www.gma-nc.com ting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834 Compa	oliance Tes No	Phone (252) 758-3310 Fax Vebsite www.gma-nc.com ting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	No No	Phone (252) 758-3310 Fax Vebsite www.gma-nc.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No No	Phone (252) 758-3310 Fax Website www.gma-nc.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (252) 758-3310 Fax Website www.gma-nc.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No No No	Phone (252) 758-3310 Fax Website www.gma-nc.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (252) 758-3310 Fax Website www.gma-nc.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (252) 758-3310 Fax Website www.gma-nc.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (252) 758-3310 Fax Website www.gma-nc.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (252) 758-3310 Fax Website www.gma-nc.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No N	Phone (252) 758-3310 Fax Vebsite www.gma-nc.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Groundwater Management Associates, Inc. 4300 Sapphire Court Suite 100 Greenville, NC 27834 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (252) 758-3310 Fax Website www.gma-nc.com ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List (Co	astal)		
Company		Listing Submitted		Area of state conducts work	
HARCO Services LLC		Phone (770) 917-8846		Coastal (East of I-95): Yes	
PO Box 2347		Fax (770) 917-0921		Central (West of I-95 and East of I-77): Yes	
Kennesaw, GA 30156				Mountains (West of I-77): Yes	
	We	ebsite www.harcoservices.com			
Comp	pliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
E	nvironmenta	I Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	ı No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	1/15/2019	Area of state conducts work	
Company Henry Nemargut Engineering Services		Phone (336) 316-0452	1/15/2019	Area of state conducts work Coastal (East of I-95): Yes	
		Phone (336) 316-0452	1/15/2019	Coastal (East of I-95): Yes	
Henry Nemargut Engineering Services			1/15/2019	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Henry Nemargut Engineering Services 2211 Chestnut Street		Phone (336) 316-0452	1/15/2019	Coastal (East of I-95): Yes	
Henry Nemargut Engineering Services 2211 Chestnut Street Wilmington, NC 28403	We	Phone (336) 316-0452 Fax (910) 762-3284	1/15/2019	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Henry Nemargut Engineering Services 2211 Chestnut Street Wilmington, NC 28403	We	Phone (336) 316-0452 Fax (910) 762-3284 ebsite	1/15/2019 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Henry Nemargut Engineering Services 2211 Chestnut Street Wilmington, NC 28403	Wo pliance Testi No	Phone (336) 316-0452 Fax (910) 762-3284 ebsite ng and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
Henry Nemargut Engineering Services 2211 Chestnut Street Wilmington, NC 28403 Comparing Leak Detector Testing:	Wo pliance Testi No No	Phone (336) 316-0452 Fax (910) 762-3284 ebsite ng and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Henry Nemargut Engineering Services 2211 Chestnut Street Wilmington, NC 28403 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	Wepliance Testi No No No	Phone (336) 316-0452 Fax (910) 762-3284 ebsite ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Henry Nemargut Engineering Services 2211 Chestnut Street Wilmington, NC 28403 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Website No No No No No No	Phone (336) 316-0452 Fax (910) 762-3284 ebsite ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Henry Nemargut Engineering Services 2211 Chestnut Street Wilmington, NC 28403 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Wo pliance Testi No No No No No	Phone (336) 316-0452 Fax (910) 762-3284 ebsite ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Henry Nemargut Engineering Services 2211 Chestnut Street Wilmington, NC 28403 Comparison Comparison Comparison Comparison Comparison Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No No	Phone (336) 316-0452 Fax (910) 762-3284 ebsite ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No
Henry Nemargut Engineering Services 2211 Chestnut Street Wilmington, NC 28403 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (336) 316-0452 Fax (910) 762-3284 ebsite ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Henry Nemargut Engineering Services 2211 Chestnut Street Wilmington, NC 28403 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (336) 316-0452 Fax (910) 762-3284 ebsite ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Henry Nemargut Engineering Services 2211 Chestnut Street Wilmington, NC 28403 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Pliance Testi No	Phone (336) 316-0452 Fax (910) 762-3284 ebsite ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Henry Nemargut Engineering Services 2211 Chestnut Street Wilmington, NC 28403 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (336) 316-0452 Fax (910) 762-3284 ebsite ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Henry Nemargut Engineering Services 2211 Chestnut Street Wilmington, NC 28403 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	Pliance Testi No	Phone (336) 316-0452 Fax (910) 762-3284 ebsite ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Henry Nemargut Engineering Services 2211 Chestnut Street Wilmington, NC 28403 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (336) 316-0452 Fax (910) 762-3284 ebsite ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

Company Highlands Environmental Solutions, Inc. Phone (919) 848-3155 Coastal (East of I-95): Yes 8410-D Falls of Neuse Road Raleigh, NC 27615 Fax (919) 848-4265 Mountains (West of I-77): Yes	
8410-D Falls of Neuse Road Raleigh, NC 27615 Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Raleigh, NC 27615	
Mountains (West of I-77): Yes	
W. L. '(
Website www.HESfast.com	
Compliance Testing and Monitoring UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: Yes Dispenser Meter Repair/Calibration:	No
Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: Yes Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Equipment Installation - Other:	No
Corrosion Protection System Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair:	No
Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services: No Other: UST Piping/Sump Installation:	No
Line Tightness Testing: No UST System Removal:	<u>Yes</u>
Environmental Service Firms Other:	
Emergency Cleanup - Spill/Release: Yes UST Compliance Consultants: Yes	
Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No	
Environmental Engineer/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: Yes	
Oil and Solvent Recycling: No Other:	
Soil and Water Testing Lab: No	
Company Listing Submitted 8/18/2020 Area of state conducts work	
INDUSTRY STANDARD CORRSION CONTROL - LLC Phone (252) 229-0485 Coastal (East of I-95): Yes	
400 HARBOR DRIVE Fax (704) 972-0300 Central (West of I-95 and East of I-77): Yes	
NEW BERN, NC 28560	
NEW BERN, NC 28560 Website WWW.ISCC.TECH Mountains (West of I-77): Yes	
NEW BERN, NC 28560	
NEW BERN, NC 28560 Website WWW.ISCC.TECH Mountains (West of I-77): Yes	No
NEW BERN, NC 28560 Website WWW.ISCC.TECH Compliance Testing and Monitoring Website UST Equipment Service Contractors	No No
NEW BERN, NC 28560 Website WWW.ISCC.TECH Compliance Testing and Monitoring UST Equipment Service Contractors Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Corrosion Protection Design Experts: Yes Spill Prevention Equipment Testing: No Spill Bucket Installation Repair:	
NEW BERN, NC 28560 Website WWW.ISCC.TECH Compliance Testing and Monitoring UST Equipmment Service Contractors Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: Corrosion Protection Design Experts: Yes Spill Prevention Equipment Testing: No UST Equipment Installation Repair: Corrosion Protection System Repairs: Yes Tank Tightness Testing: No UST Equipment Installation - Other:	No
Website WWW.ISCC.TECH Compliance Testing and Monitoring UST Equipmment Service Contractors Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: Corrosion Protection Design Experts: Yes Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: Corrosion Protection System Repairs: Yes Tank Tightness Testing: No UST Equipment Installation - Other: Corrosion Protection System Testing: Yes UST Internal Inspections (Integrity Assessments): No UST Equipment Repair:	No No
Website WWW.ISCC.TECH Compliance Testing and Monitoring UST Equipmment Service Contractors Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: Corrosion Protection Design Experts: Yes Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: Corrosion Protection System Repairs: Yes Tank Tightness Testing: No UST Equipment Installation - Other: Corrosion Protection System Testing: No UST Equipment Repair: Leak Detection Equipment Operability Check: No UST System Installation - Complete Systems:	No No No
NEW BERN, NC 28560 Website WWW.ISCC.TECH Compliance Testing and Monitoring UST Equipmment Service Contractors Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: Corrosion Protection Design Experts: Yes Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: Corrosion Protection System Repairs: Yes Tank Tightness Testing: No UST Equipment Installation - Other: Corrosion Protection System Testing: Yes UST Internal Inspections (Integrity Assessments): No UST Equipment Repair:	No No No No
NEW BERN, NC 28560 Website WWW.ISCC.TECH Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: Corrosion Protection Design Experts: Yes Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: Corrosion Protection System Repairs: Yes Tank Tightness Testing: No UST Equipment Installation - Other: Corrosion Protection System Testing: No UST Equipment Repair: Leak Detection Equipment Operability Check: No UST System Installation - Complete Systems:	No No No No
NEW BERN, NC 28560 Website WWW.ISCC.TECH Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: Corrosion Protection Design Experts: Yes Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: Corrosion Protection System Repairs: Yes Tank Tightness Testing: No UST Equipment Installation - Other: Corrosion Protection System Testing: No UST Equipment Repair: Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No UST System Installation - Complete Systems: Leak Detection Monitoring Services: No Other:	No No No No No
NEW BERN, NC 28560 Website WWW.ISCC.TECH Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: Corrosion Protection Design Experts: Yes Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: Corrosion Protection System Repairs: Yes Tank Tightness Testing: No UST Equipment Installation - Other: UST Equipment Repair: UST Equipment Repair: UST Equipment Repair: UST Equipment Repair: Leak Detection Equipment Operability Check: No UST Internal Inspections: No UST System Installation - Complete Systems: UST Piping/Sump Installation: Line Tightness Testing: No UST System Removal:	No No No No No
Website WWW.ISCC.TECH Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: Corrosion Protection Design Experts: Yes Spill Prevention Equipment Testing: Corrosion Protection System Repairs: Yes Tank Tightness Testing: No UST Equipment Installation - Other: Corrosion Protection Equipment Operability Check: No UST Internal Inspections (Integrity Assessments): No UST System Installation - Complete Systems: UST System Installation: UST System Installation: UST System Removal: Other:	No No No No No
Website WWW.ISCC.TECHCompliance Testing and MonitoringUST Equipmment Service ContractorsAutomatic Line Leak Detector Testing:NoOverfill Prevention Equipment Operability Check:NoDispenser Meter Repair/Calibration:Containment Sump Testing:NoStatistical Iventory Reconciliation Services:NoLeak Detection Equipment Installation Servicing:Corrosion Protection Design Experts:YesSpill Prevention Equipment Testing:NoSpill Bucket Installation Repair:Corrosion Protection System Repairs:YesTank Tightness Testing:NoUST Equipment Installation - Other:Corrosion Protection System Testing:YesUST Internal Inspections (Integrity Assessments):NoUST Equipment Repair:Leak Detection Equipment Operability Check:NoUST Internal Lining Inspections:NoUST System Installation - Complete Systems:Leak Detection Monitoring Services:NoOther:UST Piping/Sump Installation:Line Tightness Testing:NoUST Compliance Consultants:Other:Emergency Cleanup - Spill/Release:NoUST Compliance Consultants:No	No No No No No
Mountains (West of I-77): Yes Compliance Testing and Monitoring UST Equipment Service Contractors	No No No No No

		UST Service Provider List (Co	astal)		
Company		Listing Submitted	7/30/2020	Area of state conducts work	
JGD Associates, Inc.		Phone 4409336825		Coastal (East of I-95): Yes	
92 Moore Road		Fax		Central (West of I-95 and East of I-77): Yes	
Avon Lake, Ohio 44012				Mountains (West of I-77): Yes	
	V	Website www.jgdpe.com			
Comp	oliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironment	al Service Firms		Other: UST installation draw	wings
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	11/14/2018	Area of state conducts work	
Johnson, Spellman and Associates		Phone (770) 447-4555		Coastal (East of I-95): Yes	
350 Research Court		Fax		Central (West of I-95 and East of I-77): Yes	
Suite 130					
Peachtree Corners, GA 30092	V	Website www.jsace.com		Mountains (West of I-77): Yes	
Comp	oliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other: System design services - Engir	neering	UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironment	al Service Firms		Other: System design services - Engine	eering
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
				I .	

		UST Service Provider List (Co	astal)		
Company		Listing Submitted	5/27/2020	Area of state conducts work	
Labrador Environmental Consultants, P.C. (ea	astern	Phone (252) 809-9130		Coastal (East of I-95): Yes	
1450 Johnson Drive		Fax		Central (West of I-95 and East of I-77): Yes	
Williamston, NC 27892		Mohaita		Mountains (West of I-77): Yes	
		Website			
Com	pliance Te	esting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
E	nvironme	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other: UST removal/	closure		
Soil and Water Testing Lab:	No				
Company		Listing Submitted	8/18/2020	Area of state conducts work	
Law Petroloum, Inc.				0 (1/5 (105))/	
Law Petroleum, Inc.		Phone (704) 573-3535		Coastal (East of I-95): Yes	
11025 Arlington Church Road		·			
· · · · · · · · · · · · · · · · · · ·		Fax (704) 573-3535		Central (West of I-95 and East of I-77): Yes	
11025 Arlington Church Road		·			
11025 Arlington Church Road Charlotte, NC 28227	pliance Te	Fax (704) 573-3535		Central (West of I-95 and East of I-77): Yes	
11025 Arlington Church Road Charlotte, NC 28227	pliance Te Yes	Fax (704) 573-3535 Website	Yes	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
11025 Arlington Church Road Charlotte, NC 28227		Fax (704) 573-3535 Website esting and Monitoring	Yes No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No Yes
11025 Arlington Church Road Charlotte, NC 28227 Com Automatic Line Leak Detector Testing:	Yes	Fax (704) 573-3535 Website esting and Monitoring Overfill Prevention Equipment Operability Check:		Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
11025 Arlington Church Road Charlotte, NC 28227 Com Automatic Line Leak Detector Testing: Containment Sump Testing:	Yes Yes	Fax (704) 573-3535 Website esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	<u>Yes</u>
11025 Arlington Church Road Charlotte, NC 28227 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	Yes Yes No	Fax (704) 573-3535 Website esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No <u>Yes</u>	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	Yes Yes
11025 Arlington Church Road Charlotte, NC 28227 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Yes Yes No Yes	Fax (704) 573-3535 Website esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No <u>Yes</u> <u>Yes</u>	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	Yes Yes Yes
11025 Arlington Church Road Charlotte, NC 28227 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Yes Yes No Yes Yes	Fax (704) 573-3535 Website Esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No <u>Yes</u> <u>Yes</u> <u>Yes</u>	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes
11025 Arlington Church Road Charlotte, NC 28227 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes Yes No Yes Yes Yes Yes	Fax (704) 573-3535 Website Esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No <u>Yes</u> <u>Yes</u> <u>Yes</u>	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes
Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No Yes Yes Yes Yes Yes Yes	Fax (704) 573-3535 Website Esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No <u>Yes</u> <u>Yes</u> <u>Yes</u>	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes Yes
Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No Yes Yes Yes Yes Yes Yes	Fax (704) 573-3535 Website Esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No <u>Yes</u> <u>Yes</u> <u>Yes</u>	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No Yes Yes Yes Yes Yes Yes Yes Yes Yes	Fax (704) 573-3535 Website Esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No Yes Yes Yes Yes	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No Yes Yes Yes Yes Yes Yes Yes Noironmel	Fax (704) 573-3535 Website Esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Intal Service Firms UST Compliance Consultants:	No Yes Yes Yes Yes Yes	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes
Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes Yes No Yes Yes Yes Yes Yes Yes Yes Noironmel	Fax (704) 573-3535 Website Esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Intal Service Firms UST Compliance Consultants: UST Equipment Verification:	No Yes Yes Yes Yes Yes Yes	Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes Yes

		UST Service Provider List	t (Coastal)		
Company		Listing Sub	mitted 11/14/2018	Area of state conducts work	
McCallum PC		Phone (757) 420-2520		Coastal (East of I-95): Yes	
1808 Hayward Avenue		Fax (757) 424-2874		Central (West of I-95 and East of I-77): No	
Chesapeake, VA 23320		,		Mountains (West of I-77): No	
	1	Website www.mccallumtestinglabs.com			
Comp	pliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Chec	k: No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessment	ts): No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
E	nvironmen	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	·	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Sub	mitted 8/3/2020	Area of state conducts work	
Company MECO, Inc. of Florence		Phone (910) 223-0018	mitted 8/3/2020	Area of state conducts work Coastal (East of I-95): Yes	
• •		Phone (910) 223-0018	mitted 8/3/2020	Coastal (East of I-95): Yes	
MECO, Inc. of Florence			mitted 8/3/2020	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
MECO, Inc. of Florence 316 Raymond Street	,	Phone (910) 223-0018	mitted 8/3/2020	Coastal (East of I-95): Yes	
MECO, Inc. of Florence 316 Raymond Street Fayetteville, NC 28301		Phone (910) 223-0018 Fax (910) 223-0022	mitted 8/3/2020	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
MECO, Inc. of Florence 316 Raymond Street Fayetteville, NC 28301		Phone (910) 223-0018 Fax (910) 223-0022 Website www.mecoflorence.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	
MECO, Inc. of Florence 316 Raymond Street Fayetteville, NC 28301	pliance Tes	Phone (910) 223-0018 Fax (910) 223-0022 Website www.mecoflorence.com Sting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors	
MECO, Inc. of Florence 316 Raymond Street Fayetteville, NC 28301 Comparison	pliance Tes	Phone (910) 223-0018 Fax (910) 223-0022 Website www.mecoflorence.com Sting and Monitoring Overfill Prevention Equipment Operability Chec	.k: <u>Yes</u>	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	<u>Yes</u>
MECO, Inc. of Florence 316 Raymond Street Fayetteville, NC 28301 Comparison Leak Detector Testing: Containment Sump Testing:	pliance Tes Yes Yes	Phone (910) 223-0018 Fax (910) 223-0022 Website www.mecoflorence.com Sting and Monitoring Overfill Prevention Equipment Operability Chec Statistical Iventory Reconciliation Services:	·k: <u>Yes</u> No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	Yes Yes
MECO, Inc. of Florence 316 Raymond Street Fayetteville, NC 28301 Comparison Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	pliance Tes Yes Yes No	Phone (910) 223-0018 Fax (910) 223-0022 Website www.mecoflorence.com Sting and Monitoring Overfill Prevention Equipment Operability Chec Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	k: <u>Yes</u> No <u>Yes</u> No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	Yes Yes Yes
MECO, Inc. of Florence 316 Raymond Street Fayetteville, NC 28301 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	yes Yes No No No No Yes	Phone (910) 223-0018 Fax (910) 223-0022 Website www.mecoflorence.com Sting and Monitoring Overfill Prevention Equipment Operability Chec Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessment UST Internal Lining Inspections:	k: <u>Yes</u> No <u>Yes</u> No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	Yes Yes Yes Yes Yes Yes
MECO, Inc. of Florence 316 Raymond Street Fayetteville, NC 28301 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	Yes Yes No No No Yes Yes Yes Yes	Phone (910) 223-0018 Fax (910) 223-0022 Website www.mecoflorence.com Sting and Monitoring Overfill Prevention Equipment Operability Chec Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessment)	k: <u>Yes</u> No <u>Yes</u> No Is): No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes
MECO, Inc. of Florence 316 Raymond Street Fayetteville, NC 28301 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	yes Yes No No No No Yes	Phone (910) 223-0018 Fax (910) 223-0022 Website www.mecoflorence.com Sting and Monitoring Overfill Prevention Equipment Operability Chec Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessment UST Internal Lining Inspections:	k: <u>Yes</u> No <u>Yes</u> No Is): No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes
MECO, Inc. of Florence 316 Raymond Street Fayetteville, NC 28301 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No No No Yes Yes No	Phone (910) 223-0018 Fax (910) 223-0022 Website www.mecoflorence.com Sting and Monitoring Overfill Prevention Equipment Operability Chec Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessment UST Internal Lining Inspections:	k: <u>Yes</u> No <u>Yes</u> No Is): No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes
MECO, Inc. of Florence 316 Raymond Street Fayetteville, NC 28301 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes No No No Yes Yes No	Phone (910) 223-0018 Fax (910) 223-0022 Website www.mecoflorence.com Sting and Monitoring Overfill Prevention Equipment Operability Chec Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessment UST Internal Lining Inspections: Other:	k: <u>Yes</u> No <u>Yes</u> No Is): No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes
MECO, Inc. of Florence 316 Raymond Street Fayetteville, NC 28301 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	yes Yes No No No Yes Yes Yes No	Phone (910) 223-0018 Fax (910) 223-0022 Website www.mecoflorence.com Sting and Monitoring Overfill Prevention Equipment Operability Chec Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessment UST Internal Lining Inspections: Other:	k: Yes No Yes No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes
MECO, Inc. of Florence 316 Raymond Street Fayetteville, NC 28301 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release:	Yes Yes No No No Yes Yes No No No No No Yes Yes No No No No No No	Phone (910) 223-0018 Fax (910) 223-0022 Website www.mecoflorence.com Sting and Monitoring Overfill Prevention Equipment Operability Chec Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessment UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants:	k: Yes No Yes No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes
MECO, Inc. of Florence 316 Raymond Street Fayetteville, NC 28301 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes Yes No No No Yes Yes No No No No No Yes Yes No No No No No No	Phone (910) 223-0018 Fax (910) 223-0022 Website www.mecoflorence.com Sting and Monitoring Overfill Prevention Equipment Operability Chec Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessment UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants: UST Equipment Verification:	k: Yes No Yes No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes

		UST Service Provider List (Co	astal)		
Company		Listing Submitted		Area of state conducts work	
Mineral Springs Environmental		Phone (919) 266-8186		Coastal (East of I-95): Yes	
4600 Mineral Springs Lane		Fax		Central (West of I-95 and East of I-77): Yes	
Raleigh, NC 27616	14/	hoite		Mountains (West of I-77): Yes	
		ebsite			
Comp	oliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmenta	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:	_		
Soil and Water Testing Lab:	No				
Company		Listing Submitted	11/15/2018	Area of state conducts work	
National Tank Monitor, Inc.		Phone (800) 643-8265		Coastal (East of I-95): Yes	
P.O. Box 987				Central (West of I-95 and East of I-77): Yes	
Lonoke, AR 72086-		Fax (501) 764-4932			
	W	ebsite <u>www.nationaltankmonitor.com</u>		Mountains (West of I-77): Yes	
Comp	oliance Testi	ng and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	Yes	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	Yes	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	No
Er	nvironmenta	Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu		Waste Disposal and Treatment:	No		
		· · · · · · · · · · · · · · · · · · ·			
Oil and Solvent Recycling:	No	Other:			
Oil and Solvent Recycling: Soil and Water Testing Lab:	No No	Other:			

		UST Service Provider List (C	oastal)		
Company		Listing Submitte		Area of state conducts work	
NC PETROLEUM & CONVENIENCE MARKETE	RS	Phone (919) 782-4411		Coastal (East of I-95): Yes	
7300 GLENWOOD AVE.		Fax (919) 872-4414		Central (West of I-95 and East of I-77): Yes	
RALEIGH, NC 27612		,		Mountains (West of I-77): Yes	
	V	Vebsite <u>WWW.NCPCM.ORG</u>		mountaino (voot or 177). 100	
Com	oliance Tes	ting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
E	nvironment	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other: UST ENGIN	IEERING		
Soil and Water Testing Lab:	No				
Company		Listing Submitte	d 7/30/2020	Area of state conducts work	
Company Nova Group GBC		Phone (704) 258-5196	d 7/30/2020	Area of state conducts work Coastal (East of I-95): Yes	
		Phone (704) 258-5196	d 7/30/2020	Coastal (East of I-95): Yes	
Nova Group GBC 442 South Main St Suite # 7			d 7/30/2020	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Nova Group GBC 442 South Main St	V	Phone (704) 258-5196	d 7/30/2020	Coastal (East of I-95): Yes	
Nova Group GBC 442 South Main St Suite # 7 Davidson, NC 28036		Phone (704) 258-5196 Fax	d 7/30/2020	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Nova Group GBC 442 South Main St Suite # 7 Davidson, NC 28036		Phone (704) 258-5196 Fax Vebsite https://www.novagroupgbc.com/	7/30/2020 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Nova Group GBC 442 South Main St Suite # 7 Davidson, NC 28036 Com	pliance Tes	Phone (704) 258-5196 Fax Vebsite https://www.novagroupgbc.com/ ting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	
Nova Group GBC 442 South Main St Suite # 7 Davidson, NC 28036 Com Automatic Line Leak Detector Testing:	pliance Tes No	Phone (704) 258-5196 Fax Vebsite https://www.novagroupgbc.com/ ting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Nova Group GBC 442 South Main St Suite # 7 Davidson, NC 28036 Com Automatic Line Leak Detector Testing: Containment Sump Testing:	No No	Phone (704) 258-5196 Fax Vebsite https://www.novagroupgbc.com/ ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Nova Group GBC 442 South Main St Suite # 7 Davidson, NC 28036 Comparison Comparison Comparison Comparison Comparison Containment Sump Testing: Corrosion Protection Design Experts:	No No No No	Phone (704) 258-5196 Fax Vebsite https://www.novagroupgbc.com/ ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No No
Nova Group GBC 442 South Main St Suite # 7 Davidson, NC 28036 Comparison Comparison Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No No	Phone (704) 258-5196 Fax Vebsite https://www.novagroupgbc.com/ ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
Nova Group GBC 442 South Main St Suite # 7 Davidson, NC 28036 Comparison Comparison Comparison Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	Phone (704) 258-5196 Fax Vebsite https://www.novagroupgbc.com/ ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No
Nova Group GBC 442 South Main St Suite # 7 Davidson, NC 28036 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (704) 258-5196 Fax Vebsite https://www.novagroupgbc.com/ ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Nova Group GBC 442 South Main St Suite # 7 Davidson, NC 28036 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (704) 258-5196 Fax Vebsite https://www.novagroupgbc.com/ ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Nova Group GBC 442 South Main St Suite # 7 Davidson, NC 28036 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (704) 258-5196 Fax Vebsite https://www.novagroupgbc.com/ ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Environmental compliance in	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Nova Group GBC 442 South Main St Suite # 7 Davidson, NC 28036 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (704) 258-5196 Fax Vebsite https://www.novagroupgbc.com/ ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Environmental compliance in	No No No No No No spections	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Nova Group GBC 442 South Main St Suite # 7 Davidson, NC 28036 Com Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	No N	Phone (704) 258-5196 Fax Vebsite https://www.novagroupgbc.com/ ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Environmental compliance in	No No No No No Spections	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Nova Group GBC 442 South Main St Suite # 7 Davidson, NC 28036 Comparison Protection Design Experts: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (704) 258-5196 Fax Vebsite https://www.novagroupgbc.com/ ting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Environmental compliance in al Service Firms UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No No No No No Spections Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

		UST Service Provider List (Co	astal)		
Company		Listing Submitted		Area of state conducts work	
Petroleum Equipment and Service, Inc.		Phone (704) 335-8801		Coastal (East of I-95): Yes	
4125 Sinclair Street		Fax (704) 342-1672		Central (West of I-95 and East of I-77): Yes	
PO Box 1949 Denver, NC 28037				Mountains (West of I-77): Yes	
Deriver, NO 20037	١	Website www.petroleumequipment.net		,	
Comp	oliance Tes	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
E	nvironment	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
The state of the s					
Company		Listing Submitted	11/14/2018	Area of state conducts work	
Company Petroleum Equipment Service of Wilson, Inc.		Listing Submitted Phone (252) 237-6047	11/14/2018	Area of state conducts work Coastal (East of I-95): Yes	
Petroleum Equipment Service of Wilson, Inc. P.O. Box 502		Phone (252) 237-6047	11/14/2018	Coastal (East of I-95): Yes	
Petroleum Equipment Service of Wilson, Inc. P.O. Box 502 711 S. Goldsboro St.		Phone (252) 237-6047	11/14/2018	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Petroleum Equipment Service of Wilson, Inc. P.O. Box 502	\	Phone (252) 237-6047	11/14/2018	Coastal (East of I-95): Yes	
Petroleum Equipment Service of Wilson, Inc. P.O. Box 502 711 S. Goldsboro St. Wilson, NC 27894		Phone (252) 237-6047 Fax (252) 237-5507	11/14/2018	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Petroleum Equipment Service of Wilson, Inc. P.O. Box 502 711 S. Goldsboro St. Wilson, NC 27894		Phone (252) 237-6047 Fax (252) 237-5507 Website www.peswilson.com	11/14/2018 Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	Yes
Petroleum Equipment Service of Wilson, Inc. P.O. Box 502 711 S. Goldsboro St. Wilson, NC 27894 Comp	oliance Tes	Phone (252) 237-6047 Fax (252) 237-5507 Website www.peswilson.com Sting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors	Yes Yes
Petroleum Equipment Service of Wilson, Inc. P.O. Box 502 711 S. Goldsboro St. Wilson, NC 27894 Comparison Com	oliance Tes No	Phone (252) 237-6047 Fax (252) 237-5507 Website www.peswilson.com Sting and Monitoring Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Petroleum Equipment Service of Wilson, Inc. P.O. Box 502 711 S. Goldsboro St. Wilson, NC 27894 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	No Yes	Phone (252) 237-6047 Fax (252) 237-5507 Website www.peswilson.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Petroleum Equipment Service of Wilson, Inc. P.O. Box 502 711 S. Goldsboro St. Wilson, NC 27894 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No Yes No	Phone (252) 237-6047 Fax (252) 237-5507 Website www.peswilson.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	Yes No Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	<u>Yes</u> <u>Yes</u>
Petroleum Equipment Service of Wilson, Inc. P.O. Box 502 711 S. Goldsboro St. Wilson, NC 27894 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No Yes No No	Phone (252) 237-6047 Fax (252) 237-5507 Website www.peswilson.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	Yes No Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	Yes Yes Yes Yes Yes
Petroleum Equipment Service of Wilson, Inc. P.O. Box 502 711 S. Goldsboro St. Wilson, NC 27894 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No Yes No No No	Phone (252) 237-6047 Fax (252) 237-5507 Website www.peswilson.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	Yes No Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	Yes Yes Yes Yes
Petroleum Equipment Service of Wilson, Inc. P.O. Box 502 711 S. Goldsboro St. Wilson, NC 27894 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No Yes No No No No No No Yes	Phone (252) 237-6047 Fax (252) 237-5507 Website www.peswilson.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes
Petroleum Equipment Service of Wilson, Inc. P.O. Box 502 711 S. Goldsboro St. Wilson, NC 27894 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Yes No	Phone (252) 237-6047 Fax (252) 237-5507 Website www.peswilson.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	Yes No Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes Yes Yes Yes Yes Yes Yes Yes
Petroleum Equipment Service of Wilson, Inc. P.O. Box 502 711 S. Goldsboro St. Wilson, NC 27894 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	No Yes No	Phone (252) 237-6047 Fax (252) 237-5507 Website www.peswilson.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes No Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes Yes
Petroleum Equipment Service of Wilson, Inc. P.O. Box 502 711 S. Goldsboro St. Wilson, NC 27894 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Yes No	Phone (252) 237-6047 Fax (252) 237-5507 Website www.peswilson.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	Yes No Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes Yes
Petroleum Equipment Service of Wilson, Inc. P.O. Box 502 711 S. Goldsboro St. Wilson, NC 27894 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release:	No Yes No	Phone (252) 237-6047 Fax (252) 237-5507 Website www.peswilson.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Stal Service Firms UST Compliance Consultants:	Yes No Yes No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes Yes
Petroleum Equipment Service of Wilson, Inc. P.O. Box 502 711 S. Goldsboro St. Wilson, NC 27894 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No Yes No	Phone (252) 237-6047 Fax (252) 237-5507 Website www.peswilson.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification:	Yes No Yes No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes Yes Yes Yes Yes Yes Yes Yes

		UST	Service Provider List (Co	astal)		
Company			Listing Submitted	8/18/2020	Area of state conducts work	
Petroleum Service & Calibration, Inc.		Phone	(704) 489-1671		Coastal (East of I-95): Yes	
7973 Vista View Drive		Fax	(704) 489-1672		Central (West of I-95 and East of I-77): Yes	
Sherrills Ford, NC 28673			, ,		Mountains (West of I-77): No	
	V	Vebsite	www.petroleumtanktesting.com		mountaine (rest et 177). He	
Comp	oliance Tes	ting and	Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	Yes	Overfill	Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	Yes
Containment Sump Testing:	<u>Yes</u>	Statistic	cal Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Pre	evention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Ti	ghtness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Int	ternal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Int	ternal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>				UST System Removal:	No
Er	nvironment	al Servic	ce Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Co	ompliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No		quipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No		Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					
Company			Listing Submitted	5/14/2021	Area of state conducts work	
Company Petroleum Solutions Inc.		Phone	Listing Submitted (919) 605-1979	5/14/2021	Area of state conducts work Coastal (East of I-95): Yes	
			(919) 605-1979	5/14/2021	Coastal (East of I-95): Yes	
Petroleum Solutions Inc. 3012 Whitehart Ln. 819 Purser Drive		Phone Fax	(919) 605-1979	5/14/2021	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Petroleum Solutions Inc. 3012 Whitehart Ln.	V		(919) 605-1979	5/14/2021	Coastal (East of I-95): Yes	
Petroleum Solutions Inc. 3012 Whitehart Ln. 819 Purser Drive Raleigh, NC 27606		Fax Vebsite	(919) 605-1979 (919) 773-1704	5/14/2021	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Petroleum Solutions Inc. 3012 Whitehart Ln. 819 Purser Drive Raleigh, NC 27606		Fax Vebsite ting and	(919) 605-1979 (919) 773-1704 www.petroleumsolutionsinc.net	5/14/2021 Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	No
Petroleum Solutions Inc. 3012 Whitehart Ln. 819 Purser Drive Raleigh, NC 27606	oliance Tes	Fax Vebsite ting and Overfill	(919) 605-1979 (919) 773-1704 www.petroleumsolutionsinc.net		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors	No No
Petroleum Solutions Inc. 3012 Whitehart Ln. 819 Purser Drive Raleigh, NC 27606 Comp	oliance Tes No	Fax Vebsite ting and Overfill Statistic	(919) 605-1979 (919) 773-1704 www.petroleumsolutionsinc.net Monitoring Prevention Equipment Operability Check:	<u>Yes</u>	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Petroleum Solutions Inc. 3012 Whitehart Ln. 819 Purser Drive Raleigh, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	No Yes	Fax Vebsite ting and Overfill Statistic Spill Pre	(919) 605-1979 (919) 773-1704 www.petroleumsolutionsinc.net Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services:	Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Petroleum Solutions Inc. 3012 Whitehart Ln. 819 Purser Drive Raleigh, NC 27606 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No Yes No	Fax Vebsite ting and Overfill Statistic Spill Pre Tank Ti	(919) 605-1979 (919) 773-1704 www.petroleumsolutionsinc.net Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing:	Yes No Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No <u>Yes</u>
Petroleum Solutions Inc. 3012 Whitehart Ln. 819 Purser Drive Raleigh, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No Yes No No	Fax Vebsite ting and Overfill Statistic Spill Pre Tank Tic UST Int	(919) 605-1979 (919) 773-1704 www.petroleumsolutionsinc.net Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing:	Yes No Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No <u>Yes</u> <u>Yes</u>
Petroleum Solutions Inc. 3012 Whitehart Ln. 819 Purser Drive Raleigh, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No Yes No No No	Fax Vebsite ting and Overfill Statistic Spill Pre Tank Tic UST Int	(919) 605-1979 (919) 773-1704 www.petroleumsolutionsinc.net Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing: ternal Inspections (Integrity Assessments):	Yes No Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No Yes Yes Yes Yes Yes Yes
Petroleum Solutions Inc. 3012 Whitehart Ln. 819 Purser Drive Raleigh, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No Yes No No No No No No	Fax Vebsite ting and Overfill Statistic Spill Pre Tank Tie UST Int UST Int	(919) 605-1979 (919) 773-1704 www.petroleumsolutionsinc.net Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing: ternal Inspections (Integrity Assessments):	Yes No Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes Yes Yes Yes
Petroleum Solutions Inc. 3012 Whitehart Ln. 819 Purser Drive Raleigh, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Yes No No No No No No No No No	Fax Vebsite ting and Overfill Statistic Spill Pre Tank Tir UST Int UST Int Other:	(919) 605-1979 (919) 773-1704 www.petroleumsolutionsinc.net Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing: ternal Inspections (Integrity Assessments): ternal Lining Inspections:	Yes No Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No Yes Yes Yes Yes Yes Yes
Petroleum Solutions Inc. 3012 Whitehart Ln. 819 Purser Drive Raleigh, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Yes No	Fax Vebsite ting and Overfill Statistic Spill Pre Tank Ti UST Int UST Int Other:	(919) 605-1979 (919) 773-1704 www.petroleumsolutionsinc.net Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing: ternal Inspections (Integrity Assessments): ternal Lining Inspections:	Yes No Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes Yes Yes Yes Yes Yes
Petroleum Solutions Inc. 3012 Whitehart Ln. 819 Purser Drive Raleigh, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No Yes No	Vebsite ting and Overfill Statistic Spill Pre Tank Ti UST Int UST Int Other:	(919) 605-1979 (919) 773-1704 www.petroleumsolutionsinc.net Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing: ternal Inspections (Integrity Assessments): ternal Lining Inspections:	Yes No Yes No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes Yes Yes Yes Yes Yes
Petroleum Solutions Inc. 3012 Whitehart Ln. 819 Purser Drive Raleigh, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release:	No Yes No	Vebsite ting and Overfill Statistic Spill Pre Tank Ti UST Int UST Int Other: al Servic UST Co UST Eq	(919) 605-1979 (919) 773-1704 www.petroleumsolutionsinc.net Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing: ternal Inspections (Integrity Assessments): ternal Lining Inspections:	Yes No Yes No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes Yes Yes Yes Yes Yes
Petroleum Solutions Inc. 3012 Whitehart Ln. 819 Purser Drive Raleigh, NC 27606 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No Yes No	Vebsite ting and Overfill Statistic Spill Pre Tank Ti UST Int UST Int Other: al Servic UST Co UST Eq	(919) 605-1979 (919) 773-1704 www.petroleumsolutionsinc.net Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ightness Testing: ternal Inspections (Integrity Assessments): ternal Lining Inspections: ce Firms ompliance Consultants: quipment Verification:	Yes No Yes No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No Yes Yes Yes Yes Yes Yes

		UST Service Provider List	t (Coastal)		
Company		Listing Sub	mitted 5/22/2019	Area of state conducts work	
Petroleum Tec		Phone (704) 804-1213		Coastal (East of I-95): Y	'es
5420 Powerhouse Ct		Fax		Central (West of I-95 and East of I-77): Y	'es
Concord, NC 28027				Mountains (West of I-77): Y	'es
	W	/ebsite www.petroleumtec.com		,	
Сотр	liance Test	ing and Monitoring		UST Equipmment Service Contractor	rs
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Chec	k: No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessment	ts): No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:	Tank Cleaning	UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironmenta	al Service Firms		Other: Tai	nk Cleaning
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:	Tank Cleaning		
Soil and Water Testing Lab:	No				
Company		Listing Sub	mitted 11/14/2018	Area of state conducts work	
Company PGP Services, LLC		Listing Sub Phone (704) 619-1528	mitted 11/14/2018	Area of state conducts work Coastal (East of I-95): Y	'es
		Phone (704) 619-1528	mitted 11/14/2018	Coastal (East of I-95): Y	
PGP Services, LLC			mitted 11/14/2018	Coastal (East of I-95): Y Central (West of I-95 and East of I-77): Y	'es
PGP Services, LLC 1949 Candlewick Drive	W	Phone (704) 619-1528	mitted 11/14/2018	Coastal (East of I-95): Y	'es
PGP Services, LLC 1949 Candlewick Drive Fort Mill, SC 29715		Phone (704) 619-1528 Fax (803) 802-2441	mitted 11/14/2018	Coastal (East of I-95): Y Central (West of I-95 and East of I-77): Y	'es 'es
PGP Services, LLC 1949 Candlewick Drive Fort Mill, SC 29715		Phone (704) 619-1528 Fax (803) 802-2441 /ebsite		Coastal (East of I-95): Y Central (West of I-95 and East of I-77): Y Mountains (West of I-77): Y	'es 'es
PGP Services, LLC 1949 Candlewick Drive Fort Mill, SC 29715 Comp	oliance Test	Phone (704) 619-1528 Fax (803) 802-2441 /ebsite ing and Monitoring		Coastal (East of I-95): Y Central (West of I-95 and East of I-77): Y Mountains (West of I-77): Y UST Equipmment Service Contractor	'es 'es rs
PGP Services, LLC 1949 Candlewick Drive Fort Mill, SC 29715 Comp	oliance Test Yes	Phone (704) 619-1528 Fax (803) 802-2441 /ebsite ing and Monitoring Overfill Prevention Equipment Operability Chec	.k: <u>Yes</u>	Coastal (East of I-95): Y Central (West of I-95 and East of I-77): Y Mountains (West of I-77): Y UST Equipmment Service Contractor Dispenser Meter Repair/Calibration:	rs No
PGP Services, LLC 1949 Candlewick Drive Fort Mill, SC 29715 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	oliance Test Yes Yes	Phone (704) 619-1528 Fax (803) 802-2441 /ebsite ing and Monitoring Overfill Prevention Equipment Operability Chec Statistical Iventory Reconciliation Services:	·k: <u>Yes</u> No	Coastal (East of I-95): Y Central (West of I-95 and East of I-77): Y Mountains (West of I-77): Y UST Equipmment Service Contractor Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	rs No
PGP Services, LLC 1949 Candlewick Drive Fort Mill, SC 29715 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	oliance Test Yes Yes Yes	Phone (704) 619-1528 Fax (803) 802-2441 /ebsite ing and Monitoring Overfill Prevention Equipment Operability Chec Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	k: <u>Yes</u> No <u>Yes</u> No	Coastal (East of I-95): Y Central (West of I-95 and East of I-77): Y Mountains (West of I-77): Y UST Equipmment Service Contractor Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	rs No No Yes
PGP Services, LLC 1949 Candlewick Drive Fort Mill, SC 29715 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Ves Yes Yes Yes Yes	Phone (704) 619-1528 Fax (803) 802-2441 /ebsite ing and Monitoring Overfill Prevention Equipment Operability Chec Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	k: <u>Yes</u> No <u>Yes</u> No	Coastal (East of I-95): Y Central (West of I-95 and East of I-77): Y Mountains (West of I-77): Y UST Equipmment Service Contractor Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	rs No No Yes Yes
PGP Services, LLC 1949 Candlewick Drive Fort Mill, SC 29715 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	Yes Yes Yes Yes Yes Yes Yes Yes	Phone (704) 619-1528 Fax (803) 802-2441 /ebsite ing and Monitoring Overfill Prevention Equipment Operability Chec Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessment	k: <u>Yes</u> No <u>Yes</u> No No	Coastal (East of I-95): Y Central (West of I-95 and East of I-77): Y Mountains (West of I-77): Y UST Equipmment Service Contractor Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	res No No Yes Yes No
PGP Services, LLC 1949 Candlewick Drive Fort Mill, SC 29715 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Yes	Phone (704) 619-1528 Fax (803) 802-2441 /ebsite ing and Monitoring Overfill Prevention Equipment Operability Chec Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessment UST Internal Lining Inspections:	k: <u>Yes</u> No <u>Yes</u> No No	Coastal (East of I-95): Y Central (West of I-95 and East of I-77): Y Mountains (West of I-77): Y UST Equipmment Service Contractor Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	rs No No Yes Yes No No No
PGP Services, LLC 1949 Candlewick Drive Fort Mill, SC 29715 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes	Phone (704) 619-1528 Fax (803) 802-2441 /ebsite ing and Monitoring Overfill Prevention Equipment Operability Chec Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessment UST Internal Lining Inspections:	k: <u>Yes</u> No <u>Yes</u> No No	Coastal (East of I-95): Y Central (West of I-95 and East of I-77): Y Mountains (West of I-77): Y UST Equipmment Service Contractor Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	rs No No Yes Yes No No No No No
PGP Services, LLC 1949 Candlewick Drive Fort Mill, SC 29715 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes	Phone (704) 619-1528 Fax (803) 802-2441 /ebsite ing and Monitoring Overfill Prevention Equipment Operability Chec Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessment UST Internal Lining Inspections: Other:	k: <u>Yes</u> No <u>Yes</u> No No	Coastal (East of I-95): Y Central (West of I-95 and East of I-77): Y Mountains (West of I-77): Y UST Equipmment Service Contractor Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	rs No No Yes Yes No No No No No
PGP Services, LLC 1949 Candlewick Drive Fort Mill, SC 29715 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Yes Yes Yes Yes Yes Yes Yes Yes No Yes	Phone (704) 619-1528 Fax (803) 802-2441 /ebsite ing and Monitoring Overfill Prevention Equipment Operability Chec Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessment UST Internal Lining Inspections: Other:	k: Yes No Yes No No No	Coastal (East of I-95): Y Central (West of I-95 and East of I-77): Y Mountains (West of I-77): Y UST Equipmment Service Contractor Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	rs No No Yes Yes No No No No No
PGP Services, LLC 1949 Candlewick Drive Fort Mill, SC 29715 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	Yes Yes Yes Yes Yes Yes Yes Yes No Yes Ovironmenta	Phone (704) 619-1528 Fax (803) 802-2441 /ebsite ing and Monitoring Overfill Prevention Equipment Operability Chec Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessment UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants:	k: Yes No Yes No No No Yes	Coastal (East of I-95): Y Central (West of I-95 and East of I-77): Y Mountains (West of I-77): Y UST Equipmment Service Contractor Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	rs No No Yes Yes No No No No No
PGP Services, LLC 1949 Candlewick Drive Fort Mill, SC 29715 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Yes Yes Yes Yes Yes Yes Yes Yes No Yes Ovironmenta	Phone (704) 619-1528 Fax (803) 802-2441 /ebsite ing and Monitoring Overfill Prevention Equipment Operability Chec Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessment UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants: UST Equipment Verification:	k: Yes No Yes No No Yes Yes Yes	Coastal (East of I-95): Y Central (West of I-95 and East of I-77): Y Mountains (West of I-77): Y UST Equipmment Service Contractor Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	rs No No Yes Yes No No No No No

		UST Service Provider List (Co	astal)		
Company		Listing Submitted	7/30/2020	Area of state conducts work	
Pilot Geological, PLLC		Phone (336) 310-4527		Coastal (East of I-95): Yes	
743 Park Lawn Court		Fax (336) 310-4527		Central (West of I-95 and East of I-77): Yes	
PO 128 Kernersville, NC 27285		,		Mountains (West of I-77): Yes	
Remeisville, NC 27200	'	Website <u>www.pilotenviro.com</u>			
Comp	oliance Tes	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
E	nvironmen	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	11/8/2019	Area of state conducts work	
		Listing Submitted Phone (910) 790-8265	11/8/2019	Area of state conducts work Coastal (East of I-95): Yes	
Company Practical Environmental Solutions, PC 5634 Harvest Grove Lane		Phone (910) 790-8265	11/8/2019	Coastal (East of I-95): Yes	
Company Practical Environmental Solutions, PC			11/8/2019	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Company Practical Environmental Solutions, PC 5634 Harvest Grove Lane		Phone (910) 790-8265	11/8/2019	Coastal (East of I-95): Yes	
Company Practical Environmental Solutions, PC 5634 Harvest Grove Lane Wilmington, NC 28409	,	Phone (910) 790-8265 Fax	11/8/2019	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Company Practical Environmental Solutions, PC 5634 Harvest Grove Lane Wilmington, NC 28409	,	Phone (910) 790-8265 Fax Website www.oil-tank.com	11/8/2019 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No	No
Company Practical Environmental Solutions, PC 5634 Harvest Grove Lane Wilmington, NC 28409 Company	bliance Tes	Phone (910) 790-8265 Fax Website www.oil-tank.com sting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors	No No
Company Practical Environmental Solutions, PC 5634 Harvest Grove Lane Wilmington, NC 28409 Company Automatic Line Leak Detector Testing:	oliance Tes	Phone (910) 790-8265 Fax Website www.oil-tank.com Sting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
Company Practical Environmental Solutions, PC 5634 Harvest Grove Lane Wilmington, NC 28409 Company Automatic Line Leak Detector Testing: Containment Sump Testing:	pliance Tes No No	Phone (910) 790-8265 Fax Website www.oil-tank.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Company Practical Environmental Solutions, PC 5634 Harvest Grove Lane Wilmington, NC 28409 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No No	Phone (910) 790-8265 Fax Website www.oil-tank.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Company Practical Environmental Solutions, PC 5634 Harvest Grove Lane Wilmington, NC 28409 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	Diiance Tes No No No No	Phone (910) 790-8265 Fax Website www.oil-tank.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Company Practical Environmental Solutions, PC 5634 Harvest Grove Lane Wilmington, NC 28409 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	Phone (910) 790-8265 Fax Website www.oil-tank.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No
Company Practical Environmental Solutions, PC 5634 Harvest Grove Lane Wilmington, NC 28409 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No No	Phone (910) 790-8265 Fax Website www.oil-tank.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Company Practical Environmental Solutions, PC 5634 Harvest Grove Lane Wilmington, NC 28409 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (910) 790-8265 Fax Website www.oil-tank.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Company Practical Environmental Solutions, PC 5634 Harvest Grove Lane Wilmington, NC 28409 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (910) 790-8265 Fax Website www.oil-tank.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Company Practical Environmental Solutions, PC 5634 Harvest Grove Lane Wilmington, NC 28409 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (910) 790-8265 Fax Website www.oil-tank.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Company Practical Environmental Solutions, PC 5634 Harvest Grove Lane Wilmington, NC 28409 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Entergency Cleanup - Spill/Release:	No Yes Yes	Phone (910) 790-8265 Fax Website www.oil-tank.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Company Practical Environmental Solutions, PC 5634 Harvest Grove Lane Wilmington, NC 28409 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No Yes Yes	Phone (910) 790-8265 Fax Website www.oil-tank.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Pro	vider List (Co	astal)		
Company			Listing Submitted	8/10/2021	Area of state conducts work	
Precision Tank Service		Phone (704) 892-8600			Coastal (East of I-95): Yes	
737 Zimmer Road		Fax (704) 892-8711			Central (West of I-95 and East of I-77): Yes	
Fort Mill, SC 29707					Mountains (West of I-77): Yes	
	W	ebsite www.precisiontanks	service.com		,	
Comp	pliance Test	ing and Monitoring			UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment (Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation		No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Tes	sting:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:		<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integ		No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections	ii .	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:	Monthly UST27 Insp	pection	UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>				UST System Removal:	No
E	nvironmenta	I Service Firms			Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:		<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:		No		
Environmental Engineer/Geologist Soil and GW Cleanu	ı No	Waste Disposal and Treatment	:	No		
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					
Company			Listing Submitted	11/29/2018	Area of state conducts work	
-		Phone (704) 892-8600	Listing Submitted	11/29/2018	Area of state conducts work Coastal (East of I-95): Yes	
Company Precision Tank Service P.O. Box 2040		Phone (704) 892-8600 Fax (704) 892-8711	Listing Submitted	11/29/2018		
Company Precision Tank Service P.O. Box 2040 20468 Chartwell Center Dr		•	Listing Submitted	11/29/2018	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Company Precision Tank Service P.O. Box 2040		•		11/29/2018	Coastal (East of I-95): Yes	
Company Precision Tank Service P.O. Box 2040 20468 Chartwell Center Dr Cornelius, NC 28031	W	Fax (704) 892-8711		11/29/2018	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Company Precision Tank Service P.O. Box 2040 20468 Chartwell Center Dr Cornelius, NC 28031	W	Fax (704) 892-8711 ebsite precisiontankservice	e.com	11/29/2018 Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Company Precision Tank Service P.O. Box 2040 20468 Chartwell Center Dr Cornelius, NC 28031 Comp	W pliance Test	Fax (704) 892-8711 ebsite precisiontankservice ing and Monitoring	e.com Derability Check:		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	
Company Precision Tank Service P.O. Box 2040 20468 Chartwell Center Dr Cornelius, NC 28031 Company Automatic Line Leak Detector Testing:	W pliance Test Yes	Fax (704) 892-8711 Sebsite precisiontankservice sing and Monitoring Overfill Prevention Equipment (e.com Depart of the company of the	Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	<u>Yes</u>
Company Precision Tank Service P.O. Box 2040 20468 Chartwell Center Dr Cornelius, NC 28031 Company Automatic Line Leak Detector Testing: Containment Sump Testing:	W pliance Test Yes Yes	Fax (704) 892-8711 Pebsite precisiontankservice Ing and Monitoring Overfill Prevention Equipment Content Statistical Iventory Reconciliation	e.com Depart of the company of the	Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	Yes No
Company Precision Tank Service P.O. Box 2040 20468 Chartwell Center Dr Cornelius, NC 28031 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	W pliance Test Yes Yes No	Fax (704) 892-8711 Lebsite precisiontankservice Ling and Monitoring Overfill Prevention Equipment Control Statistical Iventory Reconciliation Spill Prevention Equipment Test Tank Tightness Testing: UST Internal Inspections (Integ	e.com Operability Check: on Services: sting: rity Assessments):	Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	Yes No No
Company Precision Tank Service P.O. Box 2040 20468 Chartwell Center Dr Cornelius, NC 28031 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Wind post of the p	Fax (704) 892-8711 Lebsite precisiontankservice Ling and Monitoring Overfill Prevention Equipment (Statistical Iventory Reconciliation Spill Prevention Equipment Test Tank Tightness Testing: UST Internal Inspections (Integ UST Internal Lining Inspections)	e.com Operability Check: on Services: sting: rity Assessments):	Yes Yes Yes Yes	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	Yes No No No No
Company Precision Tank Service P.O. Box 2040 20468 Chartwell Center Dr Cornelius, NC 28031 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	Wind pliance Test Yes Yes No No No Yes	Fax (704) 892-8711 Lebsite precisiontankservice Ling and Monitoring Overfill Prevention Equipment Control Statistical Iventory Reconciliation Spill Prevention Equipment Test Tank Tightness Testing: UST Internal Inspections (Integ	e.com Operability Check: on Services: sting: rity Assessments):	Yes Yes Yes Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes No No No No
Company Precision Tank Service P.O. Box 2040 20468 Chartwell Center Dr Cornelius, NC 28031 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	Wind post of the p	Fax (704) 892-8711 Lebsite precisiontankservice Ling and Monitoring Overfill Prevention Equipment (Statistical Iventory Reconciliation Spill Prevention Equipment Test Tank Tightness Testing: UST Internal Inspections (Integ UST Internal Lining Inspections)	e.com Operability Check: on Services: sting: rity Assessments):	Yes Yes Yes Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes No No No No No
Company Precision Tank Service P.O. Box 2040 20468 Chartwell Center Dr Cornelius, NC 28031 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Windows Pliance Test Yes Yes No No Yes Yes Yes Yes Yes Yes Yes	Fax (704) 892-8711 Lebsite precisiontankservice Ling and Monitoring Overfill Prevention Equipment (Statistical Iventory Reconciliation Spill Prevention Equipment Test Tank Tightness Testing: UST Internal Inspections (Integ UST Internal Lining Inspections)	e.com Operability Check: on Services: sting: rity Assessments):	Yes Yes Yes Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	Yes No No No No No
Company Precision Tank Service P.O. Box 2040 20468 Chartwell Center Dr Cornelius, NC 28031 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Windows Pliance Test Yes Yes No No Yes Yes Yes Yes Yes Yes Yes	Fax (704) 892-8711 Lebsite precisiontankservice Ling and Monitoring Overfill Prevention Equipment Control Statistical Iventory Reconciliation Spill Prevention Equipment Test Tank Tightness Testing: UST Internal Inspections (Integ UST Internal Lining Inspections Other:	e.com Operability Check: on Services: sting: rity Assessments):	Yes Yes Yes Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes No No No No No
Company Precision Tank Service P.O. Box 2040 20468 Chartwell Center Dr Cornelius, NC 28031 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Pliance Test Yes Yes No No Yes Yes Yes Yes Yes Yes Yes Yes	Fax (704) 892-8711 Lebsite precisiontankservice Ling and Monitoring Overfill Prevention Equipment Control Statistical Iventory Reconciliation Spill Prevention Equipment Test Tank Tightness Testing: UST Internal Inspections (Integ UST Internal Lining Inspections Other:	e.com Operability Check: on Services: sting: rity Assessments):	Yes Yes Yes Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes No No No No No
Company Precision Tank Service P.O. Box 2040 20468 Chartwell Center Dr Cornelius, NC 28031 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	Ves Yes No No Yes Yes Yes Yes Yes Yes Yes Yes No No No No No No No	Fax (704) 892-8711 Tebsite precisiontankservice Ting and Monitoring Overfill Prevention Equipment O Statistical Iventory Reconciliation Spill Prevention Equipment Test Tank Tightness Testing: UST Internal Inspections (Integ UST Internal Lining Inspections Other: UST Compliance Consultants:	e.com Operability Check: on Services: sting: rity Assessments):	Yes Yes Yes Yes No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes No No No No No
Company Precision Tank Service P.O. Box 2040 20468 Chartwell Center Dr Cornelius, NC 28031 Company Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	Ves Yes No No Yes Yes Yes Yes Yes Yes Yes Yes No No No No No No No	Fax (704) 892-8711 Tebsite precisiontankservice Ting and Monitoring Overfill Prevention Equipment of Statistical Iventory Reconciliation Spill Prevention Equipment Test Tank Tightness Testing: UST Internal Inspections (Integ UST Internal Lining Inspections Other: UST Compliance Consultants: UST Equipment Verification:	e.com Operability Check: on Services: sting: rity Assessments):	Yes Yes Yes No No Yes No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	Yes No No No No No

		UST Service Provider List (Co	pastal)		
Company		Listing Submitted		Area of state conducts work	
Professional Service Industries, Inc.		Phone (704) 598-2234		Coastal (East of I-95): Yes	
5021 W W.T. Harris Blvd.		Fax (704) 598-2236		Central (West of I-95 and East of I-77): Yes	
Charlotte, NC 28269	14/			Mountains (West of I-77): Yes	
	VV	/ebsite http://www.intertek.com/building			
Comp	oliance Testi	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
En	nvironmenta	I Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	11/15/2018	Area of state conducts work	
Progress Environmental Group, Inc.		Phone (336) 722-9999		Coastal (East of I-95): Yes	
120 Fayette Street Winston-Salem, NC 27101		Fax (336) 722-9998		Central (West of I-95 and East of I-77): Yes	
, , ,	W	ebsite www.progressenvironmental.com		Mountains (West of I-77): Yes	
Comp					
Automatic Line Leak Detector Testing:	oliance Testi	ing and Monitoring		UST Equipmment Service Contractors	
	pliance Testi No	ing and Monitoring	No		No
Containment Sump Testing:			No No	UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Containment Sump Testing: Corrosion Protection Design Experts:	No	ing and Monitoring Overfill Prevention Equipment Operability Check:		Dispenser Meter Repair/Calibration:	
	No No	ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No No No	ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No	ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No	ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No	overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En	No N	ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Il Service Firms UST Compliance Consultants:	No No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification:	No No No No No	Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List (Co	oastal)		
Company		Listing Submitted	11/15/2018	Area of state conducts work	
Protective Technologies, Inc.		Phone (803) 424-0412		Coastal (East of I-95): Yes	
711 Mill Street		Fax (803) 424-0414		Central (West of I-95 and East of I-77): Yes	i
Camden, SC 29020				Mountains (West of I-77): Yes	
		Website www.protectivetechnologiesinc.com		, , , , , , , , , , , , , , , , , , , ,	
Comp	oliance Tes	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironmen	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	11/14/2018	Area of state conducts work	
Company Pyramid Environmental & Engineering PC		Phone (336) 335-3174	11/14/2018	Area of state conducts work Coastal (East of I-95): Yes	
Pyramid Environmental & Engineering PC 503 Industrial Ave			11/14/2018		
Pyramid Environmental & Engineering PC	,	Phone (336) 335-3174	11/14/2018	Coastal (East of I-95): Yes	
Pyramid Environmental & Engineering PC 503 Industrial Ave Greensboro, NC 27406		Phone (336) 335-3174 Fax (336) 691-0648	11/14/2018	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Pyramid Environmental & Engineering PC 503 Industrial Ave Greensboro, NC 27406		Phone (336) 335-3174 Fax (336) 691-0648 Website www.pyramidenvironmental.com	11/14/2018 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Pyramid Environmental & Engineering PC 503 Industrial Ave Greensboro, NC 27406 Comp	oliance Tes	Phone (336) 335-3174 Fax (336) 691-0648 Website www.pyramidenvironmental.com sting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	
Pyramid Environmental & Engineering PC 503 Industrial Ave Greensboro, NC 27406 Comp Automatic Line Leak Detector Testing:	oliance Tes No	Phone (336) 335-3174 Fax (336) 691-0648 Website www.pyramidenvironmental.com Sting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	No
Pyramid Environmental & Engineering PC 503 Industrial Ave Greensboro, NC 27406 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	No No	Phone (336) 335-3174 Fax (336) 691-0648 Website www.pyramidenvironmental.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Pyramid Environmental & Engineering PC 503 Industrial Ave Greensboro, NC 27406 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No No	Phone (336) 335-3174 Fax (336) 691-0648 Website www.pyramidenvironmental.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No No
Pyramid Environmental & Engineering PC 503 Industrial Ave Greensboro, NC 27406 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No No	Phone (336) 335-3174 Fax (336) 691-0648 Website www.pyramidenvironmental.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Pyramid Environmental & Engineering PC 503 Industrial Ave Greensboro, NC 27406 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	Phone (336) 335-3174 Fax (336) 691-0648 Website www.pyramidenvironmental.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Pyramid Environmental & Engineering PC 503 Industrial Ave Greensboro, NC 27406 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (336) 335-3174 Fax (336) 691-0648 Website www.pyramidenvironmental.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Pyramid Environmental & Engineering PC 503 Industrial Ave Greensboro, NC 27406 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (336) 335-3174 Fax (336) 691-0648 Website www.pyramidenvironmental.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
Pyramid Environmental & Engineering PC 503 Industrial Ave Greensboro, NC 27406 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (336) 335-3174 Fax (336) 691-0648 Website www.pyramidenvironmental.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Pyramid Environmental & Engineering PC 503 Industrial Ave Greensboro, NC 27406 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No Vo No Tvironmen Yes Yes	Phone (336) 335-3174 Fax (336) 691-0648 Website www.pyramidenvironmental.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Pyramid Environmental & Engineering PC 503 Industrial Ave Greensboro, NC 27406 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No Vo No Tvironmen Yes Yes	Phone (336) 335-3174 Fax (336) 691-0648 Website www.pyramidenvironmental.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
Pyramid Environmental & Engineering PC 503 Industrial Ave Greensboro, NC 27406 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (336) 335-3174 Fax (336) 691-0648 Website www.pyramidenvironmental.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

	UST Service Provider List (Co	astal)		
	Listing Submitted	11/15/2018	Area of state conducts work	
	Phone (252) 809-3608		Coastal (East of I-95): Yes	
	Fax		Central (West of I-95 and East of I-77): Yes	
W	ebsite		Mountains (West of 1-77). No	
iance Test	ing and Monitoring		UST Equipmment Service Contractors	
No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
No	Other:		UST Piping/Sump Installation:	No
No			UST System Removal:	<u>Yes</u>
vironmenta	Il Service Firms		Other:	
Yes	UST Compliance Consultants:	No		
No	UST Equipment Verification:	No		
No	Waste Disposal and Treatment:	<u>Yes</u>		
No	Other:			
No				
No				
INO	Listing Submitted	9/14/2020	Area of state conducts work	
		9/14/2020		
	Phone (910) 769-1621	9/14/2020	Coastal (East of I-95): Yes	
		9/14/2020	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
	Phone (910) 769-1621	9/14/2020	Coastal (East of I-95): Yes	
w	Phone (910) 769-1621 Fax	9/14/2020	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
w	Phone (910) 769-1621 Fax Vebsite www.schnabel-eng.com	9/14/2020 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
W iance Test	Phone (910) 769-1621 Fax /ebsite www.schnabel-eng.com ing and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
W iance Test No	Phone (910) 769-1621 Fax 'ebsite www.schnabel-eng.com ing and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
W iance Test No No	Phone (910) 769-1621 Fax Lebsite www.schnabel-eng.com Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
W iance Test No No No	Phone (910) 769-1621 Fax Lebsite www.schnabel-eng.com Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
iance Test No No No No	Phone (910) 769-1621 Fax Lebsite www.schnabel-eng.com Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
Wiance Test No No No No No No No	Phone (910) 769-1621 Fax Tebsite www.schnabel-eng.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
Wiance Test No	Phone (910) 769-1621 Fax Tebsite www.schnabel-eng.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
Wiance Test No	Phone (910) 769-1621 Fax Tebsite www.schnabel-eng.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Wiance Test No	Phone (910) 769-1621 Fax Tebsite www.schnabel-eng.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Wiance Test No	Phone (910) 769-1621 Fax Pebsite www.schnabel-eng.com Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
iance Test No No No No No No No No No vironmenta	Phone (910) 769-1621 Fax Lebsite www.schnabel-eng.com Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: LIST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
iance Test No No No No No No No No Vironmenta Yes Yes	Phone (910) 769-1621 Fax Lebsite www.schnabel-eng.com Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: LIST Compliance Consultants: UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
	iance Test No No No No No No No No No Vironmenta Yes No No No	Phone (252) 809-3608 Fax Website Mance Testing and Monitoring No Overfill Prevention Equipment Operability Check: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: No Wironmental Service Firms Yes UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:	Website Stance Testing and Monitoring No Overfill Prevention Equipment Operability Check: No No Statistical Iventory Reconciliation Services: No No Spill Prevention Equipment Testing: No No Tank Tightness Testing: No No UST Internal Inspections (Integrity Assessments): No No UST Internal Lining Inspections: No No Other: No Vironmental Service Firms Yes UST Compliance Consultants: No No UST Equipment Verification: No No Waste Disposal and Treatment: Yes No Other:	Listing Submitted Phone (252) 809-3608 Fax Website Incomplete the state of I-95 and East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No Incomplete the state of I-95 and East of I-77): No Incomplete the state of I-95 and East of I-77): Yes Mountains (West of I-77): No Incomplete the state of I-77 in No Incomplete the state of I-95 and East of I-77): Yes Mountains (West of I-77): No Incomplete the state of I-95 and East of I-77): Yes Mountains (West of I-77): No Incomplete the state of I-95 in Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-95 and East of I-77): No Incomplete the state of I-95 in Yes Central (West of I-95 in Yes Central (West of I-95): Yes Mountains (West of I-95): Yes Central (West of I-95)

Company Listing Submitted 9/6/2018 Area of state conducts work			UST Service Provider List (Co	oastai)		
Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes Mountains (West of I-77): Yes Scharlotte, NC 28273 Website www.scsengineers.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Statistical I ventory Reconcillation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Corrosion Protection Design Experts: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation Repair: No UST Equipment Installation Repair: No UST Equipment Installation Repair: No UST Equipment Repair: No UST Equipment Installation Repair: No UST Equipment Installation Repair: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Installation Repair: No UST Equipment Repair: No UST Equipment Installation Repair: No UST Equipment Repair: No UST Equipment Installation Repair: No UST Equipment Repair: No UST Equipm	Company				Area of state conducts work	
Charlotte, NC 28273 Website www.scsengineers.com Mountains (West of I-77): Yes Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Ottainment Sump Testing: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No Corrosion Protection System Repairs: No Tank Tighness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation - Complete Systems: No UST System Removal: No UST Sy	SCS Engineers, PC		Phone (704) 504-3107		Coastal (East of I-95): Yes	
Website Www.scsengineers.com Wountains (West of I-77): Yes	2520 Whitehall Park Drive, Suite 450		Fax		Central (West of I-95 and East of I-77): Yes	
Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Octrosion Protection Design Experts: No Spill Prevention Equipment Tequipment Operability Check: No Spill Prevention Equipment Tequipment	Charlotte, NC 28273				Mountains (West of I-77): Yes	
Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Statistical Ventory Reconciliation Services: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Prevention Equipment Testing: No Spill Bucket Installation Servicing: No Spill Bucket Installation Servicing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST Equipment Repair: No UST System Installation - Other: No UST System Installation - Complete Systems: No UST System Installation - Complete Systems: No UST System Repair: No UST System Installation - Other: Environmental Services: No Other: Environmental Engineer/Geologist - Site Checks: Yes UST Compliance Consultants: Yes UST Equipment Verification: No Other: Company Listing Submitted 12/12/2019 Area of state conducts work Central (West of 1-97): Yes Mountains (West of 1-77): Yes Website www.shieldengineering.com UST Equipment Service Contractors UST Equipment Service Systems: No UST System Removal: Other: Compliance Testing and Monitoring UST Equipment Services: No UST System Removal: No Overfill Prevention Equipment Operability Check: No UST System Removal: No UST System Installation: No UST System Removal: No UST System Rem		W	ebsite <u>www.scsengineers.com</u>		•	
Containment Sump Testing: No Statistical Iventory Reconcilitation Services: No Spill Prevention Equipment Testing: No Spill Bucket Installation Servicing: No Spill Bucket Installation Repair: No Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Equipment Version - No UST Piping/Sump Installation: No UST Equipment Version - No UST Piping/Sump Installation - Complete Systems: No Ust Piping/Sump Installation: No Ust Piping/Sump Installation Repoir Systems: No Ust Piping/Sump Installation Repoir S	Com	pliance Test	ng and Monitoring		UST Equipmment Service Contractors	
Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No Usr Internal Inspections (Integrity Assessments): No Usr Equipment Installation - Other: No Usr Equipment Repair: No Usr System Installation - Complete Systems: No Usr System Installation - Complete Systems: No Usr System Installation: No Usr System Installation: No Usr System Installation: No Usr System Repair: No Usr System Installation: No Usr System Repair: No Usr System Removal: No Usr System Repair: No U	Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Corrosion Protection System Repairs: No UST Internal Inspections (Integrity Assessments): No UST Equipment Installation - Other: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST System Removal: No UST System Removal: No Other: Emergency Cleanup - Spill/Release: Privironmental Engineer/Geologist - Site Checks: Pes UST Compliance Consultants: Pervironmental Engineer/Geologist Soil and GW Cleanu Soil and Solvent Recycling: No Other: Soil and Water Testing Lab: No Company Listing Submitted 12/12/2019 Area of state conducts work Complangering, Inc. Phone (704) 394-6913 Coastal (East of I-95): Yes A301 Taggart Creek Road Charlotte, NC 28208 Website www.shieldengineering.com Compliance Testing and Monitoring Website www.shieldengineering.com UST Equipment Installation - Other: No Dispenser Meter Repair/Calibration: No Containment Sump Testing: No Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No	Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No UST Internal Lining Inspections: No UST Internal Lining Inspections: No UST System Installation - Complete Systems: No UST System Installation: No UST System Removal: No UST Internal Indinal Indin	Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Leak Detection Equipment Operability Check: No Other: No	Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Leak Detection Monitoring Services: No Other: No Cine Tightness Testing: No Company Environmental Service Firms Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: No Other: Was UST Compliance Consultants: Yes UST Equipment Verification: No Other: No Other: No Other: Soil and Solvent Recycling: No Other: Soil and Water Testing Lab: No Company Environmental Engineering, Inc. 4301 Taggart Creek Road Charlotte, NC 28208 Website www.shieldengineering.com Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Other: UST Piping/Sump Installation: No Other: No Other: Ves UST Equipment Installation: No Other: No Other: Ves UST Equipment Installation: No Other: No Other: Ves UST Equipment Service Contractors No Dispenser Meter Repair/Calibration: No Containment Sump Testing: No Dispenser Meter Repair/Calibration: No Dispense	Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Line Tightness Testing: No Environmental Service Firms	Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Environmental Service Firms Emergency Cleanup - Spill/Release: Yes UST Compliance Consultants: Yes UST Equipment Verification: No Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No Oil and Solvent Recycling: No Other: Soil and Water Testing Lab: Company Listing Submitted 12/12/2019 Area of state conducts work Charlotte, NC 28208 Website www.shieldengineering.com Listing Submitted 12/12/2019 Area of state conducts work Central (West of I-95 and East of I-77): Yes Website www.shieldengineering.com Wountains (West of I-77): Yes Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: No	Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Environmental Service Firms Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No Environmental Engineer/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: No Oil and Solvent Recycling: No Other: Soil and Water Testing Lab: No Company Listing Submitted 12/12/2019 Area of state conducts work Shield Engineering, Inc. 4301 Taggart Creek Road Charlotte, NC 28208 Website www.shieldengineering.com Website www.shieldengineering.com UST Equipmment Service Contractors Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Containment Sump Testing: No Leak Detection Equipment Installation Servicing: No	Line Tightness Testing:	No			UST System Removal:	No
Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No Environmental Engineer/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: No Oil and Solvent Recycling: No Other: Soil and Water Testing Lab: No Company Listing Submitted 12/12/2019 Area of state conducts work Shield Engineering, Inc. 4301 Taggart Creek Road Charlotte, NC 28208 Website www.shieldengineering.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: No	E	nvironmenta	I Service Firms		Other:	
Environmental Engineer/Geologist - Site Checks: Yes UST Equipment Verification: No Environmental Engineer/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: No Oil and Solvent Recycling: No Other: Soil and Water Testing Lab: No Company Listing Submitted 12/12/2019 Area of state conducts work Shield Engineering, Inc. 4301 Taggart Creek Road Charlotte, NC 28208 Website www.shieldengineering.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: No	Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: No Oil and Solvent Recycling: No Other: Soil and Water Testing Lab: No Company Listing Submitted 12/12/2019 Area of state conducts work Shield Engineering, Inc. 4301 Taggart Creek Road Charlotte, NC 28208 Website www.shieldengineering.com Website www.shieldengineering.com Compliance Testing and Monitoring Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: No						
Oil and Solvent Recycling: Soil and Water Testing Lab: No Company Listing Submitted 12/12/2019 Area of state conducts work Shield Engineering, Inc. 4301 Taggart Creek Road Charlotte, NC 28208 Fax (704) 394-6968 Central (West of I-95 and East of I-77): Yes Website www.shieldengineering.com Compliance Testing and Monitoring UST Equipmment Service Contractors Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: No						
Company Listing Submitted 12/12/2019 Area of state conducts work Shield Engineering, Inc. 4301 Taggart Creek Road Charlotte, NC 28208 Website www.shieldengineering.com Compliance Testing and Monitoring Wetsof I-77): Yes Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: No			· · · · · · · · · · · · · · · · · · ·			
Shield Engineering, Inc. 4301 Taggart Creek Road Charlotte, NC 28208 Website www.shieldengineering.com Compliance Testing and Monitoring Wordling Prevention Equipment Operability Check: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing:	Soil and Water Testing Lab:	No				
4301 Taggart Creek Road Charlotte, NC 28208 Website www.shieldengineering.com Compliance Testing and Monitoring Wountains (West of I-77): Yes Website www.shieldengineering.com UST Equipmment Service Contractors Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: No	Company		Listing Submitted	12/12/2019	Area of state conducts work	
4301 Taggart Creek Road Charlotte, NC 28208 Website www.shieldengineering.com Compliance Testing and Monitoring Wountains (West of I-77): Yes Website www.shieldengineering.com UST Equipmment Service Contractors Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: No	Shield Engineering, Inc.		Phone (704) 394-6913		Coastal (East of I-95): Yes	
Charlotte, NC 28208 Website www.shieldengineering.com Mountains (West of I-77): Yes Compliance Testing and Monitoring UST Equipmment Service Contractors Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: No			` '			
Compliance Testing and Monitoring UST Equipmment Service Contractors Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: No	Charlotte, NC 28208		1 dx (104) 334-0300			
Automatic Line Leak Detector Testing: No Overfill Prevention Equipment Operability Check: No Dispenser Meter Repair/Calibration: No Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: No		W	ebsite <u>www.shieldengineering.com</u>		Mountains (west of I-77): Yes	
Containment Sump Testing: No Statistical Iventory Reconciliation Services: No Leak Detection Equipment Installation Servicing: No	Com	pliance Test	ng and Monitoring		UST Equipmment Service Contractors	
	Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
	Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts: No Spill Prevention Equipment Testing: No Spill Bucket Installation Repair: No	Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs: No Tank Tightness Testing: No UST Equipment Installation - Other: No	Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing: No UST Internal Inspections (Integrity Assessments): No UST Equipment Repair: No	Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check: No UST Internal Lining Inspections: No UST System Installation - Complete Systems: No	Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services: No Other: UST Piping/Sump Installation: No	Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing: No UST System Removal: No	Line Tightness Testing:	No			UST System Removal:	No
Environmental Service Firms Other:	E	nvironmenta	I Service Firms		Other:	
Emergency Cleanup - Spill/Release: Yes UST Compliance Consultants: Yes	Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
	Environmental Engineer/Geologist - Site Checks:		•			
			Waste Disposal and Treatment:			
Environmental Engineer/Geologist Soil and GW Cleanu Yes Waste Disposal and Treatment: Yes	•		Other:			
	on and convent receycling.					

		UST	Service Provider List (Co	astal)		
Company			Listing Submitted		Area of state conducts work	
Superior Services		Phone	(828) 698-6286		Coastal (East of I-95): Yes	
PO Box 982		Fax	(828) 698-6294		Central (West of I-95 and East of I-77): Yes	
Hendersonville, NC 28793					Mountains (West of I-77): Yes	
	1	Website	www. superiorservices.us			
Comp	oliance Tes	sting and	Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill F	Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistica	al Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Pre	evention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	<u>Yes</u>		ghtness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>		ernal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>		ernal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:	UST Repairs, AST inspection, testing	, repair	UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>				UST System Removal:	No
Er	nvironmen	ntal Servic	e Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Co	mpliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equ	uipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste D	Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					
The state of the s						
Company			Listing Submitted	11/14/2018	Area of state conducts work	
Company Terracon Consultants, Inc.		Phone	Listing Submitted (704) 509-1777	11/14/2018	Area of state conducts work Coastal (East of I-95): Yes	
Terracon Consultants, Inc. 2701 Westport Road				11/14/2018		
Terracon Consultants, Inc.		Fax	(704) 509-1777 (704) 509-1888	11/14/2018	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Terracon Consultants, Inc. 2701 Westport Road	,		(704) 509-1777	11/14/2018	Coastal (East of I-95): Yes	
Terracon Consultants, Inc. 2701 Westport Road Charlotte, NC 28208		Fax Website	(704) 509-1777 (704) 509-1888	11/14/2018	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
Terracon Consultants, Inc. 2701 Westport Road Charlotte, NC 28208		Fax Website sting and	(704) 509-1777 (704) 509-1888 www.terracon.com	11/14/2018 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
Terracon Consultants, Inc. 2701 Westport Road Charlotte, NC 28208 Comp	oliance Tes	Fax Website sting and Overfill F	(704) 509-1777 (704) 509-1888 www.terracon.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No No
Terracon Consultants, Inc. 2701 Westport Road Charlotte, NC 28208 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	oliance Tes No	Fax Website sting and Overfill F Statistics	(704) 509-1777 (704) 509-1888 www.terracon.com Monitoring Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	
Terracon Consultants, Inc. 2701 Westport Road Charlotte, NC 28208 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No	Fax Website sting and Overfill I Statistics Spill Pre Tank Tig	(704) 509-1777 (704) 509-1888 www.terracon.com Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No
Terracon Consultants, Inc. 2701 Westport Road Charlotte, NC 28208 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No	Fax Website sting and Overfill F Statistica Spill Pre Tank Tig UST Inte	(704) 509-1777 (704) 509-1888 www.terracon.com Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments):	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No
Terracon Consultants, Inc. 2701 Westport Road Charlotte, NC 28208 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Fax Website sting and Overfill F Statistica Spill Pre Tank Tig UST Inte	(704) 509-1777 (704) 509-1888 www.terracon.com Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
Terracon Consultants, Inc. 2701 Westport Road Charlotte, NC 28208 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No No No No	Fax Website sting and Overfill F Statistica Spill Pre Tank Tig UST Inte	(704) 509-1777 (704) 509-1888 www.terracon.com Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Terracon Consultants, Inc. 2701 Westport Road Charlotte, NC 28208 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Fax Website sting and Overfill F Statistica Spill Pre Tank Tig UST Inte	(704) 509-1777 (704) 509-1888 www.terracon.com Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
Terracon Consultants, Inc. 2701 Westport Road Charlotte, NC 28208 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No	Fax Website sting and Overfill F Statistic: Spill Pre Tank Tig UST Inte UST Inte Other:	(704) 509-1777 (704) 509-1888 www.terracon.com Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
Terracon Consultants, Inc. 2701 Westport Road Charlotte, NC 28208 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No No No No No No No No No No	Fax Website sting and Overfill F Statistica Spill Pre Tank Tig UST Inte UST Inte Other:	(704) 509-1777 (704) 509-1888 www.terracon.com Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Terracon Consultants, Inc. 2701 Westport Road Charlotte, NC 28208 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Fax Website sting and Overfill F Statistics Spill Pre Tank Tig UST Inte UST Inte Other: other:	(704) 509-1777 (704) 509-1888 www.terracon.com Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Terracon Consultants, Inc. 2701 Westport Road Charlotte, NC 28208 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No N	Fax Website sting and Overfill F Statistics Spill Pre Tank Tig UST Inte UST Inte Other: htal Servic UST Col UST Equ	(704) 509-1777 (704) 509-1888 www.terracon.com Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
Terracon Consultants, Inc. 2701 Westport Road Charlotte, NC 28208 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No Vo Tvironmen Yes Yes	Fax Website sting and Overfill F Statistics Spill Pre Tank Tig UST Inte UST Inte Other: htal Servic UST Col UST Equ	(704) 509-1777 (704) 509-1888 www.terracon.com Monitoring Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections: ce Firms empliance Consultants: uipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List (Co	pastal)		
Company		Listing Submitted	11/15/2018	Area of state conducts work	
Terraquest Environmental Consultants, P.C.		Phone (919) 563-9091		Coastal (East of I-95): Yes	
100 E. Ruffin Street		Fax (919) 563-9095		Central (West of I-95 and East of I-77): Yes	
Mebane, NC 27302		Website www.terraquestpc.com		Mountains (West of I-77): Yes	
		<u> </u>			
Comp	oliance Te	esting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
Er	nvironme	ntal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	3/26/2021	Area of state conducts work	
Company The Mannik & Smith Group, Inc.		Phone (336) 302-9598	3/26/2021	Area of state conducts work Coastal (East of I-95): Yes	
The Mannik & Smith Group, Inc. 4501 New Bern Avenue			3/26/2021	Coastal (East of I-95): Yes	
The Mannik & Smith Group, Inc. 4501 New Bern Avenue Suite 130#214		Phone (336) 302-9598 Fax	3/26/2021	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
The Mannik & Smith Group, Inc. 4501 New Bern Avenue		Phone (336) 302-9598	3/26/2021	Coastal (East of I-95): Yes	
The Mannik & Smith Group, Inc. 4501 New Bern Avenue Suite 130#214 Raleigh, NC 27610	oliance Te	Phone (336) 302-9598 Fax	3/26/2021	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
The Mannik & Smith Group, Inc. 4501 New Bern Avenue Suite 130#214 Raleigh, NC 27610	<mark>oliance T</mark> e	Phone (336) 302-9598 Fax Website www.MannikSmithGroup.com	3/26/2021 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
The Mannik & Smith Group, Inc. 4501 New Bern Avenue Suite 130#214 Raleigh, NC 27610 Comp		Phone (336) 302-9598 Fax Website www.MannikSmithGroup.com esting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
The Mannik & Smith Group, Inc. 4501 New Bern Avenue Suite 130#214 Raleigh, NC 27610 Comp Automatic Line Leak Detector Testing:	No	Phone (336) 302-9598 Fax Website www.MannikSmithGroup.com esting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
The Mannik & Smith Group, Inc. 4501 New Bern Avenue Suite 130#214 Raleigh, NC 27610 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	No No	Phone (336) 302-9598 Fax Website www.MannikSmithGroup.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
The Mannik & Smith Group, Inc. 4501 New Bern Avenue Suite 130#214 Raleigh, NC 27610 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No	Phone (336) 302-9598 Fax Website www.MannikSmithGroup.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
The Mannik & Smith Group, Inc. 4501 New Bern Avenue Suite 130#214 Raleigh, NC 27610 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No	Phone (336) 302-9598 Fax Website www.MannikSmithGroup.com Pesting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No
The Mannik & Smith Group, Inc. 4501 New Bern Avenue Suite 130#214 Raleigh, NC 27610 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services:	No No No No No No	Phone (336) 302-9598 Fax Website www.MannikSmithGroup.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
The Mannik & Smith Group, Inc. 4501 New Bern Avenue Suite 130#214 Raleigh, NC 27610 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No	Phone (336) 302-9598 Fax Website www.MannikSmithGroup.com Pesting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No
The Mannik & Smith Group, Inc. 4501 New Bern Avenue Suite 130#214 Raleigh, NC 27610 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No	Phone (336) 302-9598 Fax Website www.MannikSmithGroup.com Pesting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
The Mannik & Smith Group, Inc. 4501 New Bern Avenue Suite 130#214 Raleigh, NC 27610 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release:	No No No No No No No	Phone (336) 302-9598 Fax Website www.MannikSmithGroup.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
The Mannik & Smith Group, Inc. 4501 New Bern Avenue Suite 130#214 Raleigh, NC 27610 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No No No No No No No No Trironmel Yes Yes	Phone (336) 302-9598 Fax Website www.MannikSmithGroup.com Pesting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
The Mannik & Smith Group, Inc. 4501 New Bern Avenue Suite 130#214 Raleigh, NC 27610 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No No No No No No No No No Trironmel Yes Yes	Phone (336) 302-9598 Fax Website www.MannikSmithGroup.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Intal Service Firms UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
The Mannik & Smith Group, Inc. 4501 New Bern Avenue Suite 130#214 Raleigh, NC 27610 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No No No No No No No Vo revironment Yes Yes	Phone (336) 302-9598 Fax Website www.MannikSmithGroup.com esting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Intal Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST Service Provider List (Co	astal)		
Company		Listing Submitted		Area of state conducts work	
TideLand Construction, LLC		Phone (252) 524-1644		Coastal (East of I-95): Yes	
3600 North Drive		Fax (252) 565-8724		Central (West of I-95 and East of I-77): Yes	
Greenville, NC 27834-		(===, =================================		Mountains (West of I-77): Yes	
	W	ebsite tidelandconstruction.com		mountains (west of 177).	
Comp	liance Test	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
Er	nvironmenta	al Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	8/12/2020	Area of state conducts work	
To the control of t		Elsting Submitted	0/12/2020	7.1.00 01 01010 00110010 11011	
TIMMONS GROUP		Phone (919) 866-4951	0/12/2020	Coastal (East of I-95): Yes	
		Phone (919) 866-4951	0/12/2020	Coastal (East of I-95): Yes	
TIMMONS GROUP			0/12/2020	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
TIMMONS GROUP 5410 TRINITY ROAD, SUITE 102	W	Phone (919) 866-4951	0/12/2020	Coastal (East of I-95): Yes	
TIMMONS GROUP 5410 TRINITY ROAD, SUITE 102 RALEIGH, NC 27606		Phone (919) 866-4951 Fax	0/12/2020	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
TIMMONS GROUP 5410 TRINITY ROAD, SUITE 102 RALEIGH, NC 27606		Phone (919) 866-4951 Fax /ebsite http://www.timmons.com/	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
TIMMONS GROUP 5410 TRINITY ROAD, SUITE 102 RALEIGH, NC 27606 Comp	oliance Test	Phone (919) 866-4951 Fax /ebsite http://www.timmons.com/ ing and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
TIMMONS GROUP 5410 TRINITY ROAD, SUITE 102 RALEIGH, NC 27606 Compa	oliance Test No	Phone (919) 866-4951 Fax /ebsite http://www.timmons.com/ ing and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
TIMMONS GROUP 5410 TRINITY ROAD, SUITE 102 RALEIGH, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	No No	Phone (919) 866-4951 Fax /ebsite http://www.timmons.com/ ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
TIMMONS GROUP 5410 TRINITY ROAD, SUITE 102 RALEIGH, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No No	Phone (919) 866-4951 Fax /ebsite http://www.timmons.com/ ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
TIMMONS GROUP 5410 TRINITY ROAD, SUITE 102 RALEIGH, NC 27606 Comparing Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No No No	Phone (919) 866-4951 Fax /ebsite http://www.timmons.com/ ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
TIMMONS GROUP 5410 TRINITY ROAD, SUITE 102 RALEIGH, NC 27606 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No	Phone (919) 866-4951 Fax /ebsite http://www.timmons.com/ ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No
TIMMONS GROUP 5410 TRINITY ROAD, SUITE 102 RALEIGH, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (919) 866-4951 Fax /ebsite http://www.timmons.com/ ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No
TIMMONS GROUP 5410 TRINITY ROAD, SUITE 102 RALEIGH, NC 27606 Comparing Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (919) 866-4951 Fax /ebsite http://www.timmons.com/ ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No No
TIMMONS GROUP 5410 TRINITY ROAD, SUITE 102 RALEIGH, NC 27606 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (919) 866-4951 Fax /ebsite http://www.timmons.com/ ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
TIMMONS GROUP 5410 TRINITY ROAD, SUITE 102 RALEIGH, NC 27606 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (919) 866-4951 Fax /ebsite http://www.timmons.com/ ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
TIMMONS GROUP 5410 TRINITY ROAD, SUITE 102 RALEIGH, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No N	Phone (919) 866-4951 Fax /ebsite http://www.timmons.com/ ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
TIMMONS GROUP 5410 TRINITY ROAD, SUITE 102 RALEIGH, NC 27606 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No N	Phone (919) 866-4951 Fax /ebsite http://www.timmons.com/ ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Al Service Firms UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No
TIMMONS GROUP 5410 TRINITY ROAD, SUITE 102 RALEIGH, NC 27606 Comparing Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu	No N	Phone (919) 866-4951 Fax /ebsite http://www.timmons.com/ ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No No

		UST Service Provider List (Co	astal)		
Company		Listing Submitted	8/13/2020	Area of state conducts work	
Unified Services of Texas		Phone (817) 481-9510		Coastal (East of I-95): Yes	
2110 Greenbriar dr.		Fax		Central (West of I-95 and East of I-77): Yes	
Southlake, TX 76092				Mountains (West of I-77): Yes	
	W	ebsite ustfuel.com		, , , , , , , , , , , , , , , , , , , ,	
Comp	oliance Test	ing and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
Er	nvironmenta	I Service Firms		Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	<u>Yes</u>	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	11/16/2018	Area of state conducts work	
Company UST Corrosion Management, Inc.		Phone (888) 822-2431	11/16/2018	Area of state conducts work Coastal (East of I-95): Yes	
UST Corrosion Management, Inc. 2764 Pleasant Rd. #10714		Phone (888) 822-2431	11/16/2018	Coastal (East of I-95): Yes	
UST Corrosion Management, Inc.		Phone (888) 822-2431	11/16/2018	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
UST Corrosion Management, Inc. 2764 Pleasant Rd. #10714	w	Phone (888) 822-2431	11/16/2018	Coastal (East of I-95): Yes	
UST Corrosion Management, Inc. 2764 Pleasant Rd. #10714 Fort Mill, SC 29708		Phone (888) 822-2431 Fax (803) 802-0561	11/16/2018	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
UST Corrosion Management, Inc. 2764 Pleasant Rd. #10714 Fort Mill, SC 29708		Phone (888) 822-2431 Fax (803) 802-0561 ebsite www.ustcorrosion.com	11/16/2018 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
UST Corrosion Management, Inc. 2764 Pleasant Rd. #10714 Fort Mill, SC 29708	oliance Test	Phone (888) 822-2431 Fax (803) 802-0561 ebsite www.ustcorrosion.com ing and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
UST Corrosion Management, Inc. 2764 Pleasant Rd. #10714 Fort Mill, SC 29708 Company Automatic Line Leak Detector Testing:	oliance Test No	Phone (888) 822-2431 Fax (803) 802-0561 ebsite www.ustcorrosion.com ing and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	
UST Corrosion Management, Inc. 2764 Pleasant Rd. #10714 Fort Mill, SC 29708 Comparison of Containment Sump Testing:	No No	Phone (888) 822-2431 Fax (803) 802-0561 ebsite www.ustcorrosion.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
UST Corrosion Management, Inc. 2764 Pleasant Rd. #10714 Fort Mill, SC 29708 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts:	No No No <u>Yes</u>	Phone (888) 822-2431 Fax (803) 802-0561 ebsite www.ustcorrosion.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair:	No No
UST Corrosion Management, Inc. 2764 Pleasant Rd. #10714 Fort Mill, SC 29708 Comparing Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs:	No No No <u>Yes</u> <u>Yes</u>	Phone (888) 822-2431 Fax (803) 802-0561 ebsite www.ustcorrosion.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other:	No No No
UST Corrosion Management, Inc. 2764 Pleasant Rd. #10714 Fort Mill, SC 29708 Comparing Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No Yes Yes Yes	Phone (888) 822-2431 Fax (803) 802-0561 ebsite www.ustcorrosion.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No
UST Corrosion Management, Inc. 2764 Pleasant Rd. #10714 Fort Mill, SC 29708 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No Yes Yes Yes No	Phone (888) 822-2431 Fax (803) 802-0561 ebsite www.ustcorrosion.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
UST Corrosion Management, Inc. 2764 Pleasant Rd. #10714 Fort Mill, SC 29708 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No Yes Yes Yes No No No No	Phone (888) 822-2431 Fax (803) 802-0561 ebsite www.ustcorrosion.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
UST Corrosion Management, Inc. 2764 Pleasant Rd. #10714 Fort Mill, SC 29708 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No Yes Yes Yes No No No No	Phone (888) 822-2431 Fax (803) 802-0561 Lebsite www.ustcorrosion.com Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
UST Corrosion Management, Inc. 2764 Pleasant Rd. #10714 Fort Mill, SC 29708 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No Yes Yes Yes No	Phone (888) 822-2431 Fax (803) 802-0561 ebsite www.ustcorrosion.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
UST Corrosion Management, Inc. 2764 Pleasant Rd. #10714 Fort Mill, SC 29708 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No No Yes Yes Yes No	Phone (888) 822-2431 Fax (803) 802-0561 Lebsite www.ustcorrosion.com Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
UST Corrosion Management, Inc. 2764 Pleasant Rd. #10714 Fort Mill, SC 29708 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No No Yes Yes Yes No	Phone (888) 822-2431 Fax (803) 802-0561 Lebsite www.ustcorrosion.com Ling and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No

		UST	Service Provider List (Co	astal)		
Company			Listing Submitted	7/9/2019	Area of state conducts work	
Valley Tank Testing		Phone	(813) 671-9065		Coastal (East of I-95): Yes	
451 Apollo Beach Blvd.		Fax	(866) 328-9796		Central (West of I-95 and East of I-77): Yes	
Apollo Beach, FL 33572	14/	lebsite	www.valleytank.com		Mountains (West of I-77): Yes	
	oliance Testi				UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>		Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>		al Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No		evention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No		ghtness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>		ernal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>		ernal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:			UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>				UST System Removal: Other:	No
Eı	nvironmenta				Other.	
Emergency Cleanup - Spill/Release:	No	UST Co	mpliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No		uipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	l No	Waste D	Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					
Company			Listing Submitted	9/6/2018	Area of state conducts work	
Vital Fuel Systems, Inc.		Phone	(919) 303-7374		Coastal (East of I-95): Yes	
1076 Classic Road		Fax	(919) 303-7399		Central (West of I-95 and East of I-77): Yes	
Apex, NC 27539					Mountains (West of I-77): Yes	
	W	lebsite	www.vitalfuelsystems.com			
Comp	oliance Testi	ing and	Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill	Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistic	al Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Pre	vention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Ti	ghtness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	No	UST Inte	ernal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Inte	ernal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
		0.1			UST Piping/Sump Installation:	No
Leak Detection Monitoring Services:	No	Other:				
Leak Detection Monitoring Services: Line Tightness Testing:	No No	Other:			UST System Removal:	<u>Yes</u>
Line Tightness Testing:			e Firms			
Line Tightness Testing:	No	al Servic	e Firms mpliance Consultants:	No	UST System Removal:	
Line Tightness Testing:	No nvironmenta	al Servic UST Co		No No	UST System Removal:	
Line Tightness Testing: Energency Cleanup - Spill/Release:	No nvironmenta No No	al Servic UST Co UST Eq	mpliance Consultants:		UST System Removal:	
Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No nvironmenta No No	al Servic UST Co UST Eq	mpliance Consultants: uipment Verification:	No	UST System Removal:	

		UST Service Provider List (C	oastal)		
Company		Listing Submitted	2/5/2021	Area of state conducts work	
Wildco PES		Phone (603) 935-9330		Coastal (East of I-95): Yes	
440 Harvey Rd		Fax		Central (West of I-95 and East of I-77): Yes	
497 Lendall Lane Fredericksburg VA 22405				Mountains (West of I-77): No	
Manchester, NH 3103		Website WILDCOPES.COM			
Comp	oliance Te	sting and Monitoring		UST Equipmment Service Contractors	
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
Er	nvironmen	tal Service Firms		Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company		Listing Submitted	8/13/2020	Area of state conducts work	
Company WithersRavenel, Inc.		Phone (919) 469-3340	8/13/2020	Area of state conducts work Coastal (East of I-95): Yes	
WithersRavenel, Inc. 115 MacKenan Drive			8/13/2020		
WithersRavenel, Inc.		Phone (919) 469-3340 Fax	8/13/2020	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
WithersRavenel, Inc. 115 MacKenan Drive		Phone (919) 469-3340	8/13/2020	Coastal (East of I-95): Yes	
WithersRavenel, Inc. 115 MacKenan Drive Cary, NC 27511		Phone (919) 469-3340 Fax	8/13/2020	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes	
WithersRavenel, Inc. 115 MacKenan Drive Cary, NC 27511		Phone (919) 469-3340 Fax Website www.withersravenel.com	8/13/2020 No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	No
WithersRavenel, Inc. 115 MacKenan Drive Cary, NC 27511 Comp	oliance Te	Phone (919) 469-3340 Fax Website www.withersravenel.com sting and Monitoring		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors	No No
WithersRavenel, Inc. 115 MacKenan Drive Cary, NC 27511 Compared Automatic Line Leak Detector Testing:	oliance Tes No	Phone (919) 469-3340 Fax Website www.withersravenel.com sting and Monitoring Overfill Prevention Equipment Operability Check:	No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration:	
WithersRavenel, Inc. 115 MacKenan Drive Cary, NC 27511 Comp Automatic Line Leak Detector Testing: Containment Sump Testing:	No No	Phone (919) 469-3340 Fax Website www.withersravenel.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing:	No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing:	No
WithersRavenel, Inc. 115 MacKenan Drive Cary, NC 27511 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No	Phone (919) 469-3340 Fax Website www.withersravenel.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing:	No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No
WithersRavenel, Inc. 115 MacKenan Drive Cary, NC 27511 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No	Phone (919) 469-3340 Fax Website www.withersravenel.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems:	No No No No No
WithersRavenel, Inc. 115 MacKenan Drive Cary, NC 27511 Comparing Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing:	No No No No No No No	Phone (919) 469-3340 Fax Website www.withersravenel.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments):	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair:	No No No No No
WithersRavenel, Inc. 115 MacKenan Drive Cary, NC 27511 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check:	No No No No No No No No	Phone (919) 469-3340 Fax Website www.withersravenel.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
WithersRavenel, Inc. 115 MacKenan Drive Cary, NC 27511 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (919) 469-3340 Fax Website www.withersravenel.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation:	No No No No No
WithersRavenel, Inc. 115 MacKenan Drive Cary, NC 27511 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No No No No No No No No No No	Phone (919) 469-3340 Fax Website www.withersravenel.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
WithersRavenel, Inc. 115 MacKenan Drive Cary, NC 27511 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing:	No N	Phone (919) 469-3340 Fax Website www.withersravenel.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other:	No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
WithersRavenel, Inc. 115 MacKenan Drive Cary, NC 27511 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release:	No Vo Trinomen Yes Yes	Phone (919) 469-3340 Fax Website www.withersravenel.com sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: ttal Service Firms UST Compliance Consultants:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No
WithersRavenel, Inc. 115 MacKenan Drive Cary, NC 27511 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks:	No Vo No Trironmen Yes Yes	Phone (919) 469-3340 Fax Website www.withersravenel.com Sting and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment:	No No No No No No	Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal:	No No No No No