

## UST Service Provider List (Mountains)

<b>Company</b>	<b>Listing Submitted</b>		<b>Area of state conducts work</b>
<b>ABC Global Contracting LLC</b> 32032 28 Mile Road Lenox, Michigan 48048-	<b>Phone</b> (810) 533-2416  <b>Fax</b>  <b>Website</b> <a href="http://abcglobalcontracting.com">abcglobalcontracting.com</a>	11/19/2018	<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing:	<b>Yes</b>	Overfill Prevention Equipment Operability Check:	<b>Yes</b>
Containment Sump Testing:	<b>Yes</b>	Statistical Inventory Reconciliation Services:	<b>Yes</b>
Corrosion Protection Design Experts:	<b>Yes</b>	Spill Prevention Equipment Testing:	<b>Yes</b>
Corrosion Protection System Repairs:	<b>Yes</b>	Tank Tightness Testing:	<b>Yes</b>
Corrosion Protection System Testing:	<b>Yes</b>	UST Internal Inspections (Integrity Assessments):	<b>Yes</b>
Leak Detection Equipment Operability Check:	<b>Yes</b>	UST Internal Lining Inspections:	<b>Yes</b>
Leak Detection Monitoring Services:	<b>Yes</b>	Other:	
Line Tightness Testing:	<b>Yes</b>		
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<b>Yes</b>
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<b>Yes</b>
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
<b>Advanced Environmental Solutions, LLC</b> P.O. Box 1426 Black Mountain, NC 28711	<b>Phone</b> (828) 664-9822  <b>Fax</b> (866) 425-2661  <b>Website</b> <a href="http://advancedenvironmentalsolutions.com">advancedenvironmentalsolutions.com</a>	11/14/2018	<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing:	<b>Yes</b>	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	<b>Yes</b>	Statistical Inventory Reconciliation Services:	<b>Yes</b>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<b>Yes</b>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<b>Yes</b>
Corrosion Protection System Testing:	<b>Yes</b>	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	<b>Yes</b>		
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

## UST Service Provider List (Mountains)

Company	Listing Submitted		Area of state conducts work
<b>AES of Greenville LLC</b> 141 S. Market Street Washington, NC 27889	<b>Phone</b> (252) 758-3311  <b>Fax</b> (252) 481-5814  <b>Website</b> <a href="http://www.aes-nc.com">www.aes-nc.com</a>	10/2/2017	<b>Coastal (East of I-95):</b> Yes  <b>Central (West of I-95 and East of I-77):</b> Yes  <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: <b>Yes</b> Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: <b>Yes</b> Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: <b>Yes</b> Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: <b>Yes</b> UST Internal Inspections (Integrity Assessments): <b>Yes</b> UST Internal Lining Inspections: <b>Yes</b> Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: <b>Yes</b> Waste Disposal and Treatment: No Other:		
Company	Listing Submitted		Area of state conducts work
<b>Apex Engineering, PC</b> 15850 Crabbs Branch Way Suite 200 Rockville, Maryland 20855-	<b>Phone</b> (301) 417-0200  <b>Fax</b> (301) 975-0169  <b>Website</b> <a href="http://www.apexcos.com">www.apexcos.com</a>	10/13/2017	<b>Coastal (East of I-95):</b> Yes  <b>Central (West of I-95 and East of I-77):</b> Yes  <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: <b>Yes</b> Soil and Water Testing Lab: <b>Yes</b>	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: <b>Yes</b> Waste Disposal and Treatment: <b>Yes</b> Other:		

## UST Service Provider List (Mountains)

Company	Listing Submitted			Area of state conducts work
<b>Applied Science &amp; Engineering, LLC</b> 550 N. Reo Street Tampa, FL 33609	<b>Listing Submitted</b> 1/2/2018	<b>Phone</b> (813) 207-5061  <b>Fax</b> (813) 288-1550  <b>Website</b>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:	
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:			
<b>Bunnell-Lammons Engineering Inc.</b> 130 Oval Road Suite 200 Arden, NC 28704	<b>Listing Submitted</b> 11/14/2018	<b>Phone</b> (828) 277-0100  <b>Fax</b> (828) 277-0110  <b>Website</b> <a href="http://www.blecorp.com">www.blecorp.com</a>		<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:	
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: <b>Yes</b> Soil and Water Testing Lab: <b>Yes</b>	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: <b>Yes</b> Waste Disposal and Treatment: <b>Yes</b> Other: Trust Fund Projects			

## UST Service Provider List (Mountains)

Company	Listing Submitted			Area of state conducts work
<b>Cape Lookout Environmental Sciences, PLLC</b> 8005 Clear Brook Drive Raleigh, NC 27615	<b>Phone</b> (919) 757-7901  <b>Fax</b>  <b>Website</b> <a href="http://CapeLookoutEnv.com">CapeLookoutEnv.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: <b>Yes</b> Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other:			
<b>Carbon Fuel Services, LLC</b> 301 E Main Street Cherryville, NC 28021-	<b>Phone</b> (704) 419-9939  <b>Fax</b>  <b>Website</b> <a href="http://www.carbonfuelservices.com">www.carbonfuelservices.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: Diesel Fuel Compliance Laboratory Testing	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other: Diesel Fuel Polishing, Filtration, and Recovery Services		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other: Diesel Fuel Additives and Tank Cleaning Agents			

## UST Service Provider List (Mountains)

Company	Listing Submitted			Area of state conducts work
<b>Catholic Protection Services, Inc.</b> 445 Gap Creek Rd. Elizabethton, TN 37643	<b>Phone</b> (423) 895-1500  <b>Fax</b> (423) 542-8955  <b>Website</b>	6/10/2017	<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes	
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: <b>Yes</b> Corrosion Protection System Repairs: <b>Yes</b> Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:	
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:			
Company	Listing Submitted			Area of state conducts work
<b>Christopher Dunlap, P.G.</b> 166 Michigan Avenue Asheville, NC 28806	<b>Phone</b> (828) 505-6301  <b>Fax</b>  <b>Website</b>	10/9/2017	<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes	
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:	
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: No Waste Disposal and Treatment: No Other:			

## UST Service Provider List (Mountains)

Company	Listing Submitted	10/12/2017	Area of state conducts work
<b>Cobb Environmental &amp; Technical Services, Inc.</b> P. O. Box 1602, Tupelo, MS 38802 871 South Green Street Tupelo, MS 38804	<b>Phone</b> (662) 841-0995  <b>Fax</b> (662) 841-0810  <b>Website</b> <a href="http://www.cobbenv.com">www.cobbenv.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: <b>Yes</b> Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: <b>Yes</b> Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: <b>Yes</b> Leak Detection Equipment Installation Servicing: <b>Yes</b> Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: <b>Yes</b> UST Equipment Repair: <b>Yes</b> UST System Installation - Complete Systems: <b>Yes</b> UST Piping/Sump Installation: <b>Yes</b> UST System Removal: <b>Yes</b> Other:
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: <b>Yes</b> Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	11/14/2018	Area of state conducts work
<b>Cohesion, Inc.</b> 5216 Yates Mill Pond Road Raleigh, NC 27606	<b>Phone</b> (919) 233-8626  <b>Fax</b> (919) 233-8909  <b>Website</b> <a href="http://www.cohesion-inc.com">www.cohesion-inc.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

## UST Service Provider List (Mountains)

<b>Company</b>	<b>Listing Submitted</b>		<b>Area of state conducts work</b>
<b>CROMPCO, LLC</b> 1815 Gallagher Road Plymouth Meeting, PA 19462  <b>Phone</b> (800) 646-3161 <b>Fax</b> (610) 278-7621  <b>Website</b> <a href="http://www.crompco.com">www.crompco.com</a>	11/15/2018		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: <b>Yes</b> Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: <b>Yes</b> Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: <b>Yes</b> UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: <b>Yes</b> Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
<b>Company</b>	<b>Listing Submitted</b>		<b>Area of state conducts work</b>
<b>CROMPCO, LLC</b> 1815 GALLAGHER ROAD PLYMOUTH MEETING, PA 19462  <b>Phone</b> (800) 646-3161 <b>Fax</b> (610) 278-7621  <b>Website</b> <a href="http://WWW.CROMPCO.COM">WWW.CROMPCO.COM</a>	11/14/2018		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: <b>Yes</b> Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: <b>Yes</b> Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: <b>Yes</b> UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: <b>Yes</b> Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

## UST Service Provider List (Mountains)

<b>Company</b>	<b>Listing Submitted</b>		<b>Area of state conducts work</b>
<b>DAVENPORT</b> 3722 Shipyard Boulevard Suite E Wilmington, NC 28412	<b>Phone</b> (910) 251-8912  <b>Fax</b>  <b>Website</b> <a href="http://www.davenportworld.com/">http://www.davenportworld.com/</a>	6/20/2018	<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release:	<b>Yes</b>	UST Compliance Consultants:	<b>Yes</b>
Environmental Engineer/Geologist - Site Checks:	<b>Yes</b>	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	<b>Yes</b>	Waste Disposal and Treatment:	<b>Yes</b>
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
<b>EMS Environmental, Inc.</b> 117 South Hoover Road Durham, NC 27703	<b>Phone</b> (919) 596-0470  <b>Fax</b> (919) 596-0578  <b>Website</b> <a href="http://www.emsenv.com">www.emsenv.com</a>	11/15/2018	<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<b>Yes</b>
Environmental Engineer/Geologist - Site Checks:	<b>Yes</b>	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	<b>Yes</b>	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	<b>Yes</b>		



## UST Service Provider List (Mountains)

Company	Listing Submitted			Area of state conducts work
<b>Enviro Consulting</b> 531 Pitts School Road NW Suite D Concord, NC 28027	<b>Phone</b> (704) 721-0101  <b>Fax</b> (704) 721-0102  <b>Website</b> <a href="http://www.envirocorp.net">www.envirocorp.net</a>			<b>Coastal (East of I-95):</b> Yes  <b>Central (West of I-95 and East of I-77):</b> Yes  <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: <b>Yes</b> Corrosion Protection System Repairs: <b>Yes</b> Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: <b>Yes</b> Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: <b>Yes</b> Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: <b>Yes</b> UST Internal Inspections (Integrity Assessments): <b>Yes</b> UST Internal Lining Inspections: <b>Yes</b> Other:	UST Lining Installation		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: <b>Yes</b> UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: <b>Yes</b> Waste Disposal and Treatment: No Other:			
Company	Listing Submitted			Area of state conducts work
<b>EnviroTrac Ltd.</b> 7343 West Friendly Avenue Greensboro, NC 27410	<b>Phone</b> (336) 763-6025  <b>Fax</b>  <b>Website</b> <a href="http://www.envirotrac.com">www.envirotrac.com</a>			<b>Coastal (East of I-95):</b> Yes  <b>Central (West of I-95 and East of I-77):</b> Yes  <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	UST Lining Installation		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:
Environmental Service Firms				
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: <b>Yes</b>	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: <b>Yes</b> Waste Disposal and Treatment: <b>Yes</b> Other:			

## UST Service Provider List (Mountains)

Company	Listing Submitted			Area of state conducts work
<b>ESP Associates, P.A.</b> PO Box 7030 Charlotte, NC 28241	<b>Phone</b> (704) 583-4949  <b>Fax</b> (803) 802-2515  <b>Website</b> <a href="http://www.espassociates.com">www.espassociates.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other:			
Company	Listing Submitted			Area of state conducts work
<b>Evo Corporation</b> 1703 Vargrave Street Winston-Salem, NC 27107	<b>Phone</b> (336) 725-5844  <b>Fax</b> (336) 725-6244  <b>Website</b> <a href="http://www.evocorp.net">www.evocorp.net</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: <b>Yes</b> Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other:			

## UST Service Provider List (Mountains)

Company	Listing Submitted			Area of state conducts work
<b>Falcon Engineers</b> 1210 Trinity Road Suite 110 Raleigh, NC 27607	<b>Phone</b> (919) 871-0800  <b>Fax</b> (919) 871-0803  <b>Website</b> <a href="http://www.falconengineers.com">www.falconengineers.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: <b>Yes</b>	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other: Please call for additional service options!			
<b>First Call Environmental, LLC</b> 7300 Vonclaybon Road Unit 418 Apex, NC 27523	<b>Phone</b> (800) 646-1290  <b>Fax</b> (888) 536-1352  <b>Website</b> <a href="http://www.firstcallenvironmental.com">www.firstcallenvironmental.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other:			

## UST Service Provider List (Mountains)

Company	Listing Submitted			Area of state conducts work
<b>Galloway</b> 6162 South Willow Drive Suite 320 Greenwood Village, CO 80111	11/14/2018	<b>Phone</b> (303) 770-8884  <b>Fax</b> (303) 770-3636  <b>Website</b> <a href="http://www.GallowayUS.com">www.GallowayUS.com</a>		<b>Coastal (East of I-95):</b> Yes  <b>Central (West of I-95 and East of I-77):</b> Yes  <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other: UST System Design	
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:			
<b>Geo-Hydro Engineers, Inc.</b> 2748 Interstate Street Suite A Charlotte, NC 28208	11/9/2018	<b>Phone</b> (704) 837-7174  <b>Fax</b>  <b>Website</b> <a href="http://www.geohydro.com">www.geohydro.com</a>		<b>Coastal (East of I-95):</b> Yes  <b>Central (West of I-95 and East of I-77):</b> Yes  <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:	
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:			

## UST Service Provider List (Mountains)

Company	Listing Submitted			Area of state conducts work
<b>Geological Resources, Inc.</b> 3502 Hayes Road Monroe, NC 28110	<b>Phone</b> (704) 845-4010  <b>Fax</b> (704) 845-4012  <b>Website</b> <a href="http://www.geologicalresourcesinc.com">www.geologicalresourcesinc.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:			Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:
Environmental Service Firms				
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: No Waste Disposal and Treatment: No Other:			
Company	Listing Submitted			Area of state conducts work
<b>Guardian Fueling Technologies</b> 5116 Departure Drive Raleigh, NC 27616	<b>Phone</b> (919) 729-6980  <b>Fax</b>  <b>Website</b> <a href="http://www.guardianfueltech.com">www.guardianfueltech.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: <b>Yes</b> Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: SafeGuard UST Inspection Services			Dispenser Meter Repair/Calibration: <b>Yes</b> Leak Detection Equipment Installation Servicing: <b>Yes</b> Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: <b>Yes</b> UST Equipment Repair: <b>Yes</b> UST System Installation - Complete Systems: <b>Yes</b> UST Piping/Sump Installation: <b>Yes</b> UST System Removal: <b>Yes</b> Other: FuelGuard Fuel Cleaning & Biocide Treatment
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:			

## UST Service Provider List (Mountains)

Company	Listing Submitted	11/14/2018	Area of state conducts work
<b>HARCO Services LLC</b> PO Box 2347 Kennesaw, GA 30156  <b>Phone</b> (770) 917-8846 <b>Fax</b> (770) 917-0921  <b>Website</b> <a href="http://www.harcoservices.com">www.harcoservices.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: <b>Yes</b> UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:	
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	8/25/2016	Area of state conducts work
<b>Harmon Environmental, PA</b> 615 Bruce Thomas Road Monroe, NC 28112  <b>Phone</b> (704) 764-5694 <b>Fax</b> (704) 764-5694  <b>Website</b> <a href="mailto:harmonenv@yahoo.com">harmonenv@yahoo.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:	
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

## UST Service Provider List (Mountains)

<b>Company</b>	<b>Listing Submitted</b>		<b>Area of state conducts work</b>
<b>Henry Nemargut Engineering Services</b> 2211 Chestnut Street Wilmington, NC 28403  <b>Phone</b> (336) 316-0452 <b>Fax</b> (910) 762-3284  <b>Website</b>		1/15/2019	<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	Dispenser Meter Repair/Calibration:
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	Leak Detection Equipment Installation Servicing:
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Spill Bucket Installation Repair:
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	UST Equipment Installation - Other:
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	UST Equipment Repair:
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	UST System Installation - Complete Systems:
Leak Detection Monitoring Services:	No	Other:	UST Piping/Sump Installation:
Line Tightness Testing:	No		UST System Removal:
			Other:
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<b>Yes</b>
Environmental Engineer/Geologist - Site Checks:	<b>Yes</b>	UST Equipment Verification:	<b>Yes</b>
Environmental Engineer/Geologist Soil and GW Cleanu	<b>Yes</b>	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

<b>Company</b>	<b>Listing Submitted</b>		<b>Area of state conducts work</b>
<b>HERR, Inc.</b> 303 S. Maulsby St Whiteville, NC 28472  <b>Phone</b> (910) 640-2607 <b>Fax</b> (910) 640-2609  <b>Website</b> <a href="http://www.herrteam.com">www.herrteam.com</a>		4/5/2017	<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	Dispenser Meter Repair/Calibration:
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	Leak Detection Equipment Installation Servicing:
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Spill Bucket Installation Repair:
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	UST Equipment Installation - Other:
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	UST Equipment Repair:
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	UST System Installation - Complete Systems:
Leak Detection Monitoring Services:	No	Other:	UST Piping/Sump Installation:
Line Tightness Testing:	No		UST System Removal:
			Other:
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release:	<b>Yes</b>	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<b>Yes</b>
Oil and Solvent Recycling:	<b>Yes</b>	Other:	
Soil and Water Testing Lab:	No		

## UST Service Provider List (Mountains)

<b>Company</b>	<b>Listing Submitted</b>		<b>Area of state conducts work</b>
<b>Highlands Environmental Solutions, Inc.</b> 8410-D Falls of Neuse Road Raleigh, NC 27615  <b>Phone</b> (919) 848-3155 <b>Fax</b> (919) 848-4265  <b>Website</b> <a href="http://www.HESfast.com">www.HESfast.com</a>	11/14/2018		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	<b>Yes</b>
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<b>Yes</b>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release:	<b>Yes</b>	UST Compliance Consultants:	<b>Yes</b>
Environmental Engineer/Geologist - Site Checks:	<b>Yes</b>	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	<b>Yes</b>	Waste Disposal and Treatment:	<b>Yes</b>
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
<b>INDUSTRY STANDARD CORRSION CONTROL - LLC</b> 400 HARBOR DRIVE NEW BERN, NC 28560  <b>Phone</b> (252) 229-0485 <b>Fax</b> (704) 972-0300  <b>Website</b> <a href="http://WWW.ISCC.TECH">WWW.ISCC.TECH</a>	8/22/2016		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	<b>Yes</b>	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	<b>Yes</b>	Tank Tightness Testing:	No
Corrosion Protection System Testing:	<b>Yes</b>	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		



## UST Service Provider List (Mountains)

Company	Listing Submitted	11/14/2018	Area of state conducts work
<b>Johnson, Spellman &amp; Associates, Inc.</b> 350 Research Court Suite 130 Peachtree Corners, GA 30092	<b>Phone</b> (770) 447-4555  <b>Fax</b>  <b>Website</b> <a href="http://www.jsace.com">www.jsace.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: No Waste Disposal and Treatment: No Other: mechanical engineers - fuel system design		
Company	Listing Submitted	11/14/2018	Area of state conducts work
<b>Johnson, Spellman and Associates</b> 350 Research Court Suite 130 Peachtree Corners, GA 30092	<b>Phone</b> (770) 447-4555  <b>Fax</b>  <b>Website</b> <a href="http://www.jsace.com">www.jsace.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: System design services - Engineering		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other: System design services - Engineering
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

## UST Service Provider List (Mountains)

<b>Company</b>	<b>Listing Submitted</b>		<b>Area of state conducts work</b>
<b>Jones &amp; Frank</b> 4720 Old Poole Rd Raleigh, NC 27610  <b>Phone</b> (919) 231-1998 <b>Fax</b> (919) 231-1994  <b>Website</b> <a href="http://www.jones-frank.com">www.jones-frank.com</a>	7/5/2016		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing:	<b>Yes</b>	Overfill Prevention Equipment Operability Check:	<b>Yes</b>
Containment Sump Testing:	<b>Yes</b>	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<b>Yes</b>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	<b>Yes</b>	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	<b>Yes</b>	Other:	
Line Tightness Testing:	No		
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<b>Yes</b>
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<b>Yes</b>
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
<b>Martin &amp; Slagle Geo Sciences, P.A.</b> P.O. Box 1023 24 Lookout Terrace Black Mountain, NC 28711  <b>Phone</b> (828) 669-3929 <b>Fax</b> (828) 669-5289  <b>Website</b> <a href="http://martinandslagle.com">martinandslagle.com</a>	11/19/2018		<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	
Line Tightness Testing:	No		
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	<b>Yes</b>	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	<b>Yes</b>	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		

## UST Service Provider List (Mountains)

Company	Listing Submitted			Area of state conducts work	
<b>Mineral Springs Environmental</b> 4600 Mineral Springs Lane Raleigh, NC 27616	11/13/2018	<b>Phone</b> (919) 266-8186  <b>Fax</b>  <b>Website</b>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes	
<b>Compliance Testing and Monitoring</b>		<b>UST Equipment Service Contractors</b>			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<b>Yes</b>
				Other:	
<b>Environmental Service Firms</b>					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	<b>Yes</b>	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	<b>Yes</b>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company	Listing Submitted			Area of state conducts work	
<b>National Tank Monitor, Inc.</b> P.O. Box 987 Lonoke, AR 72086-	11/15/2018	<b>Phone</b> (800) 643-8265  <b>Fax</b> (501) 764-4932  <b>Website</b> <a href="http://www.nationaltankmonitor.com">www.nationaltankmonitor.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes	
<b>Compliance Testing and Monitoring</b>		<b>UST Equipment Service Contractors</b>			
Automatic Line Leak Detector Testing:	<b>Yes</b>	Overfill Prevention Equipment Operability Check:	<b>Yes</b>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<b>Yes</b>	Statistical Inventory Reconciliation Services:	<b>Yes</b>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<b>Yes</b>	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<b>Yes</b>	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<b>Yes</b>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<b>Yes</b>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<b>Yes</b>	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<b>Yes</b>			UST System Removal:	No
				Other:	
<b>Environmental Service Firms</b>					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

## UST Service Provider List (Mountains)

Company	Listing Submitted			Area of state conducts work
<b>NC PETROLEUM &amp; CONVENIENCE MARKETERS</b> 7300 GLENWOOD AVE. RALEIGH, NC 27612	<b>Phone</b> (919) 782-4411  <b>Fax</b> (919) 872-4414  <b>Website</b> <a href="http://WWW.NCPCM.ORG">WWW.NCPCM.ORG</a>	11/15/2018	<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes	
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: No Waste Disposal and Treatment: No Other: UST ENGINEERING			
Company	Listing Submitted			Area of state conducts work
<b>Peak Hydrogeologic, PLLC</b> 470 Hogback Mountain Road Tryon, NC 28782	<b>Phone</b> (828) 817-5209  <b>Fax</b>  <b>Website</b> <a href="http://www.peakhydrogeologic.com">www.peakhydrogeologic.com</a>	6/14/2017	<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes	
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:			

## UST Service Provider List (Mountains)

<b>Company</b>	<b>Listing Submitted</b>		<b>Area of state conducts work</b>
<b>Petroleum Equipment and Service, Inc.</b> 4125 Sinclair Street PO Box 1949 Denver, NC 28037	<b>Phone</b> (704) 335-8801 <b>Fax</b> (704) 342-1672 <b>Website</b> <a href="http://www.petroleumequipment.net">www.petroleumequipment.net</a>	11/20/2018	<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing:	<b>Yes</b>	Overfill Prevention Equipment Operability Check:	<b>Yes</b>
Containment Sump Testing:	<b>Yes</b>	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<b>Yes</b>
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<b>Yes</b>
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	<b>Yes</b>	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	<b>Yes</b>	Other:	
Line Tightness Testing:	<b>Yes</b>		
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	
Soil and Water Testing Lab:	No		
<b>Petroleum Tec</b> 5420 Powerhouse Ct Concord, NC 28027	<b>Phone</b> (704) 804-1213 <b>Fax</b> <b>Website</b> <a href="http://www.petroleumtec.com">www.petroleumtec.com</a>	5/22/2019	<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
<b>Compliance Testing and Monitoring</b>			<b>UST Equipment Service Contractors</b>
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No
Leak Detection Monitoring Services:	No	Other:	Tank Cleaning
Line Tightness Testing:	No		
<b>Environmental Service Firms</b>			
Emergency Cleanup - Spill/Release:	<b>Yes</b>	UST Compliance Consultants:	No
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No
Oil and Solvent Recycling:	No	Other:	Tank Cleaning
Soil and Water Testing Lab:	No		

## UST Service Provider List (Mountains)

Company	Listing Submitted			Area of state conducts work
<b>PetroTest Inc.</b> 7 Dawn Rd. Benson, NC 27504	<b>Phone</b> (919) 902-3794  <b>Fax</b>  <b>Website</b> <a href="http://www.petrotest.net">www.petrotest.net</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: <b>Yes</b> Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: <b>Yes</b> UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: <b>Yes</b> Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:			
Company	Listing Submitted			Area of state conducts work
<b>PGP Services, LLC</b> 1949 Candlewick Drive Fort Mill, SC 29715	<b>Phone</b> (704) 619-1528  <b>Fax</b> (803) 802-2441  <b>Website</b>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: <b>Yes</b> Corrosion Protection System Repairs: <b>Yes</b> Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: No Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: <b>Yes</b> UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: <b>Yes</b> Waste Disposal and Treatment: No Other:			

## UST Service Provider List (Mountains)

Company	Listing Submitted			Area of state conducts work
<b>Pilot Geological, PLLC</b> 743 Park Lawn Court PO 128 Kernersville, NC 27285	<b>Phone</b> (336) 310-4527  <b>Fax</b> (336) 310-4527  <b>Website</b> <a href="http://www.pilotenviro.com">www.pilotenviro.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: <b>Yes</b> Waste Disposal and Treatment: <b>Yes</b> Other:			
Company	Listing Submitted			Area of state conducts work
<b>Precision Tank Service</b> P.O. Box 2040 20468 Chartwell Center Dr Cornelius, NC 28031	<b>Phone</b> (704) 892-8600  <b>Fax</b> (704) 892-8711  <b>Website</b> <a href="http://precisiontankservice.com">precisiontankservice.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: <b>Yes</b> Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: <b>Yes</b> Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: <b>Yes</b> UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: <b>Yes</b> Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: No Waste Disposal and Treatment: No Other:			

## UST Service Provider List (Mountains)

Company	Listing Submitted	11/15/2018	Area of state conducts work
<b>Progress Environmental Group, Inc.</b> 120 Fayette Street Winston-Salem, NC 27101	<b>Phone</b> (336) 722-9999  <b>Fax</b> (336) 722-9998  <b>Website</b> <a href="http://www.progressenvironmental.com">www.progressenvironmental.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: <b>Yes</b> Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other:		
Company	Listing Submitted	11/15/2018	Area of state conducts work
<b>Protective Technologies, Inc.</b> 711 Mill Street Camden, SC 29020	<b>Phone</b> (803) 424-0412  <b>Fax</b> (803) 424-0414  <b>Website</b> <a href="http://www.protectivetechnologiesinc.com">www.protectivetechnologiesinc.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: <b>Yes</b> Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: No Waste Disposal and Treatment: No Other:		



## UST Service Provider List (Mountains)

Company	Listing Submitted			Area of state conducts work
<b>Pyramid Environmental &amp; Engineering PC</b> 503 Industrial Ave Greensboro, NC 27406	<b>Phone</b> (336) 335-3174  <b>Fax</b> (336) 691-0648  <b>Website</b> <a href="http://www.pyramidenvironmental.com">www.pyramidenvironmental.com</a>	11/14/2018	<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes	
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other:			
Company	Listing Submitted			Area of state conducts work
<b>Royster Oil Company, Inc.</b> PO Box 1467 720 S Lafayette St Shelby, NC 28150	<b>Phone</b> (704) 487-6344  <b>Fax</b> (704) 487-7811  <b>Website</b> <a href="http://www.roysteroil.com">www.roysteroil.com</a>	11/19/2018	<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes	
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:			

## UST Service Provider List (Mountains)

Company	Listing Submitted	8/28/2018	Area of state conducts work
<b>SCS Engineers, PC</b> 2520 Whitehall Park Drive, Suite 450 Charlotte, NC 28273	<b>Phone</b> (704) 504-3107  <b>Fax</b>  <b>Website</b> <a href="http://www.scsengineers.com">www.scsengineers.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	9/6/2018	Area of state conducts work
<b>SCS Engineers, PC</b> 2520 Whitehall Park Drive, Suite 450 Charlotte, NC 28273	<b>Phone</b> (704) 504-3107  <b>Fax</b>  <b>Website</b> <a href="http://www.scsengineers.com">www.scsengineers.com</a>		<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

## UST Service Provider List (Mountains)

Company	Listing Submitted			Area of state conducts work
<b>Simonsen Law Firm, P.C.</b> 106 E. Queen St. P.O. Box 848 Edenton, NC 27932	<b>Phone</b> (252) 482-2175  <b>Fax</b> (252) 482-1355  <b>Website</b> <a href="http://www.simonsenlawfirm.com">www.simonsenlawfirm.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: Legal Services related to all UST issues	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:			
Company	Listing Submitted			Area of state conducts work
<b>Singleton Environmental, Inc.</b> PO Box 2012 1301 Sand Hill Road Enka, NC 28728	<b>Phone</b> (828) 667-5001  <b>Fax</b> (828) 667-0105  <b>Website</b> <a href="http://www.singletonenvironmental.com">www.singletonenvironmental.com</a>			<b>Coastal (East of I-95):</b> No <b>Central (West of I-95 and East of I-77):</b> No <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: No Waste Disposal and Treatment: No Other:			

## UST Service Provider List (Mountains)

Company	Listing Submitted			Area of state conducts work
<b>SR&amp;R Environmental, Inc.</b> 4920 Highway 421 N. PO Box 221 Wilmington, NC 28402	<b>Phone</b> (910) 763-6274  <b>Fax</b> (910) 763-6132  <b>Website</b> <a href="http://www.srrenviro.com">www.srrenviro.com</a>			<b>Coastal (East of I-95):</b> Yes  <b>Central (West of I-95 and East of I-77):</b> Yes  <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: <b>Yes</b> Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other: Vacuum Truck Services			
Company	Listing Submitted			Area of state conducts work
<b>Stahling Environmental Services, PLLC</b> P.O. Box 37203 Raleigh, NC 27627	<b>Phone</b> (919) 247-7030  <b>Fax</b>  <b>Website</b> <a href="http://www.stahlingenv.com">www.stahlingenv.com</a>			<b>Coastal (East of I-95):</b> Yes  <b>Central (West of I-95 and East of I-77):</b> Yes  <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:			

## UST Service Provider List (Mountains)

Company	Listing Submitted	11/14/2018	Area of state conducts work
<b>Superior Services</b> PO Box 982 Hendersonville, NC 28793  <b>Phone</b> (828) 698-6286 <b>Fax</b> (828) 698-6294  <b>Website</b> <a href="http://www.superiorservices.us">www.superiorservices.us</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: <b>Yes</b> Corrosion Protection System Repairs: <b>Yes</b> Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: No Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: <b>Yes</b> UST Internal Inspections (Integrity Assessments): <b>Yes</b> UST Internal Lining Inspections: <b>Yes</b> Other: UST Repairs, AST inspection, testing, repair		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	6/14/2017	Area of state conducts work
<b>Tanknology, Inc.</b> 4154 Silver Peak Pkwy Suite F Suwanee, GA 30024  <b>Phone</b> (800) 964-0700 <b>Fax</b> (855) 891-9395  <b>Website</b> <a href="http://www.Tanknology.com">www.Tanknology.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: <b>Yes</b> Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: <b>Yes</b> Corrosion Protection System Repairs: <b>Yes</b> Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: <b>Yes</b> Line Tightness Testing: <b>Yes</b>	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: <b>Yes</b> UST Internal Inspections (Integrity Assessments): <b>Yes</b> UST Internal Lining Inspections: <b>Yes</b> Other: Ikthrough inspections, internal inspections via camera		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: <b>Yes</b> Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: <b>Yes</b> UST System Removal: No Other:
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

## UST Service Provider List (Mountains)

Company	Listing Submitted	11/14/2018	Area of state conducts work
<b>Terracon Consultants, Inc.</b> 2701 Westport Road Charlotte, NC 28208  <b>Phone</b> (704) 509-1777 <b>Fax</b> (704) 509-1888  <b>Website</b> <a href="http://www.terracon.com">www.terracon.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:	
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: <b>Yes</b>	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other:		
Company	Listing Submitted	11/8/2018	Area of state conducts work
<b>Terraquest Environmental Consultants, P.C.</b> 100 E Ruffin St, Mebane, NC 27302, NC 27302  <b>Phone</b> (919) 563-9091 <b>Fax</b> (919) 563-9095  <b>Website</b> <a href="http://www.terraquestpc.com">www.terraquestpc.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:	
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

## UST Service Provider List (Mountains)

Company	Listing Submitted			Area of state conducts work
<b>Terraquest Environmental Consultants, P.C.</b> 100 E. Ruffin Street Mebane, NC 27302	<b>Phone</b> (919) 563-9091  <b>Fax</b> (919) 563-9095  <b>Website</b> <a href="http://www.terraquestpc.com">www.terraquestpc.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other:			
Company	Listing Submitted			Area of state conducts work
<b>TERRY Environmental Services of NC, Inc.</b> PO Box 25 Summerville, SC 29484	<b>Phone</b> (843) 873-8200  <b>Fax</b> (843) 873-8765  <b>Website</b> <a href="http://www.terryenvironmental.com">www.terryenvironmental.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: <b>Yes</b> Soil and Water Testing Lab: <b>Yes</b>	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: <b>Yes</b> Waste Disposal and Treatment: <b>Yes</b> Other: Trust Fund Services			

## UST Service Provider List (Mountains)

Company	Listing Submitted			Area of state conducts work
<b>The EI Group, Inc.</b> 2101 Gateway Centre Blvd, Ste 200 Morrisville, NC 27560	<b>Phone</b> (919) 657-7500  <b>Fax</b> (919) 657-7551  <b>Website</b> <a href="http://www.ei1.com">www.ei1.com</a>	9/1/2017		<b>Coastal (East of I-95):</b> Yes  <b>Central (West of I-95 and East of I-77):</b> Yes  <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:			
Company	Listing Submitted			Area of state conducts work
<b>TideLand Construction, LLC</b> 3600 North Drive Greenville, NC 27834-	<b>Phone</b> (252) 524-1644  <b>Fax</b> (252) 565-8724  <b>Website</b> <a href="http://tidelandconstruction.com">tidelandconstruction.com</a>	11/20/2018		<b>Coastal (East of I-95):</b> Yes  <b>Central (West of I-95 and East of I-77):</b> Yes  <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: <b>Yes</b> Leak Detection Equipment Installation Servicing: <b>Yes</b> Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: <b>Yes</b> UST Equipment Repair: <b>Yes</b> UST System Installation - Complete Systems: <b>Yes</b> UST Piping/Sump Installation: <b>Yes</b> UST System Removal: <b>Yes</b> Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: <b>Yes</b> Waste Disposal and Treatment: No Other:			



## UST Service Provider List (Mountains)

Company	Listing Submitted			Area of state conducts work
<b>Trifecta Services Company</b> 6120 Brookshire Blvd. Suite T Charlotte, NC 28216	<b>Phone</b> (704) 900-1977  <b>Fax</b> (704) 900-1975  <b>Website</b> <a href="http://www.trifectainc.com">www.trifectainc.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: <b>Yes</b> Soil and Water Testing Lab: <b>Yes</b>	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other:			
Company	Listing Submitted			Area of state conducts work
<b>TRS Petroleum Installation, Inc.</b> 155 Fern Avenue Marion, NC 28752	<b>Phone</b> (828) 652-6192  <b>Fax</b> (828) 652-6192  <b>Website</b>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: <b>Yes</b> Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: <b>Yes</b> Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: <b>Yes</b> Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: <b>Yes</b> Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: <b>Yes</b> Leak Detection Equipment Installation Servicing: <b>Yes</b> Spill Bucket Installation Repair: <b>Yes</b> UST Equipment Installation - Other: <b>Yes</b> UST Equipment Repair: <b>Yes</b> UST System Installation - Complete Systems: <b>Yes</b> UST Piping/Sump Installation: <b>Yes</b> UST System Removal: <b>Yes</b> Other: Industrial and Above Ground Installation		
Environmental Service Firms				
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: <b>Yes</b> UST Equipment Verification: No Waste Disposal and Treatment: No Other:			

## UST Service Provider List (Mountains)

Company	Listing Submitted	11/16/2018	Area of state conducts work
<b>UST Corrosion Management, Inc.</b> 2764 Pleasant Rd. #10714 Fort Mill, SC 29708  <b>Phone</b> (888) 822-2431 <b>Fax</b> (803) 802-0561  <b>Website</b> <a href="http://www.ustcorrosion.com">www.ustcorrosion.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: <b>Yes</b> Corrosion Protection System Repairs: <b>Yes</b> Corrosion Protection System Testing: <b>Yes</b> Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:	
Environmental Service Firms			
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		
Company	Listing Submitted	5/22/2018	Area of state conducts work
<b>Vistabution LLC</b> 8315 Six Forks Rd Suite 205 Raleigh, NC 27615  <b>Phone</b> (919) 844-9375 <b>Fax</b> (919) 861-0849  <b>Website</b> <a href="http://www.vistabution.com">www.vistabution.com</a>			<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:	Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other:	
Environmental Service Firms			
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: <b>Yes</b>	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:		

## UST Service Provider List (Mountains)

Company	Listing Submitted			Area of state conducts work
<b>Vital Fuel Systems, Inc.</b> 1076 Classic Road Apex, NC 27539	<b>Phone</b> (919) 303-7374  <b>Fax</b> (919) 303-7399  <b>Website</b> <a href="http://www.vitalfuelsystems.com">www.vitalfuelsystems.com</a>	9/6/2018	<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes	
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: <b>Yes</b> UST Equipment Repair: No UST System Installation - Complete Systems: <b>Yes</b> UST Piping/Sump Installation: No UST System Removal: <b>Yes</b> Other: removal, Upgrades. We do not work at retail fueling sites.	
Environmental Service Firms				
Emergency Cleanup - Spill/Release: No Environmental Engineer/Geologist - Site Checks: No Environmental Engineer/Geologist Soil and GW Cleanu: No Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: No Other:			
Company	Listing Submitted			Area of state conducts work
<b>WithersRavenel</b> 115 MacKenan Drive Cary, NC 27519	<b>Phone</b> (919) 469-3340  <b>Fax</b> (919) 467-6008  <b>Website</b> <a href="http://withersravenel.com/">http://withersravenel.com/</a>	9/26/2016	<b>Coastal (East of I-95):</b> Yes <b>Central (West of I-95 and East of I-77):</b> Yes <b>Mountains (West of I-77):</b> Yes	
Compliance Testing and Monitoring			UST Equipment Service Contractors	
Automatic Line Leak Detector Testing: No Containment Sump Testing: No Corrosion Protection Design Experts: No Corrosion Protection System Repairs: No Corrosion Protection System Testing: No Leak Detection Equipment Operability Check: No Leak Detection Monitoring Services: No Line Tightness Testing: No	Overfill Prevention Equipment Operability Check: No Statistical Inventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other:		Dispenser Meter Repair/Calibration: No Leak Detection Equipment Installation Servicing: No Spill Bucket Installation Repair: No UST Equipment Installation - Other: No UST Equipment Repair: No UST System Installation - Complete Systems: No UST Piping/Sump Installation: No UST System Removal: No Other:	
Environmental Service Firms				
Emergency Cleanup - Spill/Release: <b>Yes</b> Environmental Engineer/Geologist - Site Checks: <b>Yes</b> Environmental Engineer/Geologist Soil and GW Cleanu: <b>Yes</b> Oil and Solvent Recycling: No Soil and Water Testing Lab: No	UST Compliance Consultants: No UST Equipment Verification: No Waste Disposal and Treatment: <b>Yes</b> Other:			