

Underground Storage Tanks (USTs) Public Record - Summary Information

General Information

Public Record Posted Date: 1/8/2020

Total Number Of Active UST Facilities: 7,501
 Total Number Of USTs: 24152*

Summary Information For On-Site Inspections

Number Of UST Facilities Inspected: 3,220
 Inspection Period Dates: 10/1/2018 To: 10/1/2019
 Percent Compliance (Combined Measure): 41%**

Note: *Number of whole tanks = 21,937; **Compliance rate reflects implementation of new federal regulations on 10/13/2018;

Summary Information For Releases

Number Of Confirmed UST Releases: 252
 Release Reporting Period Dates 10/1/2018 To: 10/1/2019

Summary Information For Release Sources And Causes

Source			Cause													
			Spill		Overfill		Corrosion		Phys/Mech Damage		Install Problem		Other		Unknown	
#	%		#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	138	55%	0	0%	8	6%	26	19%	39	28%	0	0%	5	4%	60	43%
Piping	27	11%	0	0%	0	0%	0	0%	19	70%	0	0%	1	4%	7	26%
Dispenser	55	22%	5	9%	0	0%	5	9%	15	27%	0	0%	2	4%	28	51%
STP**	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%
Delivery Problem	1	0%	0	0%	0	0%	0	0%	1	0%	0	0%	0	0%	0	0%
Other	18	7%	2	11%	0	0%	2		7	39%	0	0%	3	17%	4	22%
Unknown	13	5%	1	8%	0	0%	0	0%	1	8%	0	0%	0	0%	11	84%
Totals	252	100%	8	3%	8	3%	33	13%	82	33%	0	0%	11	4%	110	44%

Note: Release, source and cause information is based on data from regulated tanks. Source and cause data were collected primarily using forms and reports submitted by Responsible Parties or their agents.

*Additionally, there were 300 confirmed releases from non-regulated USTs, primarily heating oil tanks. There are also 305 confirmed releases from non-usts during the reporting period.

**STP - Submersible Turbine Pump

To obtain site-specific information on UST releases contact the Regional DENR Office for the county in which the release occurred. To obtain UST compliance information contact the UST Section Central Office.