

Underground Storage Tanks (USTs) Public Record - Summary Information

General Information

Public Record Posted Date: 12/23/2020

Total Number Of Active UST Facilities: 7,406
 Total Number Of USTs: 23,940

Summary Information For On-Site Inspections

Number Of UST Facilities Inspected: 2,370
 Inspection Period Dates: 10/1/2019 To: 10/1/2020
 Percent Compliance (Combined Measure): 50%

Note: *Number of whole tanks = 21,618; **Compliance rate reflects implementation of new federal regulations on 10/13/2018;

Summary Information For Releases

Number Of Confirmed UST Releases: 240
 Release Reporting Period Dates 10/1/2019 To: 10/1/2020

Summary Information For Release Sources And Causes

Source			Cause													
			Spill		Overfill		Corrosion		Phys/Mech Damage		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	139	58%	2	1%	2	1%	26	19%	22	16%	0	0%	7	5%	80	58%
Piping	29	12%	0	0%	0	0%	3	10%	16	55%	0	0%	0	0%	10	34%
Dispenser	25	10%	0	0%	1	4%	5	20%	8	32%	0	0%	3	12%	8	32%
STP**	5	2%	0	0%	0	0%	1	20%	3	60%	0	0%	0	0%	1	20%
Delivery Problem	1	0%	0	0%	1	100%	0	0%	0	0%	0	0%	0	0%	0	0%
Other	15	6%	2	13%	0	0%	0	0%	6	40%	0	0%	2	13%	5	33%
Unknown	26	11%	0	0%	0	0%	0	0%	11	42%	0	0%	0	0%	15	58%
Totals	240	100%	4	3%	3	3%	35	13%	66	33%	0	0%	12	4%	119	44%

Note: Release, source and cause information is based on data from regulated tanks. Source and cause data were collected primarily using forms and reports submitted by Responsible Parties or their agents.

*Additionally, there were 292 confirmed releases from non-regulated USTs, primarily heating oil tanks. There are also 253 confirmed releases from non-usts during the reporting period.

**STP - Submersible Turbine Pump

To obtain site-specific information on UST releases contact the Regional DENR Office for the county in which the release occurred. To obtain UST compliance information contact the UST Section Central Office.